

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	26-Jun-24
Jam Berangkat	07.55 WIB
Jam Repair	13.05 s/d 15.30
Jam Kembali	18.10 WIB
Qty Unit Repair	8 pcs
Assy No	14X0625321
Type Unit	D 65 E
Jumlah Man Power	2 Orang
Driver	-
Methode Repair	Penambahan circuit dan ganti lampu

Maker of Harness ☐ BEI ☒ NON BEI

Couse of Defect ☐ BEI ☒ NON BEI


MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Wire	AVS 0,85 B	1.00 Meter
Wire	AVS 0,85 B-W	1.00 Meter
Wire	AVS 0,85 R-W	1.00 Meter
Wire	AVS 0,85 Y-B	3,36 Meter
Terminal	B-2	12 Pcs
Terminal	300502-0	8 Pcs
Terminal	300501-0	4 Pcs
Terminal	110500-2	12 Pcs
Terminal	7114-1471	4 Pcs
Rubber Seal	7157-7811-80	4 Pcs
Sleeve	7120-8012	4 Pcs
Sleeve	7120-1010	12 Pcs
Sumitube	SA3-1	0.67 Meter
SH Tube	SH TUBE D5	0,34 Meter
COT	COT D5	6.4 Meter
Lampu	Lampu LED putih	4 pcs
Resistor	R 220 ohm 0.5W	4 pcs

1. Modif harness GAUGE dari assy 14X0625321 ke assy 14X-06-J4510 sebanyak 4 pcs

Before


After



2. Melakukan Repair Lampu Bulb diganti ke LED sebanyak 4 pcs

Before

After



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman