

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	10-Jul-24
Jam Berangkat	09.00 WIB
Jam Repair	10.55 s/d 16.10
Jam Kembali	18.00 WIB
Qty Unit Repair	20 pcs
Assy No	14X0625321
Type Unit	D 65 P
Jumlah Man Power	3 Orang
Driver	-
Methode Repair	Penambahan circuit dan ganti lampu


Maker of Harness ☐ BEI ☒ NON BEI

Couse of Defect ☐ BEI ☒ NON BEI


MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Wire	AVS 0,85 B	3.76 Meter
Wire	AVS 0,85 B-W	3.75 Meter
Wire	AVS 0,85 R-W	2.47 Meter
Wire	AVS 0,85 Y-B	9.13 Meter
Terminal	B-2	33 Pcs
Terminal	300502-0	22 Pcs
Terminal	300501-0	11 Pcs
Terminal	110500-2	33 Pcs
Terminal	7114-1471	11 Pcs
Rubber Seal	7157-7811-80	11 Pcs
Sleeve	7120-8012	11 Pcs
Sleeve	7120-1010	33 Pcs
Sumitube	SA3-1	1.55 Meter
SH Tube	SH TUBE D5	0.66 Meter
COT	COT D5	15.4 Meter
VO	VO-B 5*6	1.21 Meter
Lampu	Lampu LED putih	9 pcs
Resistor	R 220 ohm 0.5W	9 pcs

1.Modif harness GAUGE dari assy 14X0625321
ke assy 14X-06-J4510 sebanyak 11 pcs
Before After



2. Melakukan Repair Lampu Bulb diganti ke LED sebanyak 9 pcs
Before After



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman