

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	30-Aug-24
Jam Berangkat	07.45 WIB
Jam Repair	09.45 s/d 16.25
Jam Kembali	19.15 WIB
Qty Unit Repair	20 pcs
Assy No	14X0625321
Type Unit	D 65 P
Jumlah Man Power	2 Orang
Driver	-
Methode Repair	Penambahan circuit dan ganti lampu

Maker of Harness

☐ BEI ☒ NON BEI


Cause of Defect

☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Wire	AVS 0,85 B	3.76 Meter
Wire	AVS 0,85 B-W	3.75 Meter
Wire	AVS 0,85 R-W	2.47 Meter
Wire	AVS 0,85 Y-B	9.13 Meter
Terminal	B-2	33 Pcs
Terminal	300502-0	22 Pcs
Terminal	300501-0	11 Pcs
Terminal	110500-2	33 Pcs
Terminal	7114-1471	11 Pcs
Rubber Seal	7157-7811-80	11 Pcs
Sleeve	7120-8012	11 Pcs
Sleeve	7120-1010	33 Pcs
Sumitube	SA3-1	1,55 Meter
SH Tube	SH TUBE D5	0,66 Meter
COT	COT D5	15.4 Meter
Lampu	Lampu LED putih	9 pcs
Resistor	R 220 ohm 0.5W	9 pcs

1. Modif harness GAUGE dari assy 14X0625321 ke assy 14X-06-J4510 sebanyak 11 pcs
Before After



2. Melakukan Repair Lampu Bulb diganti ke LED sebanyak 10 pcs
Before After



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman