



PT. BANSHU ELECTRIC INDONESIA

Form Control Check Ulang Stock

Jenis Defect

: Salah diameter cot

Posisi NG

: ECU

Tanggal

: 23-09-2024

Method Pengecekan

: Repair B22 → B25

Jam pengecekan

$\therefore 13.05 \text{ \$/d } 16.30$

[illegible]

Note :

CONFIRM "OK"

Approved	Checked	PIC
		
Arjun	Harini, a Leader & p	Sufimith