

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	03-Oct-23
Jam Berangkat	07.55 S/D 09.15 WIB
Jam Repair	13.05 S/D 16.15
Jam Kembali	16.40 S/D 18.15 WIB
Qty Unit Repair	1 pcs
Assy No	21T0645230-00
Type Unit	PC2000-11
Jumlah Man Power	2 Orang
Driver	1 Orang
Methode Repair	Ganti connector

Maker of Harness ☐ BEI ☒ NON BEI


Couse of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :



PART NAME	PART NO	QTY
-	-	-

1. Observasi problem terminal lepas yang terjadi main harness untuk unit PC2000-11 pada posisi CN-A06 connector 937928400 colour Yellow pada pin connector A6.
2. Proses repair ganti connector 937928400 dikarenakan lock terminal dalam connector patah
3. Setelah repair selesai, connector di pasang ke unitnya


1. Terminal push out pada wire colour Yellow



2. Repair ganti connector



3. Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman