

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	31-Oct-23
Jam Berangkat	11.00 WIB
Jam Repair	13.05 s/d 15.50 WIB
Jam Kembali	18.15 WIB
Qty Unit Repair	1 pcs
Assy No	
Type Unit	HD785-7
Jumlah Man Power	1 Orang
Driver	1 Orang
Methode Repair	Repair ganti connector




Maker of Harness ☐ BEI ☒ NON BEI

Couse of Defect ☐ BEI ☒ NON BEI


MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Connector	HD34-24-31PE	1 Pcs

1.Repair ganti connector HD34-24-31PE pada unit HD785-7 karena NG seal mundur
Before :



2.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman