

No	Screening Date	Place	Serial No	Pos. A (70 ± 10)				Pos. B (50 ±20/0)				Pos. C (50 ±20/0)				Pos. D (220 ±5/0)				Pos. E (Missing Fuse)		Pos. F (Fitting W/ Bracket)		Final Judge	Inspector	Remark
				Before		After		Before		After		Before		After		Before		After		Actual	Judge	Actual	Judge			
				Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge					
106			52306004093	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
107			52306004162	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
108			52306004142	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	0	Dicky	Wire Cross → Re-position Wire
109			52306004144	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	0	Roni	Wire Cross → Re-position Wire
110			52306004103	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
111			52306004105	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
112			52308001727	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
113			52305004463	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
114			52305004469	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
115			52306004091	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
116			52305004490	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
117			52305004852	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
118			52306004134	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
119			52305004476	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	0	Dicky	Wire Cross → Re-position Wire
120			52305004473	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
121			52306004117	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
122			52305004478	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
123			52305004962	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
124			52305004150	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
125			52305004499	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
126			52309000249	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
127			52309000108	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
128			52309000233	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
129			52308001738	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
130			52309000242	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	0	Dicky	Wrong direction branch → dis-assy Branch and Re-tapping
131			52308001687	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	0	Roni	Wire Cross → Re-position Wire
132			52308001760	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
133			52309000092	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
134			52308001756	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
135			52309000104	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
136			52309000231	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
137			52306004089	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
138			52308001711	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
139			52306004171	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
140			52308001714	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
141			52308001710	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
142			52308004076	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
143			52309000076	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
144			52309000025	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
145			52309000107	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
146			52309000211	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B: dis-assy Branch and Re-tapping
147			52309000077	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
148			52309000103	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Dicky	-
149			52309000255	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
150			52309000238	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
151			52308006328	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
152			52309000229	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Dicky	-
153			52306004128	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
154			52309000094	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Dicky	-
155			52308001467	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B: dis-assy Branch and Re-tapping
156			52308001775	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
157			52308001474	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
158			52308001758	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
159			52309000198	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Dicky	-
160			52309000096	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Dicky	-
161			52308001754	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
162			52308001697	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
163			52309000245	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
164			52309000111	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Dicky	-
165			52309000093	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
166			52309000167	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
167			52308001749	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	0	Roni	Wire Cross → Re-position Wire
168			52308001778	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0							

No	Screening Date	Place	Serial No	Pos. A (70 ± 10)				Pos. B (50 ± 20/0)				Pos. C (50 ± 20/0)				Pos. D (220 ± 5/0)				Pos. E (Missing Fuse)		Pos. F (Fitting W/ Bracket)		Final Judge	Inspector	Remark
				Before		After		Before		After		Before		After		Before		After		Actual	Judge	Actual	Judge			
				Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge							
222	16-Feb-24	DOC 1 W/H	52308001771	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
223			52308001507	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
224			52309000731	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
225			52308001774	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
226			52308001488	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
227			52305004500	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B : dis-assy Branch and Re-tapping
228			52308001874	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
229			52306004147	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B : dis-assy Branch and Re-tapping
230			52308001736	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
231			52306004126	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
232			52308001694	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B : dis-assy Branch and Re-tapping
233			52308001764	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
234			52308001673	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
235			52308001720	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
236			52308001734	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
237			52308001767	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
238			52308001785	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
239			52308001784	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
240			52308001492	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
241			52309000237	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
242			52309000205	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
243			52308001510	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
244			52306004167	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
245			52309000250	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
246			52308001717	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
247			52309000100	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
248			52308001751	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Dicky	-
249			52308001748	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
250			52308001742	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B : dis-assy Branch and Re-tapping
251			52306004145	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B : dis-assy Branch and Re-tapping
252			52309000102	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
253			52306004116	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B : dis-assy Branch and Re-tapping
254			52308001722	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
255			52306004108	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B : dis-assy Branch and Re-tapping
256			52308001730	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
257			52306004140	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B : dis-assy Branch and Re-tapping
258			52308001698	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
259			52309000257	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
260			52306004173	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B : dis-assy Branch and Re-tapping
261			52309000080	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
262			52309000106	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
263			52306004119	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	0	Dicky	Wire Cross → Re-position Wire
264			52309000238	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
265			52306004115	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Folded Branch Pos. B : dis-assy Branch and Re-tapping
266			52309000081	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Folded Branch Pos. B : dis-assy Branch and Re-tapping
267			52309000224	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	0	Roni	-
268			52308001726	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
269			52305004484	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
270			52308001737	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping
271			52309000239	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping
272	52306004150	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping		
273	52309000241	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping		
274	52308001715	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping		
275	52308001780	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping		
276	52309000091	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping		
277	52309000217	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	0	Dicky	Wire Cross → Re-position Wire		
278	52309000244	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping		
279	52309000236	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping		
280	52309000178	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping		
281	52308001777	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping		
282	52308001746	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Dicky	Branch not sequence → dis-assy Branch and Re-tapping		
283	52306004169	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping		
284	52306004082	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	0	Roni	Branch not sequence → dis-assy Branch and Re-tapping		
285	52308001490	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	0	Dicky	Wire Cross → Re-position Wire		
286	52308001696	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	0				

CHECKSHEET SCREENING & REPAIR - HARNESS S/A JK141380-7130

B.Note:										REMARK																			
- Screening part and OK result : Marking "AS" at label - Screening part and NG result :> Repair: Marking "NR" at label																													
0 : OK										Repair and OK																			
No	Screening Date	Place	Serial No	Pos. A (70 ± 10)			Pos. B (50 ± 20/0)			Pos. C (50 ± 20/0)			Pos. D (20 ± 5/0)			Pos. E (Missing Fuse)			Pos. F (Fitting W/ Bracket)			Final Judge	Inspector	Remark					

No	Screening Date	Place	Serial No	Pos. A (70 ± 10)				Pos. B (50 ±20/0)				Pos. C (50 ±20/0)				Pos. D (220 ±5/0)				Pos. E (Missing Fuse)		Pos. F (Fitting W/ Bracket)		Final Judge	Inspector	Remark
				Before		After		Before		After		Before		After		Before		After		Actual	Judge	Actual	Judge			
				Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge	Actual	Judge							
106			52308001490	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	⊖	Dicky	Wire Cross -> Re-position Wire
107			52308001696	70	0	←	0	50	0	←	0	50	0	←	0	220	0	225	0	Available	0	Can't Fitting	X	⊖	Dicky	Wire Cross -> Re-position Wire
108			52308001781	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	⊖	Dicky	Branch not sequence -> dis-assy Branch and Re-tapping
109			52308001721	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	⊖	Roni	Branch not sequence -> dis-assy Branch and Re-tapping
110			52308001493	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	⊖	Roni	Branch not sequence -> dis-assy Branch and Re-tapping
111			52308001762	70	0	←	0	50	0	55	0	50	0	←	0	220	0	←	0	Available	0	Can't Fitting	X	⊖	Dicky	Branch not sequence -> dis-assy Branch and Re-tapping
112			52309000090	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Roni	-
113			52308001473	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Dicky	-
114			52309000216	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Roni	-
115			52308001500	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Dicky	-
116			52309000097	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Roni	-
117			52308001759	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Dicky	-
118			52309000190	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Roni	-
119			52309000177	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Dicky	-
120			52308001740	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Roni	-
121			52309000202	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Dicky	-
122			52308001707	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Roni	-
123			52306004096	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Dicky	-
124			52309000185	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Roni	-
125			52309000175	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Dicky	-
126			52309000160	70	0	←	0	50	0	←	0	50	0	←	0	220	0	←	0	Available	0	Can Fitting	0	⊖	Roni	-