

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	26-Mar-24
Jam Berangkat	08.25 WIB
Jam Repair	10.30 S/D 15.05
Jam Kembali	17.05 WIB
Qty Unit Repair	20 pcs
Assy No	-
Type Unit	PC135 HARVESTER
Jumlah Man Power	1 Orang
Driver	1 Orang
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness

☐ BEI

☒ NON BEI

Couse of Defect

☐ BEI


☒ NON BEI

MATERIAL UNTUK REPAIR :


PART NAME	PART NO	QTY
Terminal	1060-16-0122	40 Pcs
Terminal	DT04-2P-E005	20 pcs
Retainer	W2P	20 pcs

1.Modif connector untuk OILCOOLER PC135 HARVESTER sebanyak 20 pcs

Before :



After :



2.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman