

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	24-Apr-24
Jam Berangkat	11.20 WIB
Jam Repair	14.15 s/d 15.15 WIB
Jam Kembali	17.45 WIB
Qty Unit Repair	1 pcs
Assy No	561-95-82614-02
Type Unit	HD785
Jumlah Man Power	2 Orang
Driver	-
Methode Repair	Check tegangan resistor dan menukar resistor

Maker of Harness ☒ BEI ☐ NON BEI

Couse of Defect ☒ BEI ☐ NON BEI

MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
-	-	-
-	-	-

1.Repair resistor pada posisi RE3 dan RE4 di assy 561-65-82614-02 sebanyak 1 pcs

Standart :


Marker RE3 : 250 Ω

Marker RE4 : 1.02 Ω


Actual :

Marker RE3 : 1.020 Ω

Marker RE4 : 250 Ω



Before :



After :



2.Assy No



CONFIRM "OK"

Disetujui	Dipenksa	Dibuat
Asst Manager QA	Leader QA	Repairman