

No. :

- Nama
Bagian
Jenis Tugas
Tujuan
Jam Berangkat
Jam Kembali

Sufimin 2
 0AM
 MODF UNIT P135F HARVEY 2 UNIT
 P-T Komatsu Indonesia
 08-00 ✓

KM Awal	429.600
KM Akhir	429.800

KM Akhir 429-809
Kendaraan ☐ Pribadi ☒ Dinas ☐ Umum
Kendaraan No. Polisi Paraf :

Muldrabman

Purwakarta : 09-08-2024

No.	Nama Pengikut	Bagian	Keterangan
Dibuat	Diketahui	Disetujui	
Pelaksana	Div. / Dept	HRD - GA	Direktur Plant
KETERANGAN	TUJUAN		
	I	II	III
Tanggal & Jam Tiba			
Tanggal & Jam Kembali			
Tanda Tangan / Stempel			
Perusahaan Yang Dikunjungi			

LAPORAN MODIF KOMATSU INDONESIA

Tanggal Repair	09-Aug-24
Jam Berangkat	07.40 WIB
Jam Repair	10.30 s/d 15.15 WIB
Jam Kembali	19.30 WIB
Qty Unit Repair	2 pcs
Type Unit	PC 135 HARVESTER
Jumlah Man Power	1 Orang
Driver	-
Methode Repair	Potong wire ganti terminal dan pasang conector

Maker of Harness ☐ BEI ☒ NON BEI



Couse of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :


PART NAME	PART NO	QTY
Terminal	1062-16-0122	24 Pcs
Terminal	1060-16-0122	24 Pcs
Terminal	+MT080-0123	4 Pcs
Terminal	+R1 25-5	2 Pcs
Terminal	+R1 25-8	2 Pcs
Wire	AVSS 0.5 B	2400 mm
Wire	AVSS 0.5 W	1200 mm
Connector	DT06-6S-EP06	2 Pcs
Connector	DT04-6P-E005	2 Pcs
Connector	DT04-2P-E005	6 Pcs
Retainer	W2P	6 Pcs
Retainer	W6P	2 Pcs
Retainer	W6S-P012	2 Pcs
Connector	+7124-9681	2 Pcs
Tape	WHVTA 19*20 B	400 mm
Fuse 10 A	+7123+3011	2 Pcs
Connector	DT06-8SA-CE05	2 Pcs
Retainer	W8S-P012	2 Pcs

1. Modif PC 135 HARVESTER sebanyak 2 unit

BEFORE



AFTER




2. Sambung wire

Before




After




3. Modif connector pada Oil Cooler sebanyak 6 pcs

Before



After



4. Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Ass Manager QA	Leader QA	Repairman