




RTVIO camera calibration board - 10 x 7 squares = 9 x 6 inner corners (enter 9 and 6 in the Studio). Keep it perfectly flat: tape it to card or a clipboard.