## Delay Example of around 1.3 ms on the STM32f407 discovery board

```
Pvoid tim6_delay(void){
// enable APB1 bus clock
RCC->APB1ENR|=RCC_APB1ENR_TIM6EN;
//TIM6 prescaler set at default to 0 for now
TIM6->PSC=0; // prescalar
TIM6->ARR = 21000; //auto reload register
TIM6->CNT=0; //clear counter register
TIM6->CR1|=TIM_CR1_CEN;
//WHEN COUNTER IS DONE THE TIM6_SR REG UIF FLAG IS SET
while(TIM6->SR==0);
TIM6->SR=0; //CLEAR uIF FLAG
```

Dr. Hassan Salamy Page 1