
JONDETECH Small is Powerful




EVK Board



USB C Connector

USB FW Upgrade



Module Connector



Hardware setup

EVK board





USB C Cable



PC running GraphDisplay






Hardware setup - Modules

Connect the module to the EVK board by pushing the module connector and inserting the module. The correct orientation is shown in the images below



Bottom view





Installation

- 1. Download and run JDT_Evaluation_Setup.msi
- 2. Once installed, JDT Evaulation Tool is available via Start Menu
- 3. Insert Module board into EVK FPC Connector.
- 4. Connect USB cable between EVK board and PC
- 5. Launch JDT Evaluation Tool
- 6. First time, the tool will installation USB Drivers for the EVK board.
- 7. Select the right com port and press start

