
# JONDETECH Small is Powerful




### **EVK Board**



**USB C Connector** 

USB FW Upgrade




**Module Connector** 



## Hardware setup

#### EVK board



£ ...

USB C Cable



PC running GraphDisplay





## Hardware setup - Modules

Connect the module to the EVK board by pushing the module connector and inserting the module. The correct orientation is shown in the images below

Top view


EVK board

J30 module

J40 module

J30 module

**Bottom view** 





#### Installation

- Download and run JDT\_Evaluation\_Setup.msi (<a href="https://github.com/JonDeTech/Evaluation-Tool">https://github.com/JonDeTech/Evaluation-Tool</a>)
- 2. Once installed, JDT Evaulation Tool is available via Start Menu
- 3. Insert Module board into EVK FPC Connector.
- 4. Connect USB cable between EVK board and PC
- 5. Launch JDT Evaluation Tool
- 6. First time, the tool will installation USB Drivers for the EVK board.
- 7. Select the right com port and press start

