




phase offset 25°



CFO $4 \times 10^{-4} R_s$



timing error $T/4$



clock offset 250 ppm

