

Mounting Hole
for M2.5 Bolt + Nut
(plastic washer recommended)


⊗ Camera facing into drawing plane

OV5640 24 Pin FPC Connector

3V3
FreeGP104
FreeGP103
FreeGP102
FreeGP101
FreeGP100*
SCL
SDA
ESP_ON
XGND

Mounting Hole
for M2.5 Bolt + Nut
(plastic washer recommended)

Keep clear of
conductive materials
(antenna keepout zone)



UI-Board 24 Pin Connector

All round footprints are Testpoints
Round markers highlight Pin 1 of some parts