

Raw Force Signals — Full Session (no conditioning)
UR5 col: raw f_z from RTDE | FUTEK col: A10 voltage converted to N

