


- 1. Run TVMON\_build.bat to ensure it's work.
- 2. Change MotorolaTvMonQiph.mcp as follow,

Create group Bltc, and subgroup Items, TiApi, TiLib and UserInterface as follow MotorolaTvMonQiph.mcp



3. Create dir TvMon\Libs\Broadcom\_Hal\src\TvMonIO, and copy those 5 files to it. And modify project bcmhal7400.mcp as follow,





- 4. Search "Gamma modify" (case sensitive) in TvMon dir and update them.
  - (1). For porting BLTC, main.c
  - (2). For porting TvMon Command mechanism, userio.h , bcmdbg.h , mainmenumgr.c, atatest.c, bCmdDigAudioDec.c , prompt.c
  - (3). For Software disable RS232 Tx solution, hw\_init.c, bkni.c
  - (4). In P5, more bCmdKpd.c, bCmdVidOut.c, elibc.h, bCmdQus.c, bqds.c, bqus.c, bqus\_3255\_scripts.c, EntropicPower.c, LsiDmnEncoderMenu.c.
- 5. Follows files only for TvMon9.10 to fix the bug in DCH3416P5. TvMon9.11 has fix this bug, so no need any more. I write them down for check, btnr\_mtm.h, btnr\_mtm.c, bCmdDigAudioDec.c.