



HOME-FRONT INSPECTION SERVICES LLC

310-347-8945

info@homefrontinspectionsservices.com

<https://www.homefrontinspectionsservices.com>



HOMEFRONT INSPECTION

8638 Hollywood Blvd
Los Angeles, CA 90069

Aubree Powers

01/29/2026



Inspector

Jesus Barriga

INTERNACHI CPI

9097754355

jesushomefront@gmail.com

TABLE OF CONTENTS

1: Inspection Details	7
2: Exterior Areas	13
3: Grounds	17
4: Water Heater(s)	31
5: Garage and/or Carport	34
6: Attic Area	36
7: Roof	39
8: Electrical/Gas Service	44
9: Bedrooms	49
10: Laundry Area	50
11: Kitchen	53
12: Bathrooms	56
13: Interior	63
14: Heating/Air Conditioning	80
15: Foundation	92
16: Sewerline inspection	100
Standards of Practice	102

How to read this report:

The defects within the report are organized into three categories. They are Minor Concern (in blue), Moderate Concern (in orange), and Major Concern (in red). The category that each defect is in does not determine the importance of the recommended repair. All defects noted on this report should be addressed. **Health and safety concerns will be in the Moderate Concern or Major Concern, depending on how the perceived danger but these should be addressed ASAP.** All repairs should be performed by licensed and/or qualified contractors in order to ensure the repairs are done safely and properly.

Minor Concern: Items or components of the home that are defective and, in the opinion of the inspector, may be considered general maintenance or are typical for the age of the home. Any recommended improvements to the home may also be in this category.

Moderate Concern: Items or components that were found to be defective and, if not addressed, these could lead to further problems. These defects are not considered to be routine maintenance. This category may also contain safety hazards or concerns.

Major Concern: Items or components that were defective and may require major/costly repairs. This category may also contain serious safety hazards or concerns that are in need of immediate attention.

These categories are based on the Inspector's professional judgment and are based on the conditions at the time of the inspection. This categorization should not be construed as to mean that items designated as a Minor Concern or Moderate Concern do not need repaired or addressed. The recommendation in each comment is more important than the category in which the defect was placed in.

Limitations: In the event that the inspector was not able to inspect/test certain areas or components of the home, there may be a Limitations tab in that section of the report. The Limitations tab may show things that need to be further evaluated after the inspection. I recommend reading any Limitations in the report and addressing them as necessary.

Photographs: Several photos and videos are in your inspection report. These photos are for informational purposes and may not include every instance or occurrence of a defect. For example, if the report has three photos of hail damage on the roof, this does not mean that there is only hail damage in those areas.

The inspection will have a significant amount of photos, however, the report may not contain all of these photos as they are used for reference and thoroughness to assist the inspector, additional photos may be provided by request.

SUMMARY

197

ITEMS INSPECTED

4

MINOR CONCERN

54

MODERATE CONCERN

18

MAJOR CONCERN

- ⊖ 2.1.1 Exterior Areas - Stucco: Missing stucco
- 🔧 2.12.1 Exterior Areas - Door Bells: Did not operate front
- ⊖ 3.1.1 Grounds - Driveways and Walkways: Moderate cracking
- ⊖ 3.1.2 Grounds - Driveways and Walkways: Moderate chipping
- ⊖ 3.4.1 Grounds - Exterior Electrical: Missing exterior outlet cover
- ⊖ 3.4.2 Grounds - Exterior Electrical: Loose fixture(s)
- ⊖ 3.4.3 Grounds - Exterior Electrical: Fixture missing
- ⊖ 3.5.1 Grounds - GFCIs: Non-Energized GFCI Outlet
- ⊖ 3.6.1 Grounds - Exterior Plumbing and Faucets: Hose bibb drips
- ⊖ 3.7.1 Grounds - Planters: Vegetation close to structure
- ⚠ 3.13.1 Grounds - Stairs & Handrails: Loose rails
- ⊖ 3.13.2 Grounds - Stairs & Handrails: Steps have gap at structure
- ⚠ 3.13.3 Grounds - Stairs & Handrails: Deteriorated staircase
- ⚠ 3.13.4 Grounds - Stairs & Handrails: Deteriorated guardrails
- ⚠ 3.13.5 Grounds - Stairs & Handrails: Stair case leaning
- ⊖ 3.16.1 Grounds - Balconies: Missing fasteners
- ⚠ 3.17.1 Grounds - Balcony and Deck Railing: Loose glass
- ⊖ 3.17.2 Grounds - Balcony and Deck Railing: Cracked tiles
- ⊖ 4.1.1 Water Heater(s) - Condition: Locked door: not inspected
- ⊖ 4.12.1 Water Heater(s) - Enclosures: Damaged door
- ⊖ 8.7.1 Electrical/Gas Service - Main Gas Valve: Gas Off
- ⚠ 10.1.1 Laundry Area - Dryer Vent: Vent painted shut
- ⊖ 10.7.1 Laundry Area - Stacked unit : Stacked unit no straps
- ⊖ 11.4.1 Kitchen - Dishwashers: Drains to disposal: no visible air gap
- ⚠ 11.6.1 Kitchen - Exhaust Vents: Did not operate
- ⊖ 12.2.1 Bathrooms - Sinks: Drain stopper not operating properly
- ⊖ 12.3.1 Bathrooms - Plumbing: Corrosion/ Discoloration observed in areas
- ⊖ 12.3.2 Bathrooms - Plumbing: Loose drain(s)

- ⊖ 12.5.1 Bathrooms - Toilets: Toilet slightly loose
- ⚠ 12.5.2 Bathrooms - Toilets: Toilet loose at floor
- ⊖ 12.7.1 Bathrooms - Showers: Shower fixture is loose
- ⚠ 12.8.1 Bathrooms - Shower Walls: Gaps present
- ⊖ 12.9.1 Bathrooms - Enclosures / Shower doors: Gaps present
- ⊖ 12.10.1 Bathrooms - Exhaust Fans: Exhaust fan noisy
- ⊖ 12.10.2 Bathrooms - Exhaust Fans: Light did not operate
- ⚠ 13.3.1 Interior - Ceiling Conditions: Evidence of moisture accumulation
- 🔧 13.4.1 Interior - Floor Conditions: Recommend grout and sealer maintenance
- ⊖ 13.4.2 Interior - Floor Conditions: Cracked tile(s)
- ⊖ 13.5.1 Interior - Doors: Sticks at jamb
- ⊖ 13.5.2 Interior - Doors: Loose hinges – service recommended
- ⊖ 13.6.1 Interior - Window Conditions: Window glazing gapped at frame – service recommended
- ⊖ 13.6.2 Interior - Window Conditions: Missing screens
- 🔧 13.8.1 Interior - Electrical: Bulbs missing/ not functioning
- ⊖ 13.8.2 Interior - Electrical: Loose outlet(s)
- ⊖ 13.8.3 Interior - Electrical: Lights flicker when operating
- ⊖ 13.8.4 Interior - Electrical: Recessed lights not operating
- ⊖ 13.8.5 Interior - Electrical: Missing cover
- ⊖ 13.9.1 Interior - Sliding Glass Doors: Did not latch/lock properly
- ⊖ 13.10.1 Interior - Sliding Door Screens: Did not latch/lock properly – service recommended
- ⊖ 13.10.2 Interior - Sliding Door Screens: Difficult to slide/operate
- ⊖ 13.11.1 Interior - Cabinets: Drawer does not open/close properly
- ⊖ 13.11.2 Interior - Cabinets: Delaminated cabinet
- ⊖ 13.12.1 Interior - Counters: Gaps present
- ⚠ 13.14.1 Interior - Stairs & Handrails: Missing handrails
- ⊖ 13.14.2 Interior - Stairs & Handrails: Loose trim pieces
- ⚠ 13.14.3 Interior - Stairs & Handrails: Loose glass
- ⚠ 13.22.1 Interior - Smoke Detectors: Missing
- ⚠ 13.23.1 Interior - Carbon Monoxide Detectors: Missing
- ⊖ 14.1.1 Heating/Air Conditioning - Air Conditioning Compressors: Unit is not level
- ⊖ 14.1.2 Heating/Air Conditioning - Air Conditioning Compressors: Unit sits low in grading area
- ⊖ 14.1.3 Heating/Air Conditioning - Air Conditioning Compressors: R22 refrigerant
- ⊖ 14.2.1 Heating/Air Conditioning - Refrigerant Lines: Insulation gap(s) observed
- ⊖ 14.3.1 Heating/Air Conditioning - Heaters: Noisy
- ⚠ 14.3.2 Heating/Air Conditioning - Heaters: Gas-fired Heater in Bedroom
- ⊖ 14.5.1 Heating/Air Conditioning - A/C Evaporator Coil Box: No secondary drain / Cut out switch
- ⚠ 14.9.1 Heating/Air Conditioning - Thermostats: Missing thermostat
- ⊖ 14.11.1 Heating/Air Conditioning - Filters: Dirty Filter
- ⊖ 14.14.1 Heating/Air Conditioning - Heater Enclosures: Dry moisture stains observed in enclosure
- ⊖ 15.3.1 Foundation - Sub Flooring: Insulation detaching and falling

- ⊖ 15.5.1 Foundation - Walls: Efflorescence present
- ⊖ 15.7.1 Foundation - Ventilation: Evidence of rodent/pest activity in the crawlspace
- 🔧 15.8.1 Foundation - Vent Screens: Worn/bent/small holes –
- ⊖ 15.12.1 Foundation - Plumbing: Unused plumbing
- ⚠ 15.12.2 Foundation - Plumbing: Cast iron corrosion
- ⊖ 16.1.1 Sewerline inspection - Defects: Cast iron : moderate corrosion
- ⚠ 16.1.2 Sewerline inspection - Defects: Backed up water at 56-68 approximate ft

1: INSPECTION DETAILS

Information

Details: Type of Inspection
Pre-Purchase

Details: In Attendance
Client, Buyer Agent

Details: Wall materials
Drywall

Details: Window materials
Double pane, Vinyl framed

Details: Style of Home
Two Story

Details: Occupancy
Occupied, Furnished

Details: Ceiling Materials
Drywall


Details: Weather
Clear

Details: Utilities
Electric, Gas, Water

Details: Floor coverings
Tile, Carpet

Details: Exterior Reference Photos

Photos of multiple sides of the property for reference



**Details: Inspection checklist**

Lights off, Oven off, HVAC off, Dishwasher off, Doors closed (garage included), Range off, Fixtures off

Items checked prior to departing inspection. The inspector is not responsible for any other parties present during the time of the inspection and their actions.

Limitations

Details

UTILITIES ON/OFF

Water on, Electricity on, Gas off

Any utilities that are off during the inspection will limit the inspection of any devices requiring water, gas, or electricity.

Details

LIMITED THERMOGRAPHIC INSPECTION

The Inspector has performed a General Home Inspection only. Although the Inspector may include images from a thermal imaging device (also known as an "infrared camera"), these images are supplemental to the General Home Inspection. You should be aware that the inspector has not performed a full, comprehensive thermographic inspection, but has used the device as a peripheral tool only.

Details

OCCUPIED/ FURNISHED/ STAGED

During the inspection process, our inspectors exercise caution to avoid damage. Therefore, they do not move personal belongings, furniture, or adhere to specific handling instructions. This practice is in place to prevent any potential harm to your property or the items within it. As a result, the presence of personal items and furnishings may limit the thoroughness of the inspection, particularly in areas covered or obstructed by these items. Areas such as electrical outlets, windows, walls, floors, countertops, cabinetry, closets, and drawers may not be fully inspected if obstructed. We recommend considering additional inspections if necessary to ensure a comprehensive evaluation of the property's condition.

Details

INSPECTION NOTES

The purpose of this inspection is primarily to identify major material defects in the property. Major material defects refer to significant issues that may affect the functionality, safety, or structural integrity of the home. On the other hand, minor and cosmetic issues are typically not included in the inspection or report, although they may be mentioned as a courtesy in some cases.

Cosmetic issues generally include small nail holes, drywall nail pops, minor cracks, chipped areas, dirty spots, and other superficial blemishes. These issues, while noticeable, are considered to be cosmetic in nature and do not pose a significant impact on the overall condition or livability of the property.

In some instances, small cracks may be observed throughout the structure. This occurrence is often seen in California construction and can be attributed to settling, earthquakes, and wind conditions. It is important to understand that such cracking is relatively common and, unless severe or indicative of more significant problems, is typically considered within the acceptable range for construction in the region.

It is crucial to note that this inspection should not be misconstrued as a code inspection. The inspection is conducted within a limited time frame and scope, focusing primarily on identifying major material defects. It does not involve a comprehensive evaluation of the property's compliance with local building codes or regulations.

To ensure a thorough understanding of the property's compliance with applicable codes, it is strongly recommended that the buyer or homeowner request all building permits and work orders associated with the property. These documents should be obtained as soon as possible and reviewed by a licensed professional, such as a contractor or building inspector, before finalizing the purchase or making any major decisions. This additional evaluation will provide a more comprehensive understanding of the property's construction history and any potential code-related concerns.

In summary, this inspection is specifically designed to identify major material defects in the property, while minor cosmetic issues are generally excluded. Small cracks and cosmetic blemishes are typically considered within acceptable limits for California construction. It is important to recognize that the inspection does not serve as a substitute for a thorough code inspection, and obtaining all relevant permits and work orders is essential for a comprehensive assessment of the property's compliance with building codes and regulations.

The inspector does not check for product recalls or manufacturer notices. Observations and comments provided in this report represent a general overview of visible conditions at the time of inspection. Not all defects are photographed or specifically noted. If concerns are identified in one area, it is recommended that all areas of similar materials or components be further evaluated by a qualified professional.

By accepting this report, the client acknowledges and agrees to read the full report in its entirety.

All recommended actions, repairs, or evaluations should be completed prior to closing or finalizing the transaction

Details**RECENTLY PAINTED IN AREAS**

There were areas of the property that were observed to have been painted recently. We recommend inquiring with seller for any past/present repairs in these areas. It is often difficult to assess the conditions of these areas, including the presence of any damage, moisture or microbial growth. Inspection is limited

Details**GAS OFF**

This inspection will not include any items that use gas/propane to function

Details**TERMITE/ ASBESTOS/ MOLD/ LEAD PAINT/ HIDDEN DEFECTS**

Disclaimer: Please be aware that this general home inspection has certain limitations and exclusions that you should be aware of. The following items, which include but are not limited to Termite/Asbestos/Mold/Lead paint, as well as hidden defects, are specifically excluded from this inspection and report:

1. Termite Inspection: This inspection does not encompass a comprehensive assessment for the presence of termites or other wood-destroying organisms. It is highly recommended to engage a qualified pest control professional to conduct a separate termite inspection to evaluate the potential presence of wood-destroying pests and any related damage.
2. Asbestos Inspection: This inspection does not include the identification or testing of asbestos-containing materials. Due to the specialized nature of asbestos identification and potential health risks, it is advisable to consult with an asbestos professional who can conduct a dedicated inspection if you suspect the presence of asbestos materials.
3. Mold Inspection: This inspection does not involve mold testing or identification. Mold growth and related issues require specialized expertise. If you have concerns about mold or indoor air quality, it is recommended to engage a qualified mold inspector or industrial hygienist to perform a separate assessment.
4. Lead Paint Inspection: This inspection does not encompass a comprehensive evaluation for the presence of lead-based paint. If your property was built before 1978 when the use of lead-based paint was common, it is advisable to hire a certified lead inspector to assess the presence of lead-based paint and any associated risks.
5. Hidden Defects: This inspection cannot identify hidden defects that are concealed within walls, ceilings, or other inaccessible areas of the property. It is important to understand that certain issues may only become apparent during more invasive or specialized inspections, such as thermal imaging, structural engineering evaluations, or specific system inspections.

Please note that the scope of this general inspection is limited to a visual assessment of accessible and visible areas and does not encompass specialized inspections for the items listed above or other potential issues not explicitly mentioned. It is recommended to engage qualified professionals with expertise in these specific areas to address any concerns or conduct further inspections as necessary.

Remember that this general inspection serves as a snapshot of the property's condition at the time of the inspection and may not capture all potential issues or hazards that may exist. It is advised to consider additional inspections or evaluations based on specific concerns or the recommendations of relevant experts to ensure a more comprehensive assessment of the property.

Details

SOLAR (IF PRESENT)

ROOF

This Inspection does not evaluate or inspect any part of any solar system or its components. The solar system, if present, falls outside of the scope of a general inspection . these systems should be evaluated by the appropriate qualified professional prior to closing