

REAL ESTATE INFORMATION NETWORK, INC.
PROPERTY INSPECTION CONTINGENCY REMOVAL ADDENDUM

This document forms an integral part of the Purchase Agreement ("Agreement") dated 01/12/2026, between Diane Nwaonicha ("Buyer") and Jemal Tamem ("Seller"). Berkshire Hathaway HomeServices RW Towne Realty ("Selling Firm") and AtCoastal Realty ("Listing Firm") for the sale of certain property commonly known as (Address): 4232 Maplehurst Road, Virginia Beach, VA 23462

Subject to A or B below, the following property inspection contingencies are hereby removed and a complete copy of the applicable Inspection(s) is attached:

(Check As Applicable)

☒ Property Inspection ☐ EIFS ☐ Lead-Based Paint Assessment ☐ Other

Mark as appropriate: A or B

☐ (A) No repairs are necessary; OR

☒ (B) **Requested Repair Items:** Seller agrees to make all repairs listed below at Seller's expense. The total cost of Requested Repair Items agreed to be repaired by Seller shall not be included in the Cap referenced in Paragraph 13 of the Agreement, unless otherwise agreed to in writing. In the performance of an EIFS repair, Seller is to use a qualified professional with experience in this field. All repairs to be completed in a workmanlike manner prior to walk through and evidence of payment, if applicable, for such work shall be provided to Buyer prior to Walk-through.

Buyer, at Buyer's expense, reserves the right to have the original inspector/firm inspect such work upon completion. Such inspection may occur at or prior to the Walk-Through. Seller remains obligated to perform all obligations under Paragraph 12 of the Agreement. Furthermore, subject to the Cap, Seller remains obligated to repair any Waived Items that fall under Paragraph 13A (Appraisal and Required Repairs), B (Wood Destroying Insect Infestation / Moisture Inspection / Repairs) or C (Well and Septic) of the Agreement.

Flashings and Penetrations

4.1. Gypsum flashing (s) should be secured and sealed to prevent moisture intrusion. Location: power ventilator

Exterior

Vinyl Siding Item: 1 1.4. Damage to the vinyl siding which can allow moisture intrusion and should be repaired. Location: front middle

Eaves, Soffits, and Trim

~~3.4. Multiple trim issues were observed, examples are listed in the report. A qualified contractor should make all necessary repairs.~~

Exterior Doors

4.1. Damage to an exterior door should be repaired or replaced as needed. Location: shed

HVAC

Condensate Drain(s) 6.2. There was no auxiliary condensate drain line or float switch installed at the condensate pan and should be corrected to prevent moisture damage if pan fills with water.

Plumbing

Water Heater

6.3. Issues were observed with the water heater, examples are in the report. Due to the age of the water heater we recommend a qualified plumbing contractor determine if repair or replacement

7.1. A hose spigot that was leaking while turned off should be repaired. Location: front

8.1. Leaking faucet controls should be repaired as needed. Location: kitchen sink

9.2. Leaking sinks should be repaired as needed. Location: kitchen sink, master bath sink

10.3. Leaking bathtub faucet controls should be repaired as needed. Location: master bathroom

10.4. There is damage to the bathroom tubs that should be repaired/replaced Location: Master & hall

12.2. A toilet ran continuously indicating the need for repair. Location: Upstairs hall bath

~~\$5,000.00~~

In lieu of any repairs, Buyer and Seller agree that Seller shall provide Buyer with a credit in the amount of ~~\$2,000.00~~ to be applied toward Buyer's closing costs and/or prepaid expenses at settlement. ~~No repairs shall be required of Seller.~~ Seller to cover the cost of a Choice Home Warranty (up to \$725).

\$7,000.00

AuthenticSource
JT DN
01/29/26
7:07 PM EST
dotloop verified

 **Selling Agent**

Page 1 of 2

~~DN~~
01/29/26
7:07 PM EST
dotloop verified

Selling Broker commission shall be reduced by 0.5%, for a total of 2.5%

Initial: Buyer

Seller

PROPERTY INSPECTION CONTINGENCY REMOVAL ADDENDUM (Continued)

Subject Property: 4232 Maplehurst Road, Virginia Beach, VA 23462

Buyer: Diane Nwaonicha

Seller: Jemal Tamem

~~12.1 Tighten toilet-hall bath
11.1. Leaking shower heads should be tightened or sealed to prevent moisture damage. Location: Upstairs hall bath
11.2. Loose shower head(s) Location: upstairs hall bath, master bath
3.5. A clear and complete circuit directory should be installed, and circuit size verified for correct installation, so that in an emergency individual circuits can be quickly shut off. Label circuit panel.
3.4. Breaker(s) were off in the main electrical service panel -Have electrician evaluate breakers are functioning as they should, correct size, etc. since they have been turned off.
3.6. Rust or corrosion was present in the panel and a qualified electrical contractor should determine source of moisture and repair as needed.
9.2. There was a loose ceiling fan which should be repaired master bedroom
9.3. Improper installation of a light fixture in the living room should be repaired or removed (over living room windows)
2.1 Repair/replace attic light fixture
7.4. Multiple receptacles issues were observed. Have a licensed electrician evaluate/repair/replace ALL outlets (GFCI's where required) and switches as needed.
10.3. There was a central security panel present. We did not engage the smoke alarm test buttons in order to prevent causing a false alarm with a security company. Confirm all smoke alarms function as they should.
Interior and Property Information
Loose railing(s) at the stairs should be secured to provide safe conditions. Location: bottom and top of staircase
3.2. Bathroom fans terminated in the attic fan can allow moisture into the attic and cause damage to the fans. Properly reroute bath fan terminations.
6.2. There were indications of moisture intrusion evidenced by stained roof deck, but the location was not accessible to test. All necessary repairs should be made if not previously corrected. Location: rear left, front right, rear right. Have evaluated by licensed roofing contractor.
6.3. Damaged roof sheathing should be repaired as needed. Location: rear power ventilator, front left plumbing vent, right of ventilator, front right- Have evaluated by licensed roofing contractor.
4.1 Window: repair/replace Location: living room right
6.2 Repair doors to latch properly. Location: water heater closet, left living area closet
3.1-3.3-Dishwasher leaks, repair to make sure it functions as it should. Could not properly test due to personal items present
4.1. The disposal was inoperable and should be repaired/replaced
12.2. There were visible observations of environmental conditions which are outside the scope of a home inspection listed in the interior section under Environmental Observations. Have appropriate company evaluate for possible remediation.~~
~~*** All repairs to be made by licensed contractors in their fields,
*** Inspection to take place 5 days prior to closing.
*** All invoices to be shared prior to final walkthrough. All invoices are to have the license information for each contractor/company included.
*** Remove all trash/personal property not listed on items to convey from interior/exterior of property prior to final walkthrough. Thank you.~~

Received by: [Signature]

Berkshire Hathaway HomeServices RW Towne Realty
(Selling Firm)

By: *Bobbi Wood* dotloop verified 01/20/26 9:47 AM EST 2MGZ-VQEV-DOKT-PZIC
(Date)

AtCoastal Realty
(Listing Firm)

By: *[Signature]* Authentisign 01/24/2026
(Date)

Diane Nwaonicha dotloop verified 01/20/26 9:52 AM EST FCTM-QYUY-J2DD-JFLA
(Buyer) (Date)

[Signature] (Buyer) (Date)

Jemal O Tamem 01/24/2026
(Seller) (Date)

[Signature] (Seller) (Date)

(FOR AGENT USE ONLY)

FOR COMPLETION BY AGENT VERIFYING REMOVAL ACCEPTANCE DATE:

This Property Inspection Contingency Removal Addendum has been accepted by all parties as of _____ ("Removal Acceptance Date").

SIGNATURE: [Signature]


☐ LISTING AGENT ☐ SELLING AGENT

AMENDMENT / ADDENDUM TO PURCHASE AGREEMENT



This document forms an integral part of the Purchase Agreement ("Agreement") dated _____, between Diane Nwaonicha ("Buyer") and Jemal O Tamem ("Seller") and Berkshire Hathaway HomeServices RW Towne Realty ("Selling Firm") and AtCoastal Realty ("Listing Firm") for all that certain piece, parcel or lot of land described as follows: 4232 Maplehurst Rd VA 23462 ("Property").

The undersigned Buyer and Seller hereby agree to the following:


  ~~\$7,000.00~~
~~\$5,000.00~~
~~\$10,000.00~~
 

Buyer and Seller agree that Seller shall provide Buyer with a credit in the amount of ~~\$2,000.00~~ to be applied toward Buyer's closing costs and/or prepaid expenses at settlement. No repairs shall be required of Seller.

~~Seller~~ to cover the cost of a Choice Home Warranty up to \$725.

Selling Agent





Selling Broker commission shall be reduced by 0.5%, for a total of 2.5%




Except as expressly set forth above, all of the other terms and conditions of the Agreement not modified above, shall remain unchanged and in full force and effect.

Berkshire Hathaway HomeServices RW Towne Realty

(Selling Firm)

By:  
Bobbi Wood (Date)

(Buyer) Diane Nwaonicha (Date)

(Buyer) _____ (Date)

 Jemal O Tamem 01/24/2026
(Seller) Jemal O Tamem (Date)

AtCoastal Realty
(Listing Firm)
 01/24/2026
By: Shannon Paschall (Date)

(Seller) _____ (Date)

FOR OPTIONAL USE AS PARTIES MAY ELECT

MOISTURE INSPECTION REPORT		
NAME & ADDRESS OF INSPECTION COMPANY Pest Heroes 2128 London Bridge Rd. Suite 103 Virginia Beach, VA 23456		ADDRESS OF PROPERTY INSPECTED 4232 Maplehurst Rd Virginia Beach, VA 23462
		DATE OF INSPECTION 2026-01-19 INSPECTION FEE 79.00
BASED ON A CAREFUL INSPECTION OF THE READILY ACCESSIBLE AREAS OF THE UNDERSTRUCTURE (AS DESCRIBED ON THE REVERSE SIDE) OF THE PROPERTY LISTED ABOVE:		
There is evidence of the presence of wood destroying fungi below the floor level of the first main floor.		YES ☐ NO ☐
There is evidence of the presence of excessive moisture conditions below the floor level of the first main floor. (If yes, describe under comments)		YES ☐ NO ☐
At the time of our inspection, there were visible damaged wooden members below the floor level of the first main floor caused by fungi.		YES ☐ NO ☐
IF ANY DAMAGE IS OBSERVED (AS SHOWN ABOVE) THAT DAMAGE WILL (CHECK ONE BELOW):		
☐ Be corrected or has been corrected by this company.		
☐ Be corrected by another company, see attached contract.		
☐ NOT be corrected by this company which recommends that damage be evaluated by a qualified building expert and that needed repairs be made.		
WERE ANY AREAS OF THE UNDERSTRUCTURE OBSTRUCTED OR INACCESSIBLE? (If yes, describe under comments)		YES ☒ NO ☐
COMMENTS House on slab no inspection below possible		
SIGNATURE OF INSPECTOR: 		
This report shall not be valid until the following statement of the property owner(s) or their duly authorized representatives is signed: THE UNDERSIGNED OWNER(S) OF THE ABOVE DESCRIBED INSPECTED PROPERTY HEREBY ACKNOWLEDGE THAT THEY ARE UNAWARE OF ANY PREVIOUS MOISTURE DAMAGE OR DIFFICULTIES INVOLVING MOISTURE THROUGHOUT THEIR OWNERSHIP OF SAID PROPERTY, OTHER THAN AS REPORTED ABOVE.		
DATE: 2026-01-19PROPERTY OWNER:  Jemal O Tamem 01/24/2026PROPERTY OWNER: _____		
ACKNOWLEDGEMENT: Purchaser acknowledges that he has received a copy of this report.		
DATE ACKNOWLEDGED: 2026-01-19		PURCHASER'S SIGNATURE:  dotloop verified 01/28/26 12:51 PM EST PROR-25HJ-OHWS-BQJ1

Wood Destroying Insect Inspection Report

Notice: Please read important consumer information on **page 2**.

Section I. General Information

Inspection Company, Address & Phone

Pest Heroes

2128 London Bridge Rd. Suite 103
Virginia Beach, VA 23456
(757) 367-8342

Company's Pest Control Business Lic. No.
15611

Date of Inspection
2026-01-19

Address of Property Inspected
**4232 Maplehurst Rd
Virginia Beach, VA 23462**

Inspector's Name, Signature & Certification, Registration, or Lic. #

Scott cohen 91177c



Structure(s) Inspected

Shared wall townhouse w att shed

Section II. Inspection Findings

This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or wood destroying insect damage. **Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:**

☒ A. **No Visible** evidence of wood destroying insects was observed.

☐ B. **Visible** evidence of wood destroying insects was observed.

☐ 1. Live insects (description & location):

☐ 2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location):

☐ 3. **Visible** damage from wood destroying insects was noted as follows (description and location):

NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs.

Section III. Recommendations

☒ No action and/or treatment recommended: (Explain if Box B in Section II is checked):

☐ Recommended action(s) and/or treatment(s) for the control of:

Section IV. Obstructions and Inaccessible Areas

The following areas of the structure(s) inspected were obstructed or inaccessible:

- ☐ Basement _____
- ☐ Crawlspace _____
- ☒ Main Level **13,4,9** _____
- ☐ Attic _____
- ☐ Garage _____
- ☒ Exterior **17** _____
- ☐ Porch _____
- ☐ Addition _____
- ☒ Other **Att shed 6,7,9,11** _____

The inspector may write out obstructions or use the following optional key:

- | | |
|-------------------------|--|
| 1. Fixed ceiling | 15. Standing water |
| 2. Suspended ceiling | 16. Dense vegetation |
| 3. Fixed wall covering | 17. Exterior siding |
| 4. Floor covering | 18. Window well covers |
| 5. Insulation | 19. Wood pile |
| 6. Cabinets or shelving | 20. Snow |
| 7. Stored items | 21. Unsafe conditions |
| 8. Furnishings | 22. Rigid foam board |
| 9. Appliances | 23. Synthetic stucco |
| 10. No access or entry | 24. Duct work, wiring, and/or plumbing |
| 11. Limited access | 25. Spray foam insulation |
| 12. No access beneath | 26. Equipment |
| 13. Only visual access | |
| 14. Cluttered condition | |

Section V. Additional Comments and Attachments (these are an integral part of the report)

Attachments **Moisture report invoice**

Signature of Seller(s) or Owner(s) if refinancing. Seller discloses to the buyer all information, to their knowledge, regarding W.D.I. infestation, damage, repair, and treatment history.

X  **Jemal O Tamem**

01/24/2026

Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.

X



dotloop verified
01/28/26 12:51 PM EST
TPAK-YM5M-WMZZ-KGYA

to the Property and finds any and all such measurements to be acceptable and shall not use the size, acreage or square footage of the Property as the basis for any termination of this Agreement. Buyer agrees to waive, release and discharge all parties to this Agreement, including REIN, from any and all claims that the square footage, acreage or other measurements of the Property were incorrectly stated in any literature concerning the Property generated by REIN's MLS Systems, including Listing and / or Tax reports.

H. PENDING BUILDING OR ZONING VIOLATIONS: Unless disclosed in writing below Seller has no actual knowledge that the Property has pending enforcement actions pursuant to the Uniform Statewide Building Code. Section 55.1-706 of the Code of Virginia states that if the Seller of a residential dwelling unit has actual knowledge of any pending enforcement actions pursuant to the Uniform Statewide Building Code that affect the safe, decent, sanitary living conditions of the Property of which the Seller has been notified in writing by the locality, or any pending violation of the local zoning ordinance that the violator has not abated or remedied under the zoning ordinance, within a time period set out in the written notice of violation from the locality or established by the court of competent jurisdiction, the Seller shall provide to a prospective Purchaser a written disclosure that so states. Such disclosure shall be provided to the Purchaser on a form provided by the Real Estate Board on its website.

I. PROPERTY PREVIOUSLY USED TO MANUFACTURE METHAMPHETAMINE: If a Seller of residential real property has actual knowledge that the Property being sold (1) was previously used to manufacture methamphetamine and (2) has not been cleaned up in accordance with state guidelines, the Seller is required to provide a written disclosure to Buyer in accordance with Section 55.1-708 of the Code of Virginia. Pursuant to Section 32.1-11.7 of the Code of Virginia, the Virginia Board of Health established Guidelines for Cleanup of Residential Property Used to Manufacture Methamphetamine. If applicable, the Disclosure Statement for Residential Property Previously Used to Manufacture Methamphetamine is attached to this Agreement as required by the Code of Virginia.

J. LIS PENDENS: If the owner of a residential dwelling unit has actual knowledge of a lis pendens filed against such dwelling unit pursuant to Section 8.01-268, such owner shall provide to a prospective purchaser a written disclosure that so states. Such disclosure shall be provided to the purchaser on a form provided by the Real Estate Board on its website.

17. BROKERAGE FEE: Selling Firm and Listing Firm are intended to be, and are, third party beneficiaries of this Agreement with respect to payment of the brokerage fee and are entitled to payment at settlement as provided by separate agreement(s). Buyer and Seller each represent and warrant to each other that they dealt with no broker in connection with, nor has any broker had any part in bringing about, this transaction other than the Listing Firm and/or Selling Firm identified herein. At closing, (i) provided that Selling Firm represents Buyer in some capacity, (A) Seller shall pay a brokerage fee due Selling Firm, if any, as follows (CHECK ONLY ONE):

 ^{2.5} ☒ percent of the Purchase Price; **OR**
☐ the sum of \$ _____,

which brokerage fee is deemed earned as of the ratification of the Agreement, and (B) Buyer shall pay additional brokerage fees due Selling Firm (and not paid by Seller pursuant to the foregoing), if any, in accordance with the terms of a separate agreement between Buyer and Selling Firm, and (ii) Seller shall pay brokerage fees due Listing Firm, if any, in accordance with the terms of a separate agreement between Seller and Listing Firm. The settlement agent shall disburse the brokerage fee to Listing Firm and Selling Firm at settlement.

Seller and Buyer shall each indemnify, defend, and hold harmless the other from and against any claim of any broker or other person for any brokerage fee, commissions, finder's fees, or other compensation in connection with this transaction if such claim is based in whole or in part by, through, or on account of, any acts of the indemnifying party or its agents, employees, or representatives and from all losses, liabilities, costs, and expenses in connection with such claim, including without limitation, reasonable attorneys' fees, court costs, and interest. The provisions of this Section 17 shall survive the closing, or the termination of this Agreement prior to the closing.

18. DEFAULT: Subject to the provisions of paragraph 19 below, if either party defaults under this Agreement, the nondefaulting party may pursue, in such party's discretion, all remedies available to the nondefaulting party at law or in equity. In the event of default, Escrow Agent shall pay the Deposit to the nondefaulting party in accordance with paragraph 5B and the nondefaulting party shall have the right to pursue such other rights and remedies against the defaulting party as the nondefaulting party may have, both legal and equitable. All of the rights and remedies hereunder are cumulative. The defaulting party shall be liable for the brokerage fee due Listing Firm and Selling Firm



5350 Kemps River Drive, Suite 108 A, Virginia Beach, VA 23464
Telephone: (757) 512-6364 Facsimile: 757-420-3811
Email: vbrooks@caplanlegal.com
Website: www.CaplanLegal.com

SELLER/BORROWER'S AUTHORIZATION FORM

RE: PROPERTY ADDRESS: 4232 Maplehurst Road, Virginia Beach, VA 23462

File No. 93332-0126

To Whom It May Concern:

I/We **Jemal Tamem** do hereby authorize you to release to Valerie M. Brooks & Caplan Law Group the following information concerning:

- Mortgage and other Loan balances (including Faxed or Verbal Payoff Statements)
- Certificate's of Satisfaction and/or any lien release information
- Homeowners/Flood Insurance Information

This information is for the confidential use of this company for the Refinance, Purchase and/or Sale of the above captioned property address.

 *Jemal O Tamem*

02/02/2026

Jemal Tamem date

Social Security No.: _____

Lender Name: _____

Lender customer service phone number: _____

Loan Number: _____

Your forwarding address: _____

A photographic or carbon copy for this authorization (being photographic or carbon copy of the signature(s) of the undersigned, may be deemed to be the original and may be used as a duplicate original.