

TRAINING DOCUMENT · SKILLCLOUD ACADEMY

All names, data, and circumstances are fictional. For educational use only.

STRUCTURAL PEST CONTROL INSPECTION REPORT (WDO)

Atlas Pest Control · Report #WDO-2025-4128 · License #OPR-11482 · Date: October 15, 2025

PROPERTY & INSPECTION DETAILS

Address:	4827 Rolando Blvd, San Diego, CA 92115
Inspector:	Robert Vance (Atlas Pest Control, Branch 3 License #RA-49811)
Inspection Date:	October 15, 2025
Building Type:	Single Family Residence with Detached 2-Car Garage

SECTION 1 FINDINGS (ACTIVE INFESTATION / INFECTION)

Section 1 contains items where there is active wood-destroying organism infestation or infection:

Finding 1A: Subterranean Termites — Detached Garage

Description: Active subterranean termite shelter tubes and live worker termite activity observed along the interior south sill plate and stud bay framing of the detached 2-car garage.

Recommendation: Trench and treat soil along garage perimeter with registered termiticide (Termidor HE) and drill/inject concrete slab edge where wood contacts foundation.

Estimated Cost for Treatment: \$1,850.00

SECTION 2 FINDINGS (CONDITIONS CONDUCTIVE)

Finding 2A: Earth-to-Wood Contact

Wood fence post adjacent to east exterior wall makes direct contact with soil. Recommend clearing soil line 2 inches below wood fence base.

Estimated Cost: \$250.00 (Optional preventive maintenance)