

Reference:

FOUNDATION ASSESSMENT REPORT

Pacific Foundation Engineering, Inc. | CA PE License #C-67482

Assessment Date: October 17, 2025 | Engineer: Dr. Alan Briggs, P.E. | Report #PFE-2025-0847

Property: 4827 Rolando Blvd, San Diego, CA 92115 | APN: 470-362-18-00

1. PURPOSE

This assessment was requested by the buyer's agent to evaluate a hairline crack in the south perimeter foundation wall identified during the general home inspection (Precision Home Inspections, Report #PHI-2025-1847, dated October 14, 2025).

2. OBSERVATIONS

Foundation Type: Raised perimeter foundation with concrete stem walls and spread footings. Wood-framed floor system above.

Crack Description: A single hairline crack was observed on the interior face of the south perimeter wall, approximately 3 feet in length and less than 1/16 inch in width. The crack is vertical and shows no lateral displacement or offset.

Floor Levelness: Floor level measurements taken at 12 points across the structure. Maximum deviation: 3/8 inch over 20 feet — within normal tolerances for a structure of this age.

Crawl Space: No evidence of water intrusion, excessive moisture, or soil movement. Ventilation adequate.

3. ASSESSMENT

Classification: NO STRUCTURAL DEFICIENCY

The observed crack is consistent with minor cosmetic settling typical of homes of this age and construction type. There is no evidence of ongoing movement, structural compromise, or foundation failure. The crack does not require structural repair.

4. RECOMMENDATION

Seal the crack with an elastomeric sealant (e.g., epoxy injection) to prevent moisture penetration. This is a maintenance item, not a structural repair.

Estimated cost of repair: \$2,200 (epoxy crack seal and monitoring pins).

5. LIMITATIONS

This assessment is based on visual observation and accessible areas only. Concealed conditions, areas beneath finishes, and subsurface conditions are excluded. This report is valid as of the date of inspection and does not warrant future performance. A licensed contractor should be engaged for any repair work.

Dr. Alan Briggs, P.E.

10/17/2025

Dr. Alan Briggs, P.E.

Date

Pacific Foundation Engineering, Inc. · 2847 Camino del Rio South, Suite 200, San Diego, CA 92108 · (619) 555-0287

Buyer's Initials (SC)(DP) Seller's Initials (PO)(RO)

4827 Rolando Blvd, San Diego, CA 92115 — Escrow #FNT-2025-09184