

REAL ESTATE INFORMATION NETWORK, INC.
PROPERTY INSPECTION CONTINGENCY REMOVAL ADDENDUM



This document forms an integral part of the Purchase Agreement ("Agreement") dated 02/22/2026,
between Sergio P Malonzo, Jr and Jasmin Malonzo ("Buyer")
Jemal O Tamem ("Seller")
BHHS RW Towne Realty ("Selling Firm")
and AtCoastal Realty ("Listing Firm")
for the sale of certain property commonly known as (Address): 4232 Maplehurst Road, Virginia Beach, VA 23462

Subject to A or B below, the following property inspection contingencies are hereby removed and a complete copy of the applicable Inspection(s) is attached:

(Check As Applicable)

☐ Property Inspection ☐ EIFS ☐ Lead-Based Paint Assessment ☐ Other _____

Mark as appropriate: A or B

☐ (A) No repairs are necessary; OR

☒ (B) **Requested Repair Items:** Seller agrees to make all repairs listed below at Seller's expense. The total cost of Requested Repair Items agreed to be repaired by Seller shall not be included in the Cap referenced in Paragraph 13 of the Agreement, unless otherwise agreed to in writing. In the performance of an EIFS repair, Seller is to use a qualified professional with experience in this field. All repairs to be completed in a workmanlike manner prior to walk through and evidence of payment, if applicable, for such work shall be provided to Buyer prior to Walk-through.

Buyer, at Buyer's expense, reserves the right to have the original inspector/firm inspect such work upon completion. Such inspection may occur at or prior to the Walk-Through. Seller remains obligated to perform all obligations under Paragraph 12 of the Agreement. **Furthermore, subject to the Cap, Seller remains obligated to repair any Waived Items that fall under Paragraph 13A (Appraisal and Required Repairs), B (Wood Destroying Insect Infestation / Moisture Inspection / Repairs) or C (Well and Septic) of the Agreement.**

The following to be completed by a licensed and qualified Roofing Contractor
1.0 Have staining evaluated for possible leaks and repair as recommended.
2.4 (1-4) Replace missing Soffits and repair or replace loose soffit panels at the front of home and rear of home.
2.4 (5) Secure or replace loose rake board metal wrap at the left side is loose and paint to match if needed.

The following to be completed by a licensed and qualified Plumbing Contractor
5.0 (1-4) Repair or replace if needed, loose toilets and tanks in the hall bath and primary bath.
5.0 (5-6) Install missing stop-valve in the Primary Bath sink and Half Bath sink
5.1 (1-2) Repair or replace dripping front hose bib.
5.1 (3-10) Repair or replace all three shower/tub water controls; Hot, Cold, and Diverter. (leak(s) behind handle when the water is turned on)
5.1 (11-12) Replace broken plumbing supply shut-off(s) "gate valve" handle in the utility room
5.1 (17) Repair/secure loose shower head water supply arm in the wall @ primary bath
5.1 (18) Repair or replace at the kitchen sink spray nozzle to function as intended
9.3 Replace seized garbage disposal and install missing hose clamp from dishwasher.

The following to be completed by a licensed and qualified Electrical Contractor
6.3 (7-10) The ceiling fan lights do not function in the primary bedroom (no power), repair or replace to light/fan fixture to operate properly.
6.4 (1) Install GFCI protected Outlet(s) within six feet of the kitchen sink.
6.5 One GFCI (Ground Fault Circuit Interrupter) protected outlet at the Hall Bath has a short. Replace GFCI outlet

HVAC:
7.5 (1) and 7.0 (1) Have the HVAC system professionally cleaned, evaluated, and repaired as recommended by a licensed HVAC contractor to ensure the system is operating properly.

Please see below

  
dot03/06/2026
3:44 AM EST 9:31 AM EST ified

Initial: Buyer


02/25/26
3:18 PM EST
dotloop verified


02/25/26
3:18 PM EST
dotloop verified

Seller





PROPERTY INSPECTION CONTINGENCY REMOVAL ADDENDUM (Continued)

Subject Property: 4232 Maplehurst Road, Virginia Beach, VA 23462

Buyer: Sergio P Malonzo, Jr and Jasmin Malonzo

Seller: Jemal O Tamem

Seller has reviewed Buyer's repair request and appreciates the thorough inspection. The agreed contract price and terms reflect the property's current condition and anticipated updates.

Seller declines to complete the requested repairs and prefers to sell the property in its present "as-is" condition.

However, Seller is willing to modify the contract as follows:

Purchase Price to be increased to \$290,000.

Seller to provide Buyer a credit at closing in the amount of \$5,000 to be applied toward Buyer's closing costs, prepaids, and/or other lender-approved expenses.

This modification is subject to the appraisal provisions contained in the Agreement. In the event the property does not appraise at or above \$290,000, the appraisal contingency and all related rights and remedies under the Agreement shall remain in full force and effect.

All other terms and conditions of the Agreement remain unchanged.

  
03/06/26 03/06/26
3:24 AM EST 03/06/26 03:04 AM EST
dotloop verified

Received by: 

BHHS RW Towne Realty
(Selling Firm)


By:  dotloop verified
02/25/26 3:09 PM EST
EDOU-GLCK-KFSB-9YJM
(Date)

AtCoastal Realty
(Listing Firm)

By:  2/28/2026
(Date)

 dotloop verified
02/25/26 3:19 PM EST
SEXR-ZEIR-CFRN-LAPM
(Buyer) (Date)

 dotloop verified
02/25/26 3:13 PM EST
AKTS-DDGT-F3EA-ELDV
(Buyer) (Date)

 03/01/2026
(Seller) (Date)

(Seller) (Date)

(FOR AGENT USE ONLY)

FOR COMPLETION BY AGENT VERIFYING REMOVAL ACCEPTANCE DATE:

This Property Inspection Contingency Removal Addendum has been accepted by all parties as of 03/06/2026 ("Removal Acceptance Date").

SIGNATURE:



dotloop verified
03/06/26 10:35 AM EST
7DBU-88FD-OADY-MGSU

☐ LISTING AGENT ☒ SELLING AGENT