


Why the cameras cannot simply be set up correctly once

Both panels: the same 1844 detections, balanced set-pose dataset, four robot headings, current floor-plane projection. Scored against commanded ground truth, offline.

All four cameras are about equally accurate (64.6-68.1 mm) — but they lean opposite ways



So we measured that lean once and shipped the numbers. On both cameras it was fitted for, it made things WORSE

