▽ ¡Felicitaciones! ¡Aprobaste!

Ten measurements, two unknown parameters.

 ${\bf Calificaci\'{o}n\ recibida\ } 100\ \% \quad {\bf Para\ Aprobar\ } 80\ \%\ o\ m\'{a}s$

Ir al siguiente elemento

Lesson 1: Practice Quiz

Lesson 1: Practice Quiz		
Pu	intos totales 6	
1.	In order to apply the method of least squares, it is necessary to know the measurement noise variances.	1 / 1 punto
	O True	
	False	
	Correct! Least squares can be applied to minimize a squared error criterion, without necessarily knowing the noise characteristics of the measurements.	
2.	For the method of least squares, select any/all that apply.	1/1 punto
		1/1/20110
	 ☐ The squared error criterion and least squares method can be applied directly to nonlinear measurement models. ✓ The method was pioneered by Carl Friedrich Gauss. 	
	Correct! The least-squares method is usually credited to Carl Friedrich Gauss (1795).	
	Given a linear observation model, the parameters that minimize the squared error criterion can be found by solving the normal equations.	
	Correct! However, there is an additional criterion required for the solution to be valid. For more details, review the "Squared Error Criterion and the Method of	
	Least Squares" lecture in this module.	
3.	$Lesson \texttt{1} referred to the Jacobian matrix, \\ \mathbf{H}, which relates the parameters of the linear model to the measurements. Assume that, for a particular problem, our model the th$	1/1 punto
	has three parameters and we obtain ten measurements - what size should the Jacobian matrix be?	
	$lacksquare$ The matrix ${f H}$ should be $10 imes3$ in size.	
	$igcap$ The matrix ${f H}$ should be $3 imes 10$ in size.	
	Correcto Right! There is one row in the matrix for each measurement and one column for each parameter.	
4.	According to the weighted squared error criterion, the error term corresponding to a measurement with a noise variance of 10 units will be weighted more highly than that of a measurement with a noise variance of 1 unit.	1/1 punto
	○ True	
	False	
	Correct! A larger noise covariance means a lower weight (i.e., a less trustworthy measurement).	
5.	In which of these cases would the method of weighted least squares produce valid solutions. Select any/all that apply.	1/1 punto
		1/1 punto
	Five measurements, five unknown parameters, and two different noise variances.	
	Correcto Correct! We have an equal number of measurements and unknowns, which means the five parameters can be estimated correctly. The non-zero noise variances	
	affect the estimator accuracy, but not the validity of the solution.	
	Five measurements, six unknown parameters.	

(correcto Correct! We have more measurements than unknowns, which means the two parameters can be estimated reliably.	
Ten measurements, two unknown parameters, and two different noise variances, one of which is exactly zero.	
You are measuring the voltage drop V across an electrical component using two different multimeters; one of the meters is known to be more reliable than the other. Which method would you use to estimate the best voltage value from noisy measurements?	1/1 punto
Weighted Least Squares	
O Least Squares	
 Correcto Correct! WLS can handle the possibility of the measurements having different noise levels (variances). 	