S3AN01A

XILINX Spartan 3AN FPGA School Board

- 1.00 New Design
- 1.01 Typo Corrections and Errata

 Verified in hardware

Errata

Pins 33 and 35 are Input Only and can not be used for LED output.

Cut wires PS2_CLK1 and PS2_DATA1 near to serial R

Connect U1.12 with U1.35

Connect U1.13 with U1.33

Do not use PS2 (1)

There are missing serial resistors for LED display.

Enable LED display segments for a short time only

Identifiers B1_nn of bank 1 pins ends in '_' what is not valid identifier in VHDL.

Use different name in VHDL and UCF

MLAB				Author MIHO		
Size A3	Project Name MLAB	Schematic Name S3AN01A			Rev 1.01	
Date:	Thursday, March 17, 2011	Sheet 1	of	5		







