

IntelligenceOps Synthetic Executive Decision Memo

Evidence-to-action memo | Flight operations decision intelligence

Public demonstration using synthetic data. No employer data, real station performance, internal screenshots, or operational evidence is shown.

OTP D15 78.6%	Target Gap -6.4 pp	TAT Risk 34%	Flights Reviewed 1,240	Ground Ops Exposure 2,180 min	Action Lanes Ready 4 / 6
------------------	-----------------------	-----------------	---------------------------	----------------------------------	-----------------------------

Leadership Ask

Approve one authority-flow route, validate one handoff-control lane, watch three operational risk lanes, and monitor one stable lane. TAT flags priority only; ownership is assigned after inherited, local, and external pressure are separated.

Decision Spine

Executive signal -> review layer -> evidence signal -> TAT lens -> decision / authority route -> success check.

APPROVE NXA / 15A

Boarding closure and ramp-readiness signal

Evidence 420 min across 18 flights

TAT lens 38% timing-risk exposure

Decision: Station GHA reviews boarding closure, ramp readiness, baggage delivery, and load-control handoff before escalation.
Success: Repeat signal reduced in the next review cycle.

VALIDATE NXB / Rotation handoff

Release / hold assumption exposed

Evidence 310 min across 11 flights

TAT lens Crew duty and rotation impact visible

Decision: OCC / Hub Control validates rotation impact, connection risk, crew duty exposure, and recovery options before assigning ownership.
Success: Constraint, owner, and caveat documented before escalation.

WATCH NXC / Airport-flow constraint

Passenger-processing constraint suspected

Evidence: 260 min across 9 flights

TAT lens: Queuing or infrastructure pressure may be driving timing risk

Decision: Airport coordination route opens only after station execution is separated from external constraint.

Success: External constraint owner and recovery window confirmed.

WATCH NXD / Repeated local pattern

Station-level signal repeats after first local corrective action

Evidence: 190 min across 7 flights

TAT lens: Timing pressure persists after first execution check

Decision: Area Manager reviews repeated station-level pattern when local corrective action does not close the issue across the next review cycle.

Success: Pattern either closes or moves to area-level corrective action with named owner.

WATCH NXA / Policy-threshold watch

Authority or supplier coordination may be required

Evidence: 150 min across 6 flights

TAT lens: Timing exposure supports prioritization but does not assign ownership alone

Decision: Senior operations approval is required when the action depends on policy threshold, authority coordination, supplier escalation, or network trade-off.

Success: Approval route, trade-off, authority owner, and caveat are recorded before action.

MONITOR NXB | Stable lane below escalation threshold

Evidence: 95 min across 5 flights

TAT lens: No immediate timing-risk break after inherited and external pressure are separated

Decision: Keep in standard review. Reopen only if inherited pressure, local execution, or external constraint changes.

TAT / Accountability Guardrail

TAT is timing-risk exposure. It supports prioritization, but ownership is assigned only after inherited pressure, local execution, and external constraints are separated.

Synthetic Decision Register

Evidence Signal | TAT Lens | Decision / Authority / Action Route | Success Check

Public demonstration using synthetic data. No employer data, real station performance, internal screenshots, or operational evidence is shown.

Lane	Evidence Signal	TAT Lens	Decision / Authority / Action Route	Success Check
APPROVE NXA / 15A	Boarding closure and ramp-readiness signal 420 min across 18 flights	38% timing-risk exposure	Station GHA reviews boarding closure, ramp readiness, baggage delivery, and load-control handoff before escalation.	Repeat signal reduced in the next review cycle.
VALIDATE NXB / Rotation handoff	Release / hold assumption exposed 310 min across 11 flights	Crew duty and rotation impact visible	OCC / Hub Control validates rotation impact, connection risk, crew duty exposure, and recovery options before assigning ownership.	Constraint, owner, and caveat documented before escalation.
WATCH NXC / Airport-flow constraint	Passenger-processing constraint suspected 260 min across 9 flights	Queuing or infrastructure pressure may be driving timing risk	Airport coordination route opens only after station execution is separated from external constraint.	External constraint owner and recovery window confirmed.
WATCH NXD / Repeated local pattern	Station-level signal repeats after first local corrective action 190 min across 7 flights	Timing pressure persists after first execution check	Area Manager reviews repeated station-level pattern when local corrective action does not close the issue across the next review cycle.	Pattern either closes or moves to area-level corrective action with named owner.
WATCH NXA / Policy-threshold watch	Authority or supplier coordination may be required 150 min across 6 flights	Timing exposure supports prioritization but does not assign ownership alone	Senior operations approval is required when the action depends on policy threshold, authority coordination, supplier escalation, or network trade-off.	Approval route, trade-off, authority owner, and caveat are recorded before action.
MONITOR NXB	Stable lane below escalation threshold 95 min across 5 flights	No immediate timing-risk break after inherited and external pressure are separated	Keep in standard review. Reopen only if inherited pressure, local execution, or external constraint changes.	Signal remains stable through the next cycle.