

Inspection Report

123 west ave

CLIENT

bob

PROPERTY ADDRESS

123 west ave

INSPECTION DATE

4/15/2026

INSPECTOR

joseph

Visual Inspection — 4/15/2026

PV Modules

- Physical Damage
None observed
- Discoloration
None observed
- Delamination
None observed
- Soiling / Dirt
Light soiling/dust visible on some panel surfaces, particularly on panels in Photo 3.

SUMMARY

Solar modules are in generally good condition with minor soiling observed on some panels.

Mounting System

- Structural Damage
None observed
- Corrosion
None observed

SUMMARY

Mounting hardware and rail systems appear intact with no visible damage or corrosion across all roof sections.

Inverters

- Loose Connections
Not visible in provided photos
- Fault Codes / Error Lights
Not visible in provided photos

SUMMARY

No inverters are visible in the provided photos; inverter condition cannot be assessed.

Shading Assessment

- Tree Growth / Obstruction
None observed
- New Construction
None observed

SUMMARY

No shading obstructions from trees or structures are visible on the solar panels at the time the photos were taken.

FOLLOW-UP ITEMS REQUIRED

- Light soiling observed on some panels — panel cleaning recommended.

Electrical Analysis — 4/15/2026

Measurement	Reading / Finding
Inverter Numbers	<i>Not visible in provided photos</i>
Amperage Readings	<i>Not visible in provided photos</i>
Voltage Readings	<i>Not visible in provided photos</i>
Fuse Condition	<i>Not visible in provided photos</i>

Inverter Assessment

No inverter equipment is visible in any of the provided photos.

String-Level Assessment

Not visible in provided photos

System Specifications

Specification	Value
Module Count	<i>Not visible in provided photos</i>
Module Wattage	<i>Not visible in provided photos</i>
Module Brand	<i>Not visible in provided photos</i>
Inverter Count	<i>Not visible in provided photos</i>
Inverter Capacity	<i>Not visible in provided photos</i>
Inverter Brand	<i>Not visible in provided photos</i>
System Voltage	<i>Not visible in provided photos</i>

Inspection Photo Gallery

4 photos — all descriptions extracted from photo content only



PANELS

Overview of a residential asphalt shingle roof showing multiple solar panel arrays across different roof planes. A cross-shaped cluster of approximately 5 panels is visible on the center-left roof face, and a row of approximately 4 panels is visible on the right roof face near the ridge. An additional single panel is visible on a separate roof section to the upper left. A chimney is located between the panel groupings. Mounting rails and clamps are visible securing the panels to the roof.




PANELS

View of a rear-facing roof slope showing a row of 3 solar panels installed near the ridge line. Mounting rails and mid/end clamps are visible. Conduit or wiring runs are partially visible along the ridge area.



PANELS

Close-up view of a roof section showing an array of approximately 8 solar panels arranged in two offset rows. Mounting rails, mid-clamps, and end-clamps are visible. Light soiling is observed on some panel surfaces. Wiring/conduit runs are partially visible near the ridge.



BLUEPRINT

Handwritten blueprint diagram labeled 'Section C' showing a racking and attachment layout. Multiple rails are drawn with measurement annotations including 24in, 48in, 42in, 22in, 40in, 45in, 46in, and 36in spacings. Circled positive and negative heads are marked at various points along the rails, labeled C2, C3, C4, C5, and C6, indicating home run and jumper connection points. A notation of '6 FT' appears between attachment points on one rail.

