

The Industry print list

The Industry v1. Online at cannonsandcoastlines.com/print-list/industry-set.

3 warships with 3 fittings each (turret, smokestack, cargo)

	PART	QTY	COLOR	SUPPORTS
	Hull <i>ship-industry.stl</i>	3	Rust brown or steel blue	No
	Turret <i>industry-turret.stl</i> The second cannon slot is on top.	3	Rust brown or steel blue	No
	Smokestack <i>industry-smokestack.stl</i>	3	Rust brown or steel blue	No
	Cargo <i>cargo.stl from the base set</i>	3	Brown	No
	Movement wheel <i>movement-wheel.stl from the base set</i>	3	Any	No
	Cannon <i>cannon.stl from the base set</i>	4	Black	No
	Cannonball <i>cannonball.stl from the base set</i>	10	Something bright, like neon green or orange	No

The parts marked "from the base set" come with the free base set download. Get it at cannonsandcoastlines.com/print-list/base-set.

Printing

SETTING	VALUE
Material	PLA. PETG works for the Shadow Fleet too.
Layer height	0.16 mm or lower
Z contouring	On
Infill	10% or more

- Lay each cannon so the flex arm's layers run across the bend, and print a spare or two.
- Print masts lying flat.

Putting It Together

THE SHIP (ONCE)

1. Stretch a thin **rubber band** around the rim of the **wheel**.
2. Push the wheel into the slot under the stern. It should be snug but still spin.

CANNONS

- Plug the **cannon** into any open slot on a ship or an island.
- Drop in a **cannonball** and press the arm down until it fires.
- You can pull a cannon and move it to another slot between shots.

FITTINGS (EVERY GAME)

- **Masts, cargo** and **barrels** plug into the deck.
- **Sails** slide down over the masts.
- Each hit knocks off one fitting. How many you have is on your faction card. A bare hull sinks on the next hit.

FLAGS AND ISLANDS

- Slide a paper flag into the slot at the top of a **mast**.
- **Islands** sit straight on the table. Plug a **short mast** in to fly your flag.
- **Island toppers** go on top of anything the right height. Same cannon slots and flag holes as a ship.

What a game needs

Each player brings a fleet printed from its list, 20 coins, one or two islands with a short mast each, the faction card and some paper flags.

The table needs 2 to 6 rocks and reefs. With three or more players, put a rock at each end of every fleet's line. Add the wind dial if you play Trade Winds. A 6 ft round table or a 6 or 8 ft folding table works well.

You also need a thin rubber band for every wheel and a cloth bag for the coins.

The islands, coins and terrain come with the free base set: cannonsandcoastlines.com/print-list/base-set.