

Initial Phase Margin of 30 Final Phase Margin of 75 degrees

- Plant
- Compensator = (s+15)/(s+150)
- Phase Margin Indicator
- Combined