
main region
ST_IDLE
1
IDLE
2
SAVE_CONFIG /save_da
3
AC
IDLE / raise turn_off_red_led raise turn_off_green_led raise turn_off_ye
TEMP_INCREASING, TEMP_DECREASI
TEM


ata()
ST_ACTIVE
CTIVE
1
ellow_led
4
2
3
TEMP_INCREASI
ING [temp >= HIGH_TEMP_VALUE]
TEMP_INCREASING, TEMP_DECREASING [temp <= LOW_TEMP_VALUE]
ST_LOW_TEMP
3
MP_DECREASING [temp < LOW_TEMP_VALUE] /aise turn_on_green_led
1
2
TEMP_INCREASING [temp < LOW_TEMP_VALUE] /aise turn_on_green_led

ING, TEMP_DECREASING [temp > LOW_TEMP_VALUE && temp < HIGH_TEMP_VALUE]


1
TEMP_INCREASING [temp >= HIGH_TEMP_VALUE] / raise PRINT_WARNING_HIGH_
2
ST_HIGH_TEMP
3
TEMP_DECREASING [temp >= HIGH_TEMP_VALUE] / raise PRINT_WARNING_HIGH_TEMP , raise turn_on_red_led

TEMP_INCREASING [temp >= LOW_TEMP_VAL

TEMP_IN

_TEMP **raise** turn_on_red_led

TEMP_DECREASING [temp < HIGH_TEMP_VALUE] **raise** turn_off_red_led **raise** turn_on_yellow_led **raise** CLEAR_WARNING_HIGH_TEMP


TEMP_INCREASING [temp >= LOW_TEMP_VALUE && temp < CL_TEMP_VALUE]/raise turn_on_ye
TEMP_INCREASING
LUE] /raise turn_on_yellow_led /raise turn_off_green_led
1
ST_MID_TEMP
6
TEMP_DECREASING [temp < LOW_TEMP_VALUE]/raise turn_off_yellow_led /raise turn_on_green_led
3
NCREASING [temp >= HIGH_TEMP_VALUE]/raise turn_off_yellow_led /raise turn_on_red_led
TEMP_DECREASIN


yellow_led
G [temp >= CL_TEMP_VALUE && temp < HIGH_TEMP_VALUE && !cooler] / raise turn_on_yellow_led ; cooler = true ; raise turn_on_cl_led
2
4
TEMP_DECREASING [temp >= LOW_TEMP_VALUE && temp < CL_TEMP_VALUE] / raise turn_on_yellow_led
5
TEMP_DECREASING [temp >= LOW_TEMP_VALUE && temp < CL_TEMP_VALUE && cooler] / raise turn_on_yellow_led ; cooler= false ; raise turn_off_cl_led
7
ING [temp >= CL_TEMP_VALUE && temp < HIGH_TEMP_VALUE] / raise turn_on_yellow_led