





Degradation evolution




True negative ($i=32$)

$D_i = 3.57\text{e-}01$
 $\delta_i = 0.00\text{e+}00$
 $\Delta f_i^- = 0.00\text{e+}00$




True positive ($i=49$)

$D_i = 7.37\text{e-}01$
 $\delta_i = 4.74\text{e-}01$
 $\Delta f_i^- = 2.42\text{e-}01$



False negative ($i=289$)

$D_i = 5.19\text{e-}01$
 $\delta_i = 3.82\text{e-}02$
 $\Delta f_i^- = 0.00\text{e+}00$



False positive ($i=302$)

$D_i = 5.00\text{e-}01$
 $\delta_i = 0.00\text{e+}00$
 $\Delta f_i^- = 3.96\text{e-}02$