





Degradation evolution




True negative ($i=30$)

$D_i = 4.37\text{e-}01$
 $\delta_i = 0.00\text{e+}00$
 $\Delta f_i^- = 0.00\text{e+}00$




True positive ($i=37$)

$D_i = 9.18\text{e-}01$
 $\delta_i = 8.37\text{e-}01$
 $\Delta f_i^- = 1.00\text{e+}00$



False negative ($i=42$)

$D_i = 5.32\text{e-}01$
 $\delta_i = 6.34\text{e-}02$
 $\Delta f_i^- = 0.00\text{e+}00$



False positive ($i=113$)

$D_i = 4.95\text{e-}01$
 $\delta_i = 0.00\text{e+}00$
 $\Delta f_i^- = 9.30\text{e-}02$