APPENDIX C
HISTORIC RESOURCES ANALYSIS AND SUPPORTING INFORMATION

This page intentionally left blank

SUB-APPENDIX C.1
3400 LAGUNA STREET HISTORIC RESOURCE EVALUATION

This page intentionally left blank

PAGE&TURNBULL

3400 LAGUNA STREET
HISTORIC RESOURCE EVALUATION, PART 1

SAN FRANCISCO, CA
[21286]

PREPARED FOR THE SAN FRANCISCO PLANNING DEPARTMENT
February 16, 2023

REVISED



TABLE OF CONTENTS

I. INTRODUCTION 1
Methodology 2
Summary of Findings 2
II. EXISTING HISTORIC STATUS 3
III. BUILDING AND PROPERTY DESCRIPTION 5
Main Building 6
1957 Addition 20
1963 Addition 25
Cottage 29
Grounds 31
Surrounding Neighborhood 32
IV. HISTORIC CONTEXT 34
Early San Francisco History 34
The Marina District 35
Social Welfare and Old Age Homes 40
V. SITE HISTORY 44
Site Development 44
Construction Chronology 50
Ownership and Occupant History 52
Select Owner and Occupant Biographies 52
Biographies of Architects and Designers 56
Julia Morgan 56
Warren C. Perry 59
Gardner A. Dailey 61
VI. EVALUATION 64
California Register of Historical Resources 64
Period of Significance 68
Integrity 68
Character-Defining Features 71
VII. CONCLUSION 73
VIII. REFERENCES 74
IX. APPENDICES 76
Building Permit Applications 76

I. INTRODUCTION

This Historic Resource Evaluation (HRE) has been prepared at the request of Heritage on the Marina for proposed alterations to the structure at 3400 Laguna Street (APN 0417/003) in San Francisco's Marina District. It revises and updates the HRE published on August 28, 2015 by Page & Turnbull. This revised HRE includes an expanded description of the stone cottage on the site, and revises the previous evaluation and character-defining features to include the stone cottage as a contributing element to the significance of the property. Other updates include text revisions replacing the phrase "master architect" with "architect of merit," a revised construction date of 1928-1929 for the stone cottage (previously thought to be 1925) that was uncovered through additional research, updated references, and the addition of building permits issued since 2015.




Figure 1: San Francisco Assessor's Map, 3400 Laguna Street marked in red; north is up.
Source: San Francisco Property Information Map, edited by author

The 3400 Laguna Street parcel consists of over half of a city block and is located on a generally square and level lot bounded by Bay Street on the north, Laguna Street to the west, and Francisco Street to the south **(Figure 1)**. The Jacobethan Revival-style main building was designed by architect Julia Morgan for the Ladies' Protection and Relief Society and was constructed in 1925. The main building has several large additions constructed in the second half of the twentieth century, including a L-shaped 1957 addition designed by Warren C. Perry and a 1963 addition designed by Gardner A. Dailey. A stone cottage, completed in 1929, is located at the northeast corner of the lot, adjacent to Bay Street. The 1925 main building and its additions remain in use as a private retirement facility in a RM-1 (residential-mixed use low density) zoning district. The main building is

set approximately ten degrees counterclockwise off cardinal direction but will be described using cardinal directions in this report.

3400 Laguna Street is not listed in the National Register of Historic Places (National Register), California Register of Historical Resources (California Register), or local San Francisco historical register. The subject property is not within the boundaries of any recorded historic district.

METHODOLOGY

This report follows the outline provided by the San Francisco Planning Department for Historic Resource Evaluation reports, and provides a building description, historic context, and an examination of the current historic status for the subject building. The report also includes an evaluation of the property's eligibility for listing in the California Register.

Page & Turnbull prepared this report using research collected at various local repositories, including the City and County of San Francisco Office of the Assessor-Recorder, the San Francisco Department of Building Inspection, the San Francisco Planning Department, and the San Francisco Public Library's History Center, as well as various online sources including Ancestry.com, Newspapers.com, and the California Digital Newspaper Collection. Key primary sources consulted and cited in this report include Sanborn Map Company fire insurance company maps, City of San Francisco Building Permit applications, San Francisco city directories, San Francisco Office of the Assessor-Recorder records, and historical newspapers. All photographs in this report were taken by Page & Turnbull in June 2015 unless otherwise noted.

SUMMARY OF FINDINGS

The property at 3400 Laguna Street has been found eligible to the California Register of Historical Places, thus qualifying as a historic resource for the purposes of review under the California Environmental Quality Act (CEQA). 3400 Laguna Street is eligible for the California Register under Criterion 1 and Criterion 3. Under Criterion 1, the property is significant for its association with the Ladies' Protection and Relief Society, one of the longest running eldercare service organizations in San Francisco. The property is additionally eligible under Criterion 3 as an excellent example of institutional architecture as designed by prominent California architect Julia Morgan, and expanded through early alterations prior to 1957 that were compatible with the English-inspired design of the property. Contributing elements of the property that support its significance include the main building, the stone cottage, and the landscape features of the front lawn. The period of significance for both criteria is 1925 to 1957, beginning with the development of the property and construction of the main building, and ending with the merger between the Ladies' Protection and Relief Society merged with another eldercare institution..

II. EXISTING HISTORIC STATUS

The following section examines the national, state, and local historic status currently assigned to the property at 3400 Laguna Street.

National Register of Historic Places

The National Register of Historic Places (National Register) is the nation's most comprehensive inventory of historic resources. The National Register is administered by the National Park Service and includes buildings, structures, sites, objects, and districts that possess historic, architectural, engineering, archaeological, or cultural significance at the national, state, or local level.

3400 Laguna Street is not currently listed in the National Register of Historic Places.

California Register of Historical Resources

The California Register of Historical Resources (California Register) is an inventory of significant architectural, archaeological, and historical resources in the State of California. Resources can be listed in the California Register through a number of methods. State Historical Landmarks and National Register-listed properties are automatically listed in the California Register. Properties can also be nominated to the California Register by local governments, private organizations, or citizens. The evaluative criteria used by the California Register for determining eligibility are closely based on those developed by the National Park Service for the National Register of Historic Places.

3400 Laguna Street is not currently listed in the California Register of Historical Resources.

California Historical Resource Status Codes

Properties listed or under review by the State of California Office of Historic Preservation are listed within the Built Environment Resource Directory (BERD) and are assigned a California Historical Resource Status Code (Status Code) of "1" to "7" to establish their historical significance in relation to the National Register of Historic Places (National Register) or California Register of Historical Resources (California Register).[1] Properties with a Status Code of "1" or "2" are either eligible for listing in the California Register or the National Register, or are already listed in one or both of the registers. Properties assigned Status Codes of "3" or "4" appear to be eligible for listing in either register, but normally require more research to support this rating. Properties assigned a Status Code of "5" have typically been determined to be locally significant or to have contextual

[1] California State Office of Historic Preservation, Built Environment Resource Directory (BERD), San Francisco County, updated September 2022.

importance. Properties with a Status Code of "6" are not eligible for listing in either register. Finally, a Status Code of "7" means that the resource has not been evaluated or needs reevaluation.

As of the last update, in September 2022, 3400 Laguna Street was not listed in the California Historic Resources Information System (CHRIS) database with any status code.

San Francisco City Landmarks

San Francisco City Landmarks are buildings, properties, structures, sites, districts, and objects of "special character or special historical, architectural or aesthetic interest or value and are an important part of the City's historical and architectural heritage."[2] Adopted in 1967 as Article 10 of the City Planning Code, the San Francisco City Landmark program protects listed buildings from inappropriate alterations and demolitions through review by the San Francisco Landmarks Preservation Advisory Board. These properties are important to the city's history, provide significant and unique examples of the past that are irreplaceable, and help to enhance the educational and cultural dimension of the city.

3400 Laguna Street is not currently designated as a San Francisco City Landmark or Structure of Merit. Furthermore, 3400 Laguna Street does not fall within the boundaries of any locally designated historic districts or conservation districts, and does not appear to have been included in any local historic resource surveys.

1976 Department of City Planning Architectural Quality Survey

The 1976 Department of City Planning Architectural Quality Survey (1976 DCP Survey) is what is referred to in preservation parlance as a "reconnaissance" or "windshield" survey. The survey looked at the entire City and County of San Francisco to identify and rate architecturally significant buildings and structures on a scale of "-2" (detrimental) to "+5" (extraordinary). No research was performed and the potential historical significance of a resource was not considered when a rating was assigned. Buildings rated "3" or higher in the survey represent approximately the top two percent of San Francisco's building stock in terms of architectural significance. However, it should be noted here that the 1976 DCP Survey has come under increasing scrutiny over the past decade due to the fact that it has not been updated in over twenty-five years. As a result, the 1976 DCP Survey has not been officially recognized by the San Francisco Planning Department as a valid local register of historic resources for the purposes of the California Environmental Quality Act (CEQA).

3400 Laguna Street is not listed in the 1976 DCP Survey.

[2] San Francisco Planning Department, *Preservation Bulletin No. 9 – Landmarks*. (San Francisco, CA: January 2003).

III. BUILDING AND PROPERTY DESCRIPTION

The property contains a building complex composed of three connected buildings, a freestanding stone cottage, and three landscape areas **(Figure 2)**. The original 1925 Julia Morgan-designed main building is labeled "1" in Figure 2. A large, L-shaped addition designed by Warren C. Perry in 1957 is labeled "2," and the 1963 addition designed by Gardner A. Dailey is labeled "3." Two small additions to the Dailey addition were designed by Spencer & Associates and completed in 1986 (not labeled in Figure 2). The freestanding stone cottage is labeled "4." The three landscape areas are the front lawn (labeled "5"), the center courtyard (labeled "6"), and the rear courtyard (labeled "7"). The property is surrounded at the north and west by open recreation fields, and to the east and south by multi-unit residential buildings.



Figure 2: Site map of the 3400 Laguna Street property showing buildings and landscape features labeled. Source: Google Earth, 2023. Edited by Page & Turnbull.

The property description that follows first describes the main building and its publicly accessible interiors, then the 1957 and 1963 additions, followed by the stone cottage, and then descriptions of the grounds and the surrounding neighborhood.

MAIN BUILDING

The main building has a U-shaped footprint, with a longer north-south portion and two wings that extend from the north and south ends of the east façade. The building is two-and-one-half stories over a partially exposed basement level, and has an attic-story penthouse at the east facade. The building is clad in brick with a 5-1 common bond, and has a hipped roof covered in slate shingles **(Figure 3)**.



Figure 3: Main building primary (west) façade, viewed facing east.



Figure 4: Main building, typical window type, in grouping of five.



Figure 5: Main building, typical dormer type.

The building's typical window type consists of two metal-frame multi-light fixed, casement or awning windows, positioned one over the other, set within a terra cotta tile surround and dividing rail, often

topped with a segmental arch with inset terra cotta floral motif. These windows are generally paired, but some are single or in multiples **(Figure 4)**. These windows are generally six-over-eight light at the first story and four-over-six light at the second story. The typical dormer type is capped with a hipped roof covered in slate shingles, containing two eight-lite metal-frame fixed or casement windows **(Figure 5)**.

PRIMARY (WEST) FAÇADE

The primary (west) façade of the main building is symmetrically arranged into seven bays and faces west onto the landscaped front yard and Laguna Street beyond. The raised basement includes six pairs of four-light metal frame fixed windows with metal screens, evenly spaced along the façade and largely obscured by foliage.

At the first story, the primary entrance is located at center, accessed by a double curved brick staircase with curved steps, and a brick landing with iron railings **(Figure 6)**. The primary entrance is a double arched opening, with a terra cotta tile surround with three engaged Corinthian terra cotta columns. The openings historically were open and led to a recessed vestibule; they are currently infilled with contemporary anodized aluminum framing; the left has a large pane of reflective glass with a three-lite transom and the right has a fully glazed door with sidelights and the same transom. Within the now-enclosed vestibule, the building's original entrance includes two paired eight-lite wood paneled doors under paired four-light wood casement windows, all set within a terra cotta surround **(Figure 7)**.



Figure 6: Primary entrance, west facade, viewed facing east.



Figure 7: Primary original entrance, viewed from within the building, viewed facing northwest.



Figure 8: Center bay of primary facade, second and third stories, viewed facing southeast.



Figure 9: Underside of center bay second story canted bay, viewed facing east.

At the second story, the center bay includes a projecting, canted oriel bay with three typical windows at center and one at each side face. The canted bay has a belt course along the window sills, and two rectangular decorative terra cotta panels centered above and below the center window **(Figure 8)**. On the underside of the oriel bay is a terra cotta entablature, featuring shield and ribbon crests

alternated with scrolled brackets **(Figure 9)**. At the third story, the center bay includes a large brick-clad pediment dormer with five eight-light metal-frame fixed or casement windows **(refer to Figure 8)**. This dormer terminates in a gabled parapet with flared ends and a shaped terra cotta tile coping, with a floral finial at the gable peak.

The first, third, fifth and seventh bays (numbering left to right) include paired typical windows at the first and second stories. The second and sixth bays have a canted bay at the first story, with three typical windows at the front face and two typical windows at the side faces, with a belt course along the lower sills and a terra cotta cornice panel and molded cornice. At the second story these bays have two pairs of typical windows, each pair separated by a relief tile panel with a floral motif. These bays are flanked by downspouts topped by sculpted basket rain catchers.

The second story terminates with a continuous terra cotta belt course above the second story windows and a terra cotta frieze with floral buttons, above which a shaped cornice conceals the gutter. At the roof are six evenly spaced typical dormers, flanking the central parapet dormer. Two brick chimneys near the roof peak are capped by terra cotta tile.

NORTH FAÇADE

The north façade of the main building is organized into five bays and faces onto a paved surface parking area and Bay Street beyond **(Figure 10)**. The east end of the façade, containing one bay, projects forward and is surrounded at the first story by the roof covering a contemporary service entrance. The façade abuts the 1957 addition at the far left (east). The raised basement includes two window openings, two metal service doors, and an open-air metal elevator mechanism **(Figure 11)**.



Figure 10: North façade of the main building, viewed facing south.




Figure 11: Exposed basement showing the elevator mechanism, viewed facing northwest.

The first bay (counting left to right) includes paired typical windows at the first and second story, and a downspout topped by a sculpted basket rain catcher at far left. The second and third bays include paired variations on the typical window type at the first story (lacking the terra cotta meeting rail)

and paired typical windows at the second story. There is a small anodized aluminum double hung window at the second story, right of the third bay. The fourth bay includes a partially glazed metal door with a transom window at the first story, and paired typical windows at the second story. The first story door has new mortar around the frame, and is accessed via a concrete stair and a concrete loading dock that continues to the right and surrounds the north and east sides of the fifth bay. The loading dock is sheltered by a corrugated metal roof supported by simple posts. The two-story projection has paired typical windows at all three sides of the first story, three typical windows at the east and west sides of the second story, and five typical windows at the north side of the second story **(Figure 12)**. The sixth bay includes paired typical windows at the first and second story.



Figure 12: West portion of north facade, viewed facing southeast.

The north façade is capped by the same belt course above the second story windows, and terra cotta frieze with floral buttons, above which a shaped cornice conceals the gutter. At the roof are four typical dormers, three above the second, third, and fourth bays, and one at the projecting fifth bay. A brick chimney capped by terra cotta tile is located at the roof.

EAST (REAR) FAÇADE

The east façade of the main building faces onto a landscaped courtyard and the later additions to the building beyond. The façade expresses the "U" of the building's footprint; the south (left) and north (right) wings project to the east from the central section of the building. The north wing intersects with and is covered by the 1957 addition. The east face of the south wing is configured into three bays **(Figure 13)**. The first and third bays have paired typical windows at the first and second story. The second bay, at center, is offset and expresses an interior stairwell: it consists of a half-glazed wood-paneled door surrounded by a brick Tudor arch at the first story, and typical paired windows located between the first and second stories. The façade terminates in the same belt course, cornice and gutter as the rest of the building, above which there is a single centered atypical dormer, containing three rather than two typical windows.



Figure 13: Left (south) projection of the east façade, viewed facing west

The north face of the south wing is organized in three bays **(Figure 14 and Figure 15)**. The first and third bays have typical windows at first and second stories, with an additional slim eight-lite metal frame casement window at the far right of the first story of the third bay. The center bay has no window openings. The façade terminates in the same belt course, cornice and gutter as the rest of

the building, above which are typical dormers at the second and third bays, with an additional atypical dormer at far right: this dormer is recessed and not visible from ground level, has a metal framed 12-lite window and a shed roof clad in composite shingles.




Figure 14: Left (east) portion of the north face of the south projection, viewed facing south.



Figure 15: Right (west) portion of the north face of the south projection, viewed facing south.

The central, recessed portion of the east façade is organized into five bays, with the fifth bay (at far right) covered at the first story by the end of the 1957 addition **(Figure 16)**. The first and fourth bays (counting left to right) include paired four-light metal-frame windows at the exposed basement, and typical windows at the first and second story. Fenestration at the second bay is offset and expresses an interior stairwell. A wood-paneled door with an eight-lite casement window, sandstone surround, broken top rail, topped with a segmental arch with inset terra cotta floral motif is located at the first story, accessed via a curved brick stair with iron rails. There is a typical paired window at the second story. The third bay includes a two-story projecting canted bay, with paired four-lite metal-frame windows at the exposed basement, and three typical windows at center and two typical windows at each side face of the first and second stories. The fifth bay, at far right, is covered by the 1957 addition and includes a typical window at the second story. The façade includes four downspouts topped by sculpted basket rain catchers, two at right and two at left.



Figure 16: East (central) portion of east façade, viewed facing northwest.

The façade terminates with the same belt course, cornice and gutter as the rest of the building, above which are several atypical dormers and a fourth-story penthouse **(Figure 17)**. Atypical dormers include a shed-roof dormer clad in composite shingles with a metal framed 12-lite window at left, aligned with the first bay; a hipped-roof continuous dormer clad in slate shingles with three groups of three eight-light metal frame windows, which spans the width of the three center bays and the penthouse above it; and a small, recessed shed-roof dormer at far right with an aluminum sash sliding window and a skylight. At the central fourth-story penthouse, two slate-clad towers with flat roofs flank a continuous band of metal frame eight-light casement windows, underneath a shed roof. Each tower includes a large, centered flower medallion and terminates with a molded cornice. A metal fire escape is located right of center, leading down to the roof of the canted bay.



Figure 17: Detail of dormers and fourth-story penthouse, viewed facing west.

The south face of the north wing abuts the 1957 addition, which extends at the first story to reach the central portion of the east façade of the main building, thereby covering the first story of the north wing **(Figure 18)**. (The 1957 addition is described in a subsequent section of this report.) The second story includes paired typical windows at left and center, and inset sliding glass doors at right, which provide access to an open-air terrace paved with ceramic tile and shaded by a contemporary canvas awning. The façade terminates with the same belt course, cornice, and gutter as the rest of the building, above which is a typical dormer right of center and an atypical dormer including an aluminum vent instead of windows at left: this dormer also has a flat-roof addition at left. Although not visible from ground level, a typical dormer is located at the east-facing portion of the projection roof, above the 1957 addition.



Figure 18: South face of north projection, viewed facing northwest.

SOUTH FAÇADE

The south façade of the main building is organized into six bays and faces directly onto a paved area and the 1963 addition beyond. Similar to the north façade, the south façade is organized into six bays. The first bay, counting from left to right, includes paired typical windows at the first and second story **(Figure 19)**. The second bay is a large two-story projecting wing, with triple typical windows at the first and second stories of the west face, five typical windows at the first and second stories of the south face, and paired 10-lite wood doors under four-light transoms at the first story of the east face, with triple typical windows at the second story **(Figure 20)**. The entry doors are sheltered by a non-historic canvas awning and accessed via a concrete stair and concrete landing with iron railing. There is a typical downspout at the left of this east face of this wing.



Figure 19: South façade, viewed facing northeast.



Figure 20: South façade, viewed facing northwest.

The third and fourth bays at the south façade include paired typical windows at the first and second stories, but the glass at the first story windows is leaded stained glass, expressing an interior chapel **(Figure 21)**. Between the second story windows at the third and fourth bays there is a tall narrow blind niche. The fifth bay includes no fenestration but has decorative brick treatments, square at the first story and diamond at the second story. The sixth bay includes paired typical windows at the first and second stories. The façade includes a raised water table at the left and a typical downspout at the far right. The façade terminates with the same belt course, cornice, and gutter as the rest of the building, above which are typical dormers at the second, third, fourth and fifth bays.



Figure 21: South façade, viewed facing north.

PUBLICLY ACCESSIBLE INTERIOR SPACES OF THE MAIN BUILDING

3400 Laguna Street is a private retirement facility, and most spaces are accessible only to residents and staff. Publicly accessible interior spaces are located close to the primary entrance at the first story of the 1925 main building. Finishes are largely original and include glazed ceramic tile floors, smooth stucco walls, plastered beam or wood coffered ceilings, dropped-arch openings, wood trims and built-in shelving in the library, and carved stone fireplace surrounds and mantles with floral motifs **(Figure 22 to Figure 24)**. Bannisters at stairwells to upper floors include carved wood supports, and doors to private wings at the first story are multi-lite wood.



Figure 22: Lobby and reception area, viewed facing south.



Figure 23: Sitting room, viewed facing northeast.



Figure 24: Library and reading room, viewed facing south.

1957 ADDITION

The 1957 addition has an L-shaped footprint; the addition's primary four-story volume runs north-south to the east of the main building, with a shorter two-story wing running east-west to connect to the wing that projects east from the north end of the main building's east façade. The two portions of the 1957 addition are described separately below.

PRIMARY VOLUME

The primary volume of the 1957 addition is four stories over a partially raised basement. This portion of the building has a rectangular footprint with projecting rectangular stair towers at the north and south facades. This portion of the building is clad in board-formed concrete, capped with a flat roof, and intersects with the 1963 addition at its southwest corner. All windows at this portion of the building are anodized aluminum unless described otherwise.



Figure 25: Primary volume of the 1957 addition, north façade, viewed facing southeast.

The north façade faces onto a paved areaway, the stone cottage, and Bay Street beyond, and is organized into three bays **(Figure 25)**. The central bay contains a projecting stair tower. The basement level is fully exposed at this façade by a paved area. At the basement, the first bay

(counting from left to right) includes a double hung window with frosted glass, a vented opening, and a two-part fixed and casement window; the second (central) bay includes a half-glazed metal door; and the third bay includes a two-part fixed and casement window. At the first story, the first and third bays include fixed and casement windows under transoms, while the second bay includes a half-glazed metal entry door. At the second through fourth stories, all bays include two-part fixed and casement or sliding windows. The second bay windows are offset, expressing the interior stairwell, and the central-bay tower rises above the roofline, allowing roof access at its south side. The north façade terminates with a concrete coping.

The east façade faces onto the rear courtyard at center and adjacent residential buildings at the north and south, and is organized into fifteen bays **(Figure 26 and Figure 27)**. Fenestration includes small double hung windows, large two-part fixed and casement windows, and two-part fixed and casement windows under transom windows, which are generally evenly distributed along all bays, except the first and fifteenth bays (counting from left to right), which include no fenestration. At the tenth bay, a first-story fully glazed aluminum door with awning transom provides access to the rear courtyard. Directly left of the door are two large fixed windows under transoms. The east façade terminates with a concrete coping.

The south façade intersects with the 1963 addition and faces onto a paved driveway and Francisco Street beyond. The façade is organized into three bays, with a projection constituting the first and second bays (counting left to right) **(Figure 28)**. At the first story, the first and second bays intersect with and are covered by the 1963 addition, and the third bay includes a large six-light metal sash window. At the upper stories, the first bay has no fenestration; the second bay includes punched balconies with openings (doors and windows, largely not visible from the street) along the south and east facades, and the third bay includes large two-part fixed and casement windows. The façade terminates in concrete coping.




Figure 26: East façade, facing southwest.



Figure 27: East façade, viewed facing northwest



Figure 28: South façade, viewed facing north.

The west façade of the 1957 addition faces onto the central courtyard and the main building beyond **(Figure 29)**. The façade intersects with both the east-west wing of the 1957 addition at left (north), and the 1963 addition at right (south). The façade is organized into 15 bays, and window types include two-part fixed and casement windows (some with transoms), small double hung windows, and three-part fixed and sliding windows. At the first bay (counting left to right), the basement is fully exposed due to an areaway, and includes a two-part fixed and casement window and a small double hung window. The intersecting northwest wing covers second, third and fourth bays at the

first and second bays. The 1963 addition intersects at the first story of the twelfth through fifteenth bays. The remainder of the façade includes evenly spaced windows. At the seventh and tenth bays, above the first story windows are raised rectangular embellishments, each with a brick diamond detail, mirroring the embellishment at the south façade of the northwest wing (refer to **Figure 32**). The façade terminates with a concrete coping, above which is an elevator penthouse at the roof aligned with the fourth bay.



Figure 29: West façade, viewed facing east.

NORTHWEST WING

The northwest wing of the 1957 addition is two stories over a partially raised basement. This portion of the building has a rectangular footprint, is clad largely in concrete with some brick-clad areas, and has a flat roof. The west end of this wing intersects with the main building, and the east end intersects with the west façade of the 1957 addition's primary volume, and therefore the wing includes only north and south facades.

The north façade is clad in concrete and faces onto a paved parking area and Bay Street beyond **(Figure 30)**. The basement at this façade is exposed via an areaway and includes four evenly spaced sets of three-light anodized aluminum siding windows covered with metal fencing, and a set of double metal doors with vents and a half-glazed metal door at far left, fully below grade and accessed via a straight concrete stair. The first story includes five evenly spaced sets of four awning-over-casement anodized aluminum clad wood windows, set within a recessed plane **(Figure 31)**. The second story is cantilevered over the first story approximately three feet and includes two pairs of anodized-aluminum frame sliding windows, alternated with two pairs of small anodized aluminum

double hung windows, with a tripartite anodized aluminum fixed and sliding window at far left. The north façade terminates with a slim concrete coping.



Figure 30: 1957 Addition, east-west wing, north façade.



Figure 31: North façade, window detail.

The south façade, facing onto the central courtyard and the 1963 addition beyond, is clad in brick at the exposed basement and first story, and in concrete at the second story **(Figure 32)**. The exposed basement and first story of this façade extend west to the center portion of the main building, covering the first floor of the north wing; the second story extends only to the terminus of the north wing. The exposed basement includes eleven evenly spaced anodized aluminum sliding windows, each with a tilted brick sill and a tinted concrete lintel. At the first story is a continuous band of 13 tripartite anodized aluminum-clad wood awning-over-casement window groups, framed in a slightly

recessed wood colonnade and separated by slender Corinthian columns **(Figure 33)**. At far right, a fully glazed metal door is set within the arcade, framed by sidelights and a transom and accessed via a straight concrete ramp with metal pipe rails. Above the arcade is a parapet featuring five evenly spaced decorative brick diamond medallions. The second story is recessed approximately six feet from the first story and is clad in board-formed concrete. Fenestration includes evenly spaced small anodized aluminum double hung windows and larger two pane and tripartite sliding windows. This façade terminates in concrete coping.



Figure 32: South facade showing courtyard, viewed facing northwest



Figure 33: South façade second-story window detail, viewed facing north

1963 ADDITION

The 1963 addition is oriented parallel to the south edge of the lot and has a generally rectangular footprint, set on an east-west axis. The building is one story, clad in textured concrete and capped largely with a flat roof, although two sections of the building have pitched roofs. The 1963 addition intersects with the 1957 addition at its northeast corner. The typical window type consists of an anodized aluminum two part fixed and casement under transom, with slightly inset surrounds.

The east façade faces onto a concrete ramp and concrete drive, and a multi-unit residential building beyond. At center is a fully glazed metal door with a large fixed steel sidelight, sheltered by a canvas awning and accessed via a concrete ramp with metal rail **(Figure 34)**. At right is a four-lite steel-frame window. Both the door and window are set in recessed portions of the façade that are clad in ceramic tile. This façade terminates with a band of slightly recessed concrete, and a projecting roof with paneled concrete eaves.



Figure 34: East facade of the 1963 addition, viewed facing northwest.



Figure 35: South façade, viewed facing west.

The south façade faces on to a very narrow yard with a thick hedge, and Francisco Street beyond. The façade includes a water table marked by a recessed band in the façade, and is organized into five bays. The first four bays (counting left to right) each include two typical windows, and the fifth bay includes a projecting rectangular panel with one typical window set within it, topped by a projecting band **(Figure 35)**. The façade terminates in a band of recessed concrete, and a projecting roof with paneled concrete eaves.

The west facade faces onto an enclosed yard and Laguna Street beyond, and is organized into three bays. The first and third bays (counting left to right) have the typical water table, recessed cornice, and eave treatment as the other portion of the building, and no fenestration **(Figure 36)**. The second bay is a large brick clad projection capped with a slate-shingled front gable roof. This projection is part of alterations that were designed by Spencer & Associates and completed in 1986 **(Figure 37)**. The projection includes a canted bay window at its west side, with a fixed six-lite anodized aluminum frame window at its front face and fixed four-lite anodized aluminum frame windows at the side faces. The canted bay is clad in ceramic tile, as is the cornice at all three sides of the projection. The west wall of the projection extends beyond the perimeter of the rest of the projection, and the façade here terminates with a front gable parapet. The projection includes an entrance (not visible from the street) at its south side, set within a deep recess and accessed via an L-plan wood ramp with wood rails.



Figure 36: West façade, viewed facing southeast.



Figure 37: West façade, viewed facing northeast.

The north façade of the 1963 addition faces onto a concrete ramp and the main building and the central courtyard beyond. The façade is organized into six bays. The first three bays (counting left to right) are covered by a large projection with a rectangular footprint that intersects with the 1957 addition at the east. This projection is part of the 1986 Spencer & Associates alterations and has a similar treatment as the projection at the west façade, with brick cladding and a hipped roof with an east-west roofline and slate shingle cladding **(Figure 38)**. This projection includes paired fully glazed anodized aluminum leaf doors in the first and third bays, surrounded by glazed ceramic tile, and a three-sided glass bay with a pyramidal glass roof at center, below a gabled parapet. The west-facing portion of this projection includes paired fully glazed anodized aluminum leaf doors at left and right, and a projecting chimney stack at center **(Figure 39)**. The remaining three bays at the north façade

include typical windows, and the façade terminates with a band of recessed concrete, and a projecting roof with paneled concrete eaves **(Figure 40)**.



Figure 38: North façade, projection and courtyard, viewed facing southeast.



Figure 39: West façade of projection at the north façade, with 1957 addition visible beyond, viewed facing east.



Figure 40: North façade, viewed facing southeast.

COTTAGE

A one-story stone cottage is located at the northeast corner of the property, enclosed within a wood fence and gate. It is a one-story residence with an 'L' plan; its exterior walls are constructed of coursed, roughly dressed ashlar stone and appear to have been repointed with Portland cement. The building's steeply pitched hipped roof is covered in asbestos shingles and features two copper vents, one on the east slope and one on the south slope. The exterior walls terminate in copper gutters and broad wood plates. A tapering, stucco-clad chimney adjoins the north façade and rises approximately five feet above the eave.

The primary façade faces south **(Figure 41)**. The right (east) portion of the façade is the building's ell, projecting forward approximately six feet, and contains two wood-frame paired casements. The left (west) portion of the façade features a centered four-lite wood Dutch door, flanked by paired wood-frame casement windows. The door is accessed by a walkway of concrete pavers.



Figure 41: Primary (south) façade, view facing north. Photograph taken in March 2022.

The west façade features a projecting, flat-roofed glazed boxed bay with stucco-clad base **(Figure 42)**. The wood-framed windows are arranged with 24 lites on the west face and eight lites on each side face. The boxed bay terminates in a simple molded wood cornice with metal coping.



Figure 42: Oblique view of west and south façades, viewed facing northeast. Photograph taken in March 2022.

The north façade features the large stucco clad chimney, located west of center. A vinyl-sash casement window is located between the chimney and the west end of the façade **(Figure 43)**. Between the chimney and the window near the eave is an area that appears to have been infilled with non-original stones. The only feature at the east façade is a wood-frame casement window with an exposed wood lintel near the north end of the façade **(Figure 44)**.



Figure 43: West half of north façade, viewed facing southeast. Photograph taken in March 2022.



Figure 44: East façade, viewed facing northwest. Photograph taken in March 2022.

GROUNDS

The grounds of the property can be separated into three discrete landscaped areas: a front yard that faces on to Laguna Street, extending between Francisco Street and Bay Street; a central courtyard that is surrounded by the main building and its additions; and a rear courtyard that is located behind (east of) the 1957 addition's primary volume and faces adjacent multi-family residential buildings. These landscaped areas are labeled 5, 6, and 7, respectively, in **Figure 2**. All of these areas are formally landscaped. A non-historic paved surface parking lot is located north of the main building, filling the area between Bay Street and the north façades of the 1925 main building and the northwest wing of the 1957 addition.

The front yard consists of curvilinear paths, shaped shrubs, hedges, lawns, and small trees, with larger trees at the far north edge of the property along Bay Street **(Figure 45).** The yard is symmetrically arranged around the primary entrance of the main building; concrete paved paths lead from the bottom of the front entrance steps to two gates at the western edge of the property. A small, enclosed garden is located at the south portion of the front yard and is associated with the 1962 addition. A low, mortared brick base that is topped by an iron fence encircles the front yard. This fence extends along the north and south perimeter of the property as well; the north and south portions of the fence also include a dense hedge.



Figure 45: Front yard, viewed facing north.

The central courtyard includes a large paved brick area, concrete circulation paths (including short sections of stairs), and areas of grass lawn. Two concrete cross-shaped fountains with concave corners are located on axis with the two-story bay window at the east façade of the main building

(Figure 46). Around the paved courtyard are pruned shrubs, small and medium-size mature trees, and various species of flowers. This courtyard extends south to provide access, via paved circulation paths, to the 1963 addition and the doors at the south wing of the main building.



Figure 46: Central courtyard, viewed facing west.



Figure 47: Rear courtyard, viewed facing northeast.

The rear courtyard is located to the east of the 1957 addition and is accessed from the adjacent building by a concrete ramp and set of stairs. An at-grade concrete path leads along the rear façade of the 1956 addition and provides access to the courtyard from the north and south sides of the building. The courtyard includes bushes, a wooden trellis with vines and hyacinths planted along many of the tinted curvilinear concrete walkways pathways, and mature trees **(Figure 47)**.

SURROUNDING NEIGHBORHOOD

3400 Laguna Street is located in a mixed residential and commercial neighborhood. Structures are mainly multi-family residences, constructed largely in the 1920s with some more contemporary infill construction. Some buildings east and south of the subject property include first-story commercial use. The Moscone Recreation Center is directly west of the property across Laguna Street. To the northeast is Fort Mason Park, established in 1972. The surrounding residential blocks do not have

any setbacks and are built abutting their neighbors, with private yards in the center of each block **(Figure 48 to Figure 50)**.



Figure 48: Bay Street, east of subject property, viewed facing southeast.



Figure 49: Ft. Mason Park, north across Bay Street from the subject property, viewed facing northeast.



Figure 50: 1500-1550 Bay Street, contemporary construction northwest of the subject property, viewed facing northwest on Bay Street looking toward intersection with Laguna Street.

IV. HISTORIC CONTEXT

EARLY SAN FRANCISCO HISTORY

Native American communities and their ancestors inhabited the region that would become the San Francisco Bay Area for centuries preceding the arrival of Europeans. European settlement of what is now San Francisco began in 1776 with the simultaneous establishment of the Presidio of San Francisco by representatives of the Spanish Viceroy, and Mission San Francisco de Asís (or Mission Dolores) by members of the Franciscan order of the Catholic Church. The establishment of Mission Dolores, and the twenty other California missions, brought the mission system to the region, which aimed to convert local indigenous peoples to Catholicism, expand the Spanish colonial sphere of influence, and establish a colonial society. While the mission system claimed to be based on the voluntary conversion of neophytes, large numbers of Native Americans were forcibly relocated to support the missions, devastating cultural continuity for many communities, and decimating indigenous populations through exposure to disease.[3]

In 1821, Mexico declared independence from the Spanish colonial government, taking with it the former Spanish colony of Alta California, including the land which would become San Francisco. Along with independence from the Spanish colonial government, Alta California was also subject to the secularization acts passed by the Mexican government that removed the power of the missions and sought to end the mission system, reclaiming mission lands to be redistributed through the rancho system.

During the Mexican period, a small village, whose first permanent resident in 1835 was British seaman William Richardson, was established around a plaza (today called Portsmouth Square) above a cove in San Francisco Bay. This village, which was called Yerba Buena, served as a minor trading center inhabited by a few hundred people of diverse nationalities. In 1839, a few streets were laid out around the plaza by resident Jean Vigot and settlement expanded up the slopes of Nob Hill. Not long after the United States seized California in 1846 and Captain John B. Montgomery planted an American flag at Portsmouth Square (named after Montgomery's ship the *Portsmouth*), an Irish-born surveyor named Jasper O'Farrell extended the original street grid by Vigot, while also laying out Market Street from what is now the Ferry Building to Twin Peaks. Blocks north of the planned Market Street alignment were laid out in small 50-*vara* square blocks, whereas blocks south

[3] Robert Archibald, "Indian Labor at the California Missions," *The Journal of San Diego History,* Spring 1978, v. 24, no. 2, accessed February 10, 2023, https://sandiegohistory.org/journal/1978/april/labor/; Charles Wollenberg, *Golden Gate Metropolis: Perspectives on Bay Area History* (Berkeley, California: Institute of Governmental Studies, University of California, Berkeley, 1985), 44-48.

of Market Street were laid out in larger 100 *vara* blocks.[4] The following year the village of Yerba Buena was renamed San Francisco to take advantage of the name's association with the bay.[5]

The discovery of gold at Sutter's Mill in 1848 brought explosive growth to San Francisco, with thousands of would-be gold-seekers making their way to the isolated trading outpost on the edge of the North American continent. Between 1846 and 1852, the population of San Francisco mushroomed from less than 1,000 people to almost 35,000. The lack of level land for development around Portsmouth Square soon pushed development south to Market Street, eastward onto filled tidal lands, and westward toward Nob Hill. At this time, most buildings in San Francisco were concentrated downtown, and the outlying portions of the peninsula remained unsettled throughout much of the late nineteenth century.[6] San Francisco's waterfront was transformed into a major shipping center for goods en route to the gold mines in the Sierra Nevada Mountains.[7]

The discovery of the Comstock Silver Lode in 1859 also prompted renewed investment in and marvelous profits from mining and real estate through the 1870s for a few wealthy San Franciscans.[8] Construction and real estate values skyrocketed in the city, just as they had following the discovery of gold in 1848.[9] With the decline of gold production in 1855, San Francisco's economy diversified to include agriculture, manufacturing, shipping, construction, and banking.[10] Prospering from these industries, a new elite of merchants, bankers, and industrialists arose to shape the development of the city as the foremost financial, industrial, and shipping center of the West.

THE MARINA DISTRICT

3400 Laguna Street is located within San Francisco's Marina District neighborhood. The boundaries of the Marina are roughly defined by the San Francisco Bay to the north, Van Ness Avenue and Fort Mason to the east, Lombard Street to the south, and the Presidio of San Francisco to the west.

As shown on the U.S. Coast Survey map, most of what is today the Marina District was historically submerged beneath San Francisco Bay **(Figure 51)**. During the first decades of the City's history, the eastern part of the Marina District consisted of an enormous sand dune bounded approximately by Black Point (today's Fort Mason) on the north, Leavenworth Street on the east, Fillmore Street on the

[4] A *vara* is is an antiquated Spanish unit of measurement.
[5] Rand Richards, *Historic Walks in San Francisco: 18 Trails Through the City's Past,* (San Francisco: Heritage House Publishers, 2002), xii-xiii.
[6] Rand Richards, *Historic San Francisco. A Concise History and Guide,* (San Francisco: Heritage House Publishers, 2001), 77.
[7] Susan Dinkelspiel Cerny, *An Architectural Guidebook to the City: San Francisco and the Bay Area,* (Salt Lake City: Gibbs Smith, 2007), 1.
[8] Gray Brechin, *Imperial San Francisco: Urban Power, Earthly Ruin,* (Berkeley: University of California Press, 1999).
[9] Cerny, *An Architectural Guidebook to the City: San Francisco and the Bay Area,* 3.
[10] Rand Richards, *Historic San Francisco. A Concise History and Guide*, 77.

west, and Lombard Street on the south. Several lagunas, or lakes, are also shown south of Lombard Street. The largest of these was known as "Washerwoman's Lagoon" as it was the site of numerous laundry facilities, as well as other industries requiring large amounts of fresh water **(Figure 52)**. What is today the heart of the Marina District was a shallow tideland with a "rural landscape of mud flats, shanties, pastures, and small farms."[11] The primary routes through the area were the Presidio Road, developed during the 1840s, and the Bay Shore & Fort Point Road, a toll road developed in 1864 which ran from North Beach to the Presidio.[12]




Figure 51: Overlay of current street grid onto the 1869 Coast Survey map on current street grid. Source: David Rumsey Map Collection

[11] Christopher VerPlanck, "From Mud Flats to Marina: Building a San Francisco Neighborhood," *Heritage News* 35 (Summer 2007), 5.
[12] Robert Bardell, "The Presidio Road," *The Argonaut*, Vol. 23, No.2, Winter 2012, 4-11.



Figure 52: View of the Marina District, circa 1860, viewed facing west, with Washerwoman's Lagoon in the mid-ground Source: Carleton E. Watkins Collection, Bancroft Library, University of California, Berkeley

To the east was Fort Mason, a military reservation created in 1850 at Black Point, a prominent outcropping of rock. Fort Mason was not fortified, however, until 1863 during the Civil War. Immediately southwest of Fort Mason was Lobos Square, bounded by Chestnut, Laguna, Webster and Bay streets. The Square was reserved in 1855 by the San Francisco Board of Supervisors but remained vacant throughout the nineteenth century. As discussed in Randolph Delehanty's study of San Francisco parks: "It was the only true bayside reservation and fronted on the tidal marshes near what became Gashouse Cove and the Fulton Iron Works. Nothing was done to improve the site until the filling in of the marshes for the gigantic Panama-Pacific International Exposition of 1915."[13]

The "Gashouse Cove" [Gas House Cove] mentioned by Delehanty referenced the gas works constructed by the San Francisco Gas Light Company in the late 1800s. In particular, a massive gas storage tank was constructed at the northwest corner of Bay and Laguna streets (visible in a 1938 aerial photograph included as **Figure 54**). In addition to the gas and iron works, other industrial plants located in the area included the California Pressed Brick Company, the Pacific Ammonia Chemical Company, and a soap and tallow works.[14]

[13] Randolph Stephen Delehanty, *San Francisco Parks and Playground, 1839 to 1990: The History of Public Good in One North American City (Volumes I and II)*, Harvard University Thesis, 1992, 82-83.
[14] VerPlanck, "From Mud Flats to Marina," 6.

After the 1906 earthquake and subsequent fire, two refugee camps were established in the area. By 1910, San Francisco merchants raised over four million dollars to acquire the Harbor View area for the site of a world's fair. Suction dredges were used to pump sand and mud from San Francisco Bay to fill the remaining area behind an existing seawall, and existing buildings adjacent to the newly filled land were demolished to make way for construction of the fair buildings.

The Panama-Pacific International Exposition (PPIE) opened in February 1915—celebrating both the completion of the Panama Canal and San Francisco's recovery from the 1906 earthquake. Over 18 million visitors came to the fair over the course of the year, marveling at an astonishing array of "temples" and "palaces" constructed at the site. The future site of 3400 Laguna Street was located within the Amusement and Concession Zone of the fair (visible at right in **Figure 53**).




Figure 53: Detail of the 1914 Southern Pacific "Map of San Francisco and Vicinity" showing the layout of the Panama Panama-Pacific International Exhibition. Source: David Rumsey Map Collection

The vast majority of the PPIE buildings were designed to be temporary, and by 1916 the only remaining buildings were the Yacht Harbor, the North Gardens (now Marina Green), the Palace of Fine Arts, and the Column of Progress (no longer extant). The streetcar lines established by the San Francisco Municipal Railway to provide access to the fair also remained in use, making the former PPIE lands extremely attractive for residential development. In 1922, the Marina Corporation was formed to develop 55 acres bounded by Fillmore, Scott, Chestnut and Marina Boulevard. Here, diagonal and curvilinear streets were installed to provide bay views and promote the idea of a

residential park. Residential and commercial uses were generally segregated as the result of the passage of San Francisco's first zoning law in 1917.[15]

In the 1920s and 1930s, the new Marina District—as the former Harbor View area came to be known—experienced a sustained residential building boom. New houses, flats, and apartments were constructed in a variety of architectural styles, with Mediterranean Revival and Classical Revival influenced designs by far the most popular. Other common influences included Tudor Revival, Spanish Colonial Revival, and French Provincial designs, as well as scattered examples of Art Deco style buildings. The subject building, built as the Ladies Protective & Relief Society retirement home on a large parcel at the northwest corner of Francisco and Laguna Streets, was one of the most prominent new buildings in the Marina.



Figure 54: East end of the Marina District in 1938, showing Lobos Square/Funston Playground left of center and subject property indicated with red arrow; note the gas storage tank north of Funston Playground. Source: Harrison Ryker, accessed at the David Rumsey Map Collection

[15] VerPlanck, "Marina District Development Takes Off," *Heritage News*, Vol. XXXV, No. 4, Fall 2007, 5.

Civic development accompanied the growth of the Marina District. This included construction of the Funston Playground (now called Moscone Recreation Center, located directly west from the subject building), as well as the Marina Junior High School (1937). Chestnut Street evolved as the primary commercial corridor, largely because it marked the route of the Geary-Van Ness streetcar line, later replaced by buses. By the late 1930s, the Marina District was almost completely built out **(Figure 54)**. Promotional literature from the 1930s touted the Marina District's schools, parks, tennis courts and thousands of beautiful homes as the "garden spot" of San Francisco.[16]

World War II brought a rush of military activity at Fort Mason and the Presidio. Fort Mason supervised transportation activities at other installations in the Bay Area and was used as a port of embarkation for military personnel.

During the mid-20th century, Lombard Street—providing direct access to the Golden Gate Bridge—was developed with a large number of motels catering to auto tourists. More recently, the Marina District suffered severe damage during the 1989 Loma Prieta Earthquake, as liquefaction of the land filled for the PPIE caused buildings to collapse and gas mains to burst. The damaged properties have since been renovated or rebuilt, and the neighborhood is currently considered an attractive residential district within the city.

SOCIAL WELFARE AND OLD AGE HOMES

The following history of old age care facilities in San Francisco is informed by the historic landmark nomination for the University Mound Old Ladies' Home, completed by staff of the San Francisco City Planning Department in 2015, unless otherwise noted.[17]

Retirement and old age care has historically responded to shifts in social and economic conditions and social reform legislation. In the pre-industrial era, the aging farmer was likely to be employed as long as his health held out. As Americans increasingly earned their livelihoods at factories rather than farms, older people in cities became less able to participate in remunerative activities, and were often forced into poverty, living in almshouses or other institutions with other needy persons, orphans, and the insane. Late 19th century welfare and charity workers advocated for separate institutionalization of poor elders, forming a "home" that provided cheap, efficient care for those not only destitute but likely infirm as well. However, many questioned the propriety of sending the

[16] Sanborn Map Company (1924-1949); San Francisco Public Library Vertical Files: "SF Districts: Marina;" Chris VerPlanck, "From Mud Flats to Marina: Building a San Francisco Neighborhood," *Heritage News* 35 (Summer 2007), 5-8.
[17] San Francisco Planning Department, "Landmark Designation Report, University Mound Old Ladies' Home, 350 University Street," May 20, 2015.

middle-class old people to these same places for care, and instead, many private old age homes were founded around this time period. By the end of the century, most of the residents in an old age home were white, middle-class women who had paid to enter. [18]

The first old age home for ladies in Philadelphia, the Indigent Widows' and Single Women's Society (Society) opened in 1817, and provides insight into the model of private nursing homes. The Society declined any applicant who had been raised in poverty, and accepted respectable women who came from refined walks of life and were used to certain comforts. The Society wanted the women to see the institution as their home and the other inmates as their family. To this end, women were provided private rooms and meals were taken at a general table meant to ensure a feeling of family unity. Each applicant was required to give proof of her character and provide recommendations. Once admitted, she was given a one-year probationary period and expected to donate her labor, sewing, knitting, and quilting to help raise money for the institution.[19]

By the beginning of the 20th century, scores of similar homes were in every large American city.[20] In 1932, shortly after the San Francisco Ladies' Protection and Relief Society was completed and opened at 3400 Laguna Street, the San Francisco city directory listed 25 "Homes and Asylums," including seven orphanages and five asylums specifically for women or girls. Of the institutions listed at this time, only four are extant and still operate as convalescent/nursing homes. In addition to the Ladies' Protection and Relief Society at 3400 Laguna Street, these include the Hebrew Home for the Aged and Disabled (Jewish Home San Francisco) at 302 Silver Avenue (designed by Samuel Lightner Hyman, 1923, extensively altered in 1969 by Howard Friedman and with a 1970 courtyard and fountain designed by Lawrence Halprin); the Christian Science Benevolent Association on the Pacific Coast (Arden Wood) at 445 Wawona Street (designed by Henry Gutterson, 1930) and the University Mound Old Ladies' Home, at 350 University Street (designed by Martin J. Rist and Alfred I. Coffey, 1931-2) **(Figure 55 to Figure 57)**.

[18] San Francisco Planning Department, "Landmark Designation Report, University Mound Old Ladies' Home, 350 University Street," May 20, 2015, 20-1.
[19] Carole Haber, *Beyond Sixty-Five: The Dilemma of Old Age in America's Past* (Cambridge: Cambridge University Press, 1983).
[20] Haber, *Beyond Sixty-Five: The Dilemma of Old Age in America's Past*.



Figure 55: Jewish Home of San Francisco, 302 Silver Avenue, view of 1969 Howard Friedman addition. Source: www.jhsf.org



Figure 56: Christian Science Benevolent Association on the Pacific Coast (Arden Wood), 445 Wawona Street, designed by Henry Gutterson, 1930. Source: www.ardenwood.org



Figure 57: University Mound Old Ladies' Home, designed by Martin J. Rist and Alfred I. Coffey, 1932. Source: San Francisco Public Library, AAD-0005.

Changes in federal law during the first half of the twentieth century had significant impacts on the landscape of welfare care in the United States—particularly eldercare. The 1935 Social Security Act

provided direct payments to many American elderly, who may not have been able to afford private care facilities in the past. In 1946, Congress passed the Hill-Burton Act, offering federal subsidies to fund modern hospital construction. In 1954, the Hill-Burton Act was expanded to fund hospital-affiliated nursing homes.[21] This change in policy coincided with the growing popularity of private nursing homes in the United States, which formed a marketplace of eldercare options through the 1950s and 1960s. Clear evidence of this trend is available in San Francisco city directories: in 1951 and 1952, directories listed only one nursing home, and in 1953 none were listed. The 1955-1956 directory, however, had thirteen. These facilities do not appear to be related to hospitals in the city and therefore are unlikely the direct result of the Hill-Burton Act, but their establishment conveys a new era in eldercare—in which care for the aging transitioned from the sphere of social welfare into the broader sphere of modern medicine and healthcare.

[21] Laura Katz Olson, *The Not-So-Golden Years: Caregiving, the Frail Elderly, and the Long-Term Care Establishment* (Lanham, MD: Rowman & Littlefield, 2003), 158.

V. SITE HISTORY

SITE DEVELOPMENT

Prior to the construction of 3400 Laguna Street in 1925, the subject site was platted but largely undeveloped until the construction of the Panama-Pacific International Exposition in 1915. The site was located in the Amusement and Concession Zone of the fair, and a detail of the 1915 Sanborn Insurance Company Map shows attractions including the Submarines, Natatorium, Indian Pueblo, Incubator, and the Grand Canyon of Arizona on or near the subject site **(Figure 58).**




Figure 58: 1915 Sanborn Fire Insurance Company Map, with the approximate subject site outlined in red; note location of the gas holding tanks of the Pacific Gas and Electric Co. amid the fairgrounds, at the northwest corner of Laguna and Bay. Source: San Francisco Public Library.

After the close of the fair, all of the amusements and their related buildings were demolished, and the subject site was vacant in the early 1920s—at which point it was donated to the Ladies' Protection and Relief Society.[22] Although original bulding permits for 3400 Laguna Street have not

[22] "History," Heritage on the Marina, February 10, 2023, https://heritageonthemarina.org/about-heritage-on-the-marina.

been recovered, the completion of the building, designed by prominent architect Julia Morgan, was announced in the *San Francisco Chronicle* on May 15, 1925. The building was described as three stories over a basement, built to face Funston Square. The construction costs were partly covered through a $50,000 donation from the late Lizzie G. Hovey, friend of the institution; what is described as an "attractive Serena court in the garden" was made possible by a bequest from Serena Goodall Keil.[23]

A 1925 photograph, noted on the back as the "new home of the S. F. Ladies Protection and Relief Society," shows the primary and south facades of the building, with few differences from the building's current appearance **(Figure 59)**. The double arches of the primary entrance are portals opening to a recessed vestibule, rather than enclosed as they are today; however, their shape and configuration remain the same. None of the penthouses, elevator tower, or stair tower are visible: although no permits are on file for the additon of these features, they appear to have been constructed after 1925.



Figure 59: 1925 photograph of 3400 Laguna Street. Source: Lothers and Young Collection, San Francisco Historical Photograph Collection, AAC-9988.

[23] "Society in New Home," *San Francisco Chronicle*, May 15, 1925.

The stone cottage near Bay Street was constructed as a dwelling from late 1928 to 1929.[24] The building was designed by local Berkeley designer and contractor Ernest Higgins.



Figure 60: Aerial photograph of 3400 Laguna Street in 1938, showing extensive grounds east of the building. Source: Harrison Ryker photograph, accessed at the David Rumsey Map Collection.

A 1938 aerial photograph of the subject property shows the extensive landscaped grounds to the east of the building, which appear to extend to full depth of the current rear courtyard, and include pathways, mature vegetation, and gridded plantings, but does not include the two squared fountains and brick patio that are currently within the center courtyard **(Figure 60 and Figure 61)**. Although the resolution of the photograph does not provide conclusive information about whether the penthouse and elevator stack had been constructed by this time, there is a clearly visible stair

[24] "Building Contracts, Etc." *The Recorder.* 1928 Dec 10. Accessed February 13, 2023; *Building and Engineering.* Volume 28, July to December 1928. Accessed February 13, 2023. Note that the plaque for the stone cottage that is located on the site states that the cottage was constructed in 1925 and funded through a donation by Edith Allyne.

stack corresponding with the location of the current stair stack to the penthouse, suggesting that the penthouse was in place at this time.



Figure 61: Gardens of the Ladies' Protection and Relief Society, 1935. Source: San Francisco Historical Photograph Collection, #AAC-9991

The 1950 Sanborn Map Company map provides little new information about the subject property. The building is described as two-and-one-half stories over a basement, with steam heat and electric lights. The stone cottage—the only other building within the grounds at this time—is noted on the Sanborn map as in use as a storehouse **(Figure 62)**.




Figure 62: 1950 Sanborn Fire Insurance Company Map, with the subject site outlined in red
Source: San Francisco Public Library Online Database

In a 1956 photograph of 3400 Laguna Street, the only change visible to the primary façade is the enclosure of the left arch of the front vestibule entrance **(Figure 63)**. In this photograph, the stair and elevator stacks are both visible.



Figure 63: 1956 photograph of 3400 Laguna Street. Source: San Francisco Historical Photograph Collection, #AAC-9989

Also in 1956, permits were drawn for the construction of an addition to 3400 Laguna Street. The addition was designed by architect Warren C. Perry, and provided space for new residents, which was necessary after the merger of the San Francisco Ladies' Protection and Relief Society with the Crocker Old People's Home. Originally permitted as a three-story addition, a second permit was requested in 1957 to add a fourth floor, reflecting the building's current configuration. The new wing was completed at a reported cost of $1 million and was at that time the first facility specifically designed for the aged to be built in San Francisco in more than 25 years.[25] Residents moved into the facility in 1957. A permit to remodel the stone cottage was also issued in 1957, listing Hewitt C. Wells as architect. A plaque at the site states that this building was "reconstructed" that year. It appears that building was returned to its original use as a dwelling under this scope of work, and the building is referenced as the "superintendent's cottage" in a 1958 article in the *San Francisco Examiner* titled "Home for Aged Opens Tomorrow."[26] Additional alterations that may have occurred at that time include repointing and construction of the boxed bay at the west façade.

In 1962, architect Gardner A. Dailey was contracted to design another addition to the building. This addition was a one-story infirmary, with reinforced concrete walls, roof and floor. The cost of construction was reported at $300,000, and the building was designed to handle 32 patients.[27] The addition's simple utilitarian design reflects its serious medical use. Further 1986 additions to the wing, by Spencer & Associates, have enlivened the building with brick-clad gables and a glazed sunroom that reference the Tudor/Jacobethan architectural style of the original Julia Morgan building.

A Sanborn Map Company map updated to the mid-1990s shows the O-shaped footprint created by the 1925 main building, the L-plan 1956 addition, and the slim rectangular footprint of the 1963 addition **(Figure 64)**.

[25] "For a Better Old Age," *San Francisco Chronicle*, April 25, 1958.
[26] "Home for Aged Opens Tomorrow." *San Francisco Examiner.* April 17, 1958. Accessed February 13, 2023.
[27] "The Heritage Extension Work Begins," *San Francisco Chronicle,* November 21, 1962.




Figure 64: Mid-1990s Sanborn Insurance Map, subject site outlined in red; this map does not show the 1986 additions to the 1963 addition. Source: San Francisco Property Information Map.

In 1993, the loading area at the north façade of the main building was reconfigured to include an exterior platform and metal roof, reflecting its current appearance. Alterations to the building since the mid-1990s have been largely interior or related to building upkeep (full permit record follows); in 1994, however, a series of aluminum windows was replaced with wood-clad metal windows at the first story of the north portion of the 1956 addition, affording this area of the addition greater compatibility with the older building that it adjoins.

Construction Chronology

The following table provides a timeline of major construction activity at 3400 Laguna Street, based on building permit applications on file with the San Francisco Department of Building Inspection. Cancelled and expired permits are not included. The building has also experienced numerous alterations to its fire safety and ventilation systems, as well as minor interior renovations. These are not listed below.

Date Filed	Permit Number	Owner	Architect (a) or Contractor (c)	Scope of Alterations
7/27/1956	187273	Ladies' Protection and Relief Society	Warren C. Perry (a); Erpentraut & Summers (c); Thomas E. Chace (eng.)	New 3 story addition with a basement
1/16/1957	194048	Ladies' Protection and Relief Society	Warren C. Perry (a); Erpentraut & Summers (c); Thomas E. Chace (eng.)	Add 1 floor to the new building now under construction
6/24/1957	199407	Ladies' Protection and Relief Society	Hewitt C. Wells (a); Wagner & Martinez (c)	Remodeling of existing stone cottage
8/23/1962	270319	The Heritage	Gardner A. Dailey (a); Gilbert, Forsberg, Diekmann, Schmiidt (arch. const); Swinerton & Walberg Co. (c)	New 1-story infirmary addition with basement, with reinforced concrete walls, roof & floors, and metal stud partitions
12/30/1963	292115	The Heritage	Gardner A. Dailey (a)	New bathrooms added to second and third floors with some partition changes
6/13/1980	461073	The Heritage	Unknown	8 sliding glass doors
10/26/1989	626043	The Heritage	Plant Builders Inc. (c)	Remove 2 masonry fireplaces & chimneys (damaged in earthquake) and provide waterproof caps
5/27/1990	651545	The Heritage	Plant Builders Inc. (c)	Reconstructed 3 brick chimneys from attic upwards (exact replacements)
6/4/1993	722871	The Heritage	Thomas R. Potts (a)	Construct additional platform area at loading dock and add light weight metal roof over platform area
7/28/1993	726419	The Heritage	Muratore Corp.	Repair tile around drain and correct leaks at existing terrace deck
10/15/1993	732103	The Heritage	Dasse Design	Parapet and ornament bracing
12/2/1993	722871	The Heritage	Thomas R. Potts (a)	New horizontal extension consisting of new loading

Date Filed	Permit Number	Owner	Architect (a) or Contractor (c)	Scope of Alterations
				dock metal roof and support system
11/10/1994	758539	The Heritage	Muratore Corp.	Replace aluminum windows with wood windows to conform to the rest of the building in existing openings
6/12/1996	796188	The Heritage	Barker Assoc.	Replace existing deteriorating front entry hand rail and guard rail
8/12/1997	828851	The Heritage	Lawson Roofing Co.	Remove roofing, install "taper installation system"
8/15/1998	857399	The Heritage	Lawson Roofing Co.	Reroofing work
5/7/2002	965971	The Heritage	Western Roofing Service	Remove & replace existing slate roof to match existing
2/20/2015	201502208910	Not listed	Not listed	Reroofing at unspecified location
9/2/2016	201609026686	Not listed	Not listed	One story horizontal addition at unspecified location
9/17/2018	201809170424	Not listed	Not listed	Renovation of interior of cottage with additional exterior scope replacing access ramp and railing and existing wood fence
5/13/2022	202205134177	Not listed	Not listed	Reroofing at unspecified location

OWNERSHIP AND OCCUPANT HISTORY

Select Owner and Occupant Biographies

HISTORY OF THE LADIES' PROTECTION AND RELIEF SOCIETY, ORIGINAL OWNER

The following history of the Ladies' Protection and Relief Society is sourced from the collection of the California Historical Society, accessed at the Online Archive of California, unless otherwise cited.[28]

With the stated mission to "render protection and relief to strangers, to sick and dependent women and children," a group of middle-class San Francisco women, headed by philanthropist Mrs. A.B.

[28] California Historical Society, "Finding Aid to the San Francisco Ladies' Protection and Relief Society Records MS 3576," *Online Archive of California,* Accessed February 13, 2023, https://oac.cdlib.org/findaid/ark:/13030/kt338nf0rf/?query=Ladies%E2%80%99+Protection+and+Relief+Society

Eaton, formed the San Francisco Ladies' Protection and Relief Society in 1853. From an office at 151 Sacramento Street, a Board of Lady Managers was placed in charge of the daily affairs, and a Board of Trustees managed financial decisions. The Society offered relief to women and their dependent children who had moved to San Francisco seeking relatives or fortunes, only to find themselves alone and impoverished.

By 1857 the Society had grown from an office to a live-in home at Second and Tehama Streets known as the "Hospitality House." The Society developed a program to help orphans find adopted families. In 1858 the Act of Legislature granted the Society permission to apprentice the children in a system known as "binding out." Doubling as an employment agency, the Society sent orphans to work in local businesses or in family homes as domestic servants. While this was a charitable effort, it also represented class attitudes of the Society members who sought to place the children in lower paying jobs, which reflected what they believed to be the children's proper station in life.

In 1860 the Society moved again, to an imposing brick structure designed by S.C. Bugbee, at the intersection of Geary Avenue and Franklin Street, an area that was at that time considered the edge of town **(Figure 65)**. The house served as both home and school, with lessons in sewing, cooking and moral training for young women. Most of the women were trained to go into department sales, hairdressing and later, clerking and typing. This system of in-house education continued until 1913, after which the children were educated in the public schools.




Figure 65: Second home Ladies' Protection and Relief Society, at Geary and Franklin streets, c. 1865. Source: Library of Congress

Attitudes regarding childcare institutions changed in the 1920s, and foster care homes started to replace the impersonal atmosphere of the large, often overcrowded institutions. In response to the changing ideology, the Society began to discuss what other social services they could offer the city of San Francisco. After much deliberation, they chose to help the elderly. The Society commissioned noted architect Julia Morgan to design a new facility to serve as a retirement home at 3400 Laguna Street. After it opened in 1925, the home developed a reputation of one of the finest private retirement homes in the city.

The terms for admission were laid out as follows in a *San Francisco Chronicle* article marking the opening of the new facility:

> [....] A nominal charge of $1 a day will be made, subject to modification for special need. No worthy person entitled to such care as we plan to give will be excluded from the benefits of the home, save as space is limited. Convalescent women and children (not bed patients) will be received for a term of three weeks. Dependent women will be received for life, if their conduct proves such as to make them adaptable to the general environment.[29]

[29] "Society in New Home," *San Francisco Chronicle*, May 15, 1925.

The public was invited to the opening of the Society's new facility over the weekend **(Figure 66)**.



Figure 66: *San Francisco Chronicle* article announcing the opening of the new home of the Ladies' Protection and Relief Society, including the home's oldest resident, Mrs. Amy Walker, 87. Source: *San Francisco Chronicle*, May 15, 1025

The Society retained ownership of the property at Geary and Franklin, however, and this land continued to be of great value. After leasing the property to various businesses over the years, the Society drafted a tremendously lucrative contract with the Jack Tar Hotel. This 1954 contract assured them of a secure economic future.

The Scandinavian Benevolent and Relief Society was among the many Victorian relief societies which existed at the same time as the San Francisco Ladies' Protection and Relief Society. Founded in 1875 by Minnie Nelson, the Society was dedicated to the care of the elderly. With a staff of volunteers, they established an "old people's home" on Francisco Street near Powell and Stockton. The Society remained at this site until 1884, when Mary Crocker offered her lot at the corner of Pine and Pierce as a memorial to her late husband Charles Crocker, the railroad magnate. When the Society moved to their new location, they promptly changed their name to the Crocker Old People's Home. After

the San Francisco Fire Department condemned the building as a fire hazard in the 1930s, the Society engaged in 20-year legal dispute until they were finally forced to leave in the early 1950's.

After much discussion and litigation, the San Francisco Ladies' Protection and Relief Society and the Crocker Old People's Home decided to merge into a single organization. After completion of a new wing at the Julia Morgan building at 3400 Laguna Street, the Crocker Old People's Home moved in 1957. The merged entity continued operating as the San Francisco Ladies' Protection Society, renaming the 3400 Laguna Street facility "The Heritage" in 1959. After the merger, the organization's mission shifted away from convalescent care—which had been one focus of the Ladies' Protection and Relief Society for many decades—towards an exclusive eldercare mission.[30]

The organization is officially now the San Francisco Ladies' Protection and Relief Society DBA (doing business as) The Heritage. In 2013, a new DBA name was added: Heritage on the Marina. This organization has been in operation in San Francisco for over 160 years.

BIOGRAPHIES OF ARCHITECTS AND DESIGNERS

Julia Morgan

Julia Morgan (1872–1957) was born in San Francisco and grew up in Oakland. After graduating from high school, she enrolled in the College of Civil Engineering at the University of California, and in 1894 became the first woman at the University to graduate with a degree in civil engineering. She subsequently studied with famed architect Bernard Maybeck, who encouraged her to enroll at the prestigious École des Beaux-Arts in Paris.[31] Through the influence of Maybeck, Morgan was visited by Phoebe Apperson Hearst during her time in Paris, resulting in a longstanding association with the Hearst family that would lead to a number of important commissions.[32] In 1901, Morgan graduated from the École des Beaux-Arts, becoming the first woman to receive a certificate in architecture from the École.

Morgan returned to the San Francisco Bay area and worked for a time with the architect John Galen Howard. During this time Morgan completed drawings for the Hearst Mining Building at the University of California. Morgan also worked on drawings for the University's Greek Theater, and served as supervisor for its construction.

[30] "History," Heritage on the Marina.
[31] Sara Holmes Boutelle, *Julia Morgan Architect*, (New York: Abbeville Press Publishers, 1995), 23-24.
[32] Cary James, *Julia Morgan*, (New York: Chelsea House Publishers, 1990), 45.

In 1904 Morgan became the first woman in California registered as an architect. Among her first commissions was remodeling the Hacienda del Pozo de Verona, the large county residence of Phoebe Apperson Hearst. This was followed by a commission to design a Mission-style bell tower known as "El Campanil" for Mills College, a women's college in Oakland (1904). More designs for Mills College followed, including the Margaret Carnegie Library (1905), a gymnasium, and an infirmary. Working at a time when women's organizations were growing in prominence, Morgan was frequently chosen as the architect for their institutional buildings, which comprised the majority of her non-residential work.[33] Among her most important clients was the Young Women's Christian Association (YWCA), for whom she designed building in numerous California cities **(Figure 67)**.



Figure 67: Oakland YWCA, constructed 1913-1915. Source: Google Images

Morgan's career was propelled in part by rebuilding efforts following the 1906 earthquake and fire, including the reconstruction of the Fairmont Hotel in San Francisco. In 1907, she moved into an office at the Merchants Exchange Building in San Francisco, where she remained for several decades.[34] Over the ensuing years, Morgan was commissioned to design hundreds of buildings, both residential and institutional. In her designs, Morgan was "eminently practical in her use of form, space and structure. [...] The exteriors of her buildings show a balance between deliberate understatement of the whole and precise definition of the parts."[35] Her work was not confined to any particular architectural style, but rather demonstrated flexibility in blending American and European historical influences with her Classically inspired Beaux-Arts training.

[33] Richard W. Longstreth, *Julia Morgan – Architect*, (Berkeley: Architectural Heritage Association, 1986), 6.
[34] Boutelle, *Julia Morgan Architect*, 42
[35] Longstreth, *Julia Morgan*, 9.

Morgan was also strongly influenced by the increasingly popular Arts and Crafts style, which in the San Francisco Bay area was absorbed into what is today known as the First Bay Tradition. In this respect, Morgan often eschewed complicated structural devices but was perfectly willing to expose structural members when she felt they were "compatible with other aspects of the design; that is, when both utilitarian and aesthetic purposes were served without compromising either."[36]

Morgan maintained a working relationship with Phoebe Hearst's son, William Randolph Hearst. In 1919, William Randolph Hearst also began working with Morgan on the designs for an estate known as "Casa Grande" in the Santa Lucia Mountains near San Simeon, California. Over the next eighteen years Morgan was involved in work on the building, today famed as Hearst Castle.



Figure 68: Sketch for the Berkeley City Women's Club, c. 1929. Source: landmarkscalifornia.org

She also worked on several clubhouse buildings, including the Sausalito Women's Club (1916-18), the Claremont Club in Berkeley, the Foothill Club in Saratoga (1915), the Studio Club in Hollywood (1926), and the Romanesque/Moorish styled Berkeley City Women's Club (1929) which is the Berkeley City Club today **(Figure 68)**.[37] She designed another women's use building, the Ladies'

[36] Longstreth, *Julia Morgan*, 28.
[37] James, *Julia Morgan*, 87.

Protection and Relief Society in San Francisco, in 1925. In 1929 she was recognized by the University of California with an honorary doctoral degree.

In 1932, Morgan underwent an operation for an infected ear that resulted in the severing of nerves that affected her balance and left her with a facial droop.[38] Nevertheless, she continued working on commissions, including remodeling the Hearst Building in San Francisco (1937), as well as a complex of Bavarian-styled buildings at William Randolph Hearst's Wyntoon estate near Mount Shasta. She also continued to design columbaria, including the Homelani Columbarium in Hilo, Hawaii (1935-37), as well as the Chapel of the Chimes Mortuary in Santa Rosa (1938).[39]

By the 1940s, however, Morgan began slowing her architectural practice, in part because of recurring memory lapses.[40] In 1950 she closed her practice altogether, and after a series of small strokes became reclusive.[41] She died at age 85 in February of 1957, and is buried in the Mountain View Cemetery in Oakland. In 2014, the American Institute of Architects posthumously awarded the AIA Gold Medal to Julia Morgan. Morgan is the first woman to ever be given the AIA Gold Medal.[42] She has been recognized internationally as one of the United States and California's most prominent architects and is considered to be an architect of merit.[43]

Warren C. Perry

Warren Charles Perry was born May 12, 1884 in Santa Barbara, California, but grew up in Berkeley, where his family had moved when he three years old.[44] He graduated from Berkeley High in 1903 and began undergraduate studies in Civil Engineering at the University of California at Berkeley. Perry took classes with John Galen Howard and during the summers of 1906 and 1907 worked in Howard's San Francisco office. Perry traveled to Paris in the fall of 1907 to study at the renowned École des Beaux-Arts, and returned to the Bay Area in 1911. He joined the faculty of the Department of Architecture at Berkeley that year, and began to work on residential and commercial projects in

[38] James, *Julia Morgan*, 97-98.
[39] Mark Anthony Wilson, *Julia Morgan Architect of Beauty*, (Santa Barbara: Gibbs Smith, Publisher, 2007), 86-87.
[40] James, *Julia Morgan*, 102-105.
[41] James, *Julia Morgan*, 105.
[42] "Julia Morgan, 2014 AIA Gold Medal Recipient", American Institute of Architects website, accessed February 10, 2023, https://www.aia.org/awards/7046-gold-medal.
[43] While the National Register and California Register have previously used the terminology "master" architect or builder, the terminology used here to reflect current best practices is "architect of merit," which similarly refers to an architect with "recognized greatness" in their field, whether at a local, state, national, or, even an international, level.
[44] David Parry, "Warren Charles Perry". The Encyclopedia of San Francisco, accessed online at http://sfhistoryencyclopedia.com/articles/p/perryWarren.html.

Howard's San Francisco architecture firm.[45] In 1913 Perry was licensed and established his own practice.

Perry succeeded Howard as Chairman of the School of Architecture in 1927 and two years later was appointed Dean of the School, a position he held until 1950. Perry designed, alongside George Kelham, the George C. Edwards Track Stadium, which opened in 1932 **(Figure 69)**.




Figure 69: George C. Edwards Track Stadium at UC Berkeley. Source: Google Maps, 2022.


Figure 70: 2530 Vallejo Street, San Francisco. Source: Google Images

Perry's teaching responsibilities did not allow a great deal of time for private practice, but he did complete some residential projects in San Francisco—including 2530 Vallejo, a blend of the classical and shingle styles, for his family **(Figure 70)**, as well as 3140 Pacific (1926) and 3150 Pacific (1932), and a remodeled Victorian at 3028 Clay. Some other prominent houses in the city designed by Perry are the Italian Renaissance-style corner house at 2585 Pacific (1924), 570 El Camino del Mar in Sea Cliff (1930), and 165 Terrace Drive in St. Francis Wood, designed in 1936.

Perry was a member of the State Board of Architectural Examiners for 13 years from 1931 to 1943, and served as president for two of them, 1934-35. He also served as vice president of the San Francisco Chapter of the American Institute of Architects (AIA) for two years, 1936-1937, and then as its president in 1938. Perry was recognized for his contributions to architectural education and the profession by being made a Fellow of the AIA, the highest honor that institution bestows, in 1947.

[45] "Warren Charles Perry, Architecture: Berkeley", University of California: In Memorium, 1980, accessed February 10, 2023 http://texts.cdlib.org/view?docId=hb1j49n6pv;NAAN=13030&doc.view=frames&chunk.id=div00073&toc.depth=1&toc.id=&brand=oac4.

Perry retired in 1954, making the design for the addition to the Ladies' Relief and Protection Society at 3400 Laguna Street one of his final projects. Perry died in San Francisco in 1980 at the age of 95.

Gardner A. Dailey

Gardner Dailey was born in St. Paul, Minnesota, in 1895 and moved to California in 1915 to work for Donald McLaren's landscape architecture firm.[46] He enrolled at the University of California, Berkeley in 1919, and continued his education at Stanford and Heald's Engineering School in San Francisco. Topics of study focused on botany and economics, as well as engineering and architecture. In 1926, he made a major tour of Europe, where he married Marjorie Dunne of San Francisco. Upon his return, he established his own architectural offices in San Francisco in 1926.

During the early years of his practice, Dailey focused on residential design in eclectic Spanish and Neoclassical styles exhibiting traditional revival influences in his work. In 1929, three years after establishing his architectural practice, his design for the Arnold House in Hillsborough was featured in the publication *California Arts and Architecture*.[47] A public commission for the Palega Playground Field House in San Francisco, constructed one year after the Arnold House, continued Dailey's early interest building in the Spanish Eclectic style.

Although his early work focused on the use of accepted historic styles, in the 1930s Dailey began to explore modern design. In 1935, he designed his first Modernist house, known as the Liebes House, in Hillsborough, which was distinguished by a two-story staircase and full height windows. The Lowe House (1936) in Woodside, was one of Gardner Dailey's most famous pre-war houses, published widely from 1936-1942. This house conveyed the "Early California" aesthetic favored by Dailey and his rival William Wurster at this time, derived from adobe ranch houses and spare timber-framed, rural vernacular structures built by Anglo farmers and miners **(Figure 71)**.[48]

An informal attitude and a desire to harmonize buildings with their sites connected Gardner Dailey with his counterparts, including William Wurster—the most recognized and studied of his contemporaries. Wurster and Dailey, along with a small group of Bay Area architects and landscape architects, came to define the second period of Bay Area regionalism of the 1930s and 1940s, known as the Second Bay Region Tradition.

---

[46] "Biographical Note: Inventory of the Gardener A. Dailey Collection, 1923-1979", University of California at Berkeley, Environmental Design Archives, accessed online at http://www.oac.cdlib.org/findaid/ark:/13030/kt396nb7zw/admin/#bioghist-1.8.4.
[47] *California Art and Architecture* (July 1929): 44-48.
[48] Pacific Coast Architecture Database, "Lowe, William, Jr., House, Woodside, CA", accessed February 10, 2023, https://pcad.lib.washington.edu/building/715/.




Figure 71: 1 Raycliff Terrace, San Francisco, 1951. Source: DOCOMOMO/NOCA.




Figure 72: Brazil Building, for the Golden Gate International Exposition on Treasure Island, 1939 Source: UC Berkeley Environmental Design Archives.

In addition to residential design, Dailey's firm designed medical, commercial, educational, civic, and recreational buildings. He was commissioned by organizations including the Matson Shipping Company, Stanford University, University of California at Berkeley, and the San Francisco Recreation and Parks Department. He designed the Brazil Pavilion for the Golden Gate International Exposition on Treasure Island **(Figure 72)** and was included in the seminal New York Museum of Modern Art's 1944 show "Built in USA," as well as the San Francisco Museum of Art (now the San Francisco Museum of Modern Art) show "Domestic Architecture in the San Francisco Bay Region" in 1949.

Over the course of his career, Dailey wrote little about his buildings or the overarching theory that informed his designs. When asked by *Architectural Record* about the existence of a Bay Area Style, Dailey responded that, "…if there is a Bay Area Style it is because there are—and always have been—Bay Area People."[49] Although he is best remembered for his influence in establishing the Second Bay Region Tradition, the canon of Dailey's architectural works shows the rapid evolution of twentieth century architectural design during his career, and specifically its articulation within a Bay Area context. Works from his early period, although more conservative and traditional in approach, represent the formative period of his career and together with his later works, including the 1963 addition to the Ladies' Protection and Relief Society, shows the maturity and progression of one of the Bay Area's most prominent designers. Dailey died on October 24, 1967, at the age of 72.

[49] "Is there a Bay Area Style?" *Architectural Record,* 105, no. 5 (May 1949): 93-94.

VI. EVALUATION

CALIFORNIA REGISTER OF HISTORICAL RESOURCES

The California Register of Historical Resources (California Register) is an inventory of significant architectural, archaeological, and historical resources in the State of California. Resources can be listed in the California Register through a number of methods. State Historical Landmarks and National Register-listed properties are automatically listed in the California Register. Properties can also be nominated to the California Register by local governments, private organizations, or citizens. The evaluative criteria used by the California Register for determining eligibility are closely based on those developed by the National Park Service for the National Register of Historic Places.
In order for a property to be eligible for listing in the California Register, it must be found significant under one or more of the following criteria.

- **Criterion 1 (Events):** Resources that are associated with events that have made a significant contribution to the broad patterns of local or regional history, or the cultural heritage of California or the United States.

- **Criterion 2 (Persons):** Resources that are associated with the lives of persons important to local, California, or national history.

- **Criterion 3 (Architecture):** Resources that embody the distinctive characteristics of a type, period, region, or method of construction, or represent the work of a master, or possess high artistic values.

- **Criterion 4 (Information Potential):** Resources or sites that have yielded or have the potential to yield information important to the prehistory or history of the local area, California, or the nation.

The following section examines the eligibility of 3400 Laguna Street for individual listing in the California Register.

Criterion 1 (Events)

The property at 3400 Laguna Street is significant under Criterion 1 (Events) at the local level as the contemporary site of one of the longest operating—if not the longest operating—eldercare service organizations in San Francisco. With the stated mission to “render protection and relief to strangers, to sick and dependent women and children," the San Francisco Ladies' Protection and Relief Society started providing services in San Francisco in 1853. The Society shifted from orphan and family care

to eldercare in the 1920s, and commissioned noted architect Julia Morgan to design an elder residence home at 3400 Laguna Street (which also provided space to convalescent women and children). The property at 3400 Laguna Street has made a significant contribution to the history of the city through early and ongoing efforts to protect and care for the city's older population.

In 1957, the San Francisco Ladies' Protection and Relief Society merged with the Crocker Old People's Home—another longstanding service organization, that was first established as the Scandinavian Benevolent and Relief Society in 1875. By the time of the merger, medically oriented private nursing homes were rapidly being established in the United States, and the Ladies' Protection Society had become one of numerous institutions providing eldercare to a wide range of San Franciscans. While the consolidated organization, known as "The Heritage," continued to reflect the institution's history of service and has remained a prominent retirement facility, its significant associations with the social welfare mission of the Ladies' Protection and Relief Society ended during the changing landscape of healthcare and eldercare in the 1950s. As all additions to the main building were completed either in support of or after the merger in 1957, these additions do not contribute to the significance of the property as the location of an early and long-operating eldercare facility. Only the main building and early extant landscaping features constructed in 1925, the stone cottage constructed in 1928-1929, and other pre-1957 alterations contribute to the significance of the property under Criterion 1.

The Crocker Old People's Home was also an established welfare and eldercare institution in San Francisco by the time of its relocation and merger with the Ladies' Protection and Relief Society in 1957. However, neither the 1925 main building nor the 1957 addition appear to convey this institution's significant associations with social welfare dating to the late nineteenth and early twentieth centuries. Therefore, 3400 Laguna Street is not eligible for listing in the California Register under Criterion 1 for its associations with the Crocker Old People's Home.

In summary, the elements of the property at 3400 Laguna Street that represent the early history of the site (including the main building, front lawn, and the stone cottage) are the best existing expression of the San Francisco Ladies' Protection and Relief Society's important social welfare mission of the twentieth century; therefore, this property is significant under Criterion 1 (Events).

Criterion 2 (Persons)

The property at 3400 Laguna Street is not significant under Criterion 2 (Persons) for any close association with persons important to local, California, or national history. Although many persons who have made contributions to the city's civic and artistic history have spent their later years at 3400 Laguna Street, research has not uncovered any person who lived at 3400 Laguna Street whose

contributions meet the threshold that would make the property significant for its association with those individuals. Likewise, significance of association with a person is generally assigned to buildings that are the location of a person's productive life, and residents of 3400 Laguna Street have generally moved to the property to rest and relax in their later years. Overall, 3400 Laguna Street does not have any direct association with any historically significant persons, and is therefore not historically significant under Criterion 2 (Persons).

Criterion 3 (Architecture)

The property at 3400 Laguna Street is significant under Criterion 3 (Architecture) as a representative work of prominent architect Julia Morgan and for the overall early design of the property, including the contributing elements of the original landscaping and 1929 stone cottage, which evoke an English-inspired setting for the eldercare facility.

Julia Morgan has been widely recognized as an architect of merit and is considered one of the most significant women architects in the United States. Morgan was the first woman to graduate from the University of California with a degree in civil engineering, the first woman to receive a certificate from the École des Beaux-Arts, and the first female registered architect in California. During the course of her forty-year career, Morgan was commissioned to design hundreds of buildings, both residential and institutional. Working at a time when women's organizations were growing in prominence, Morgan was frequently chosen as the architect for women's institutional buildings, which comprise the majority of her non-residential work. In style, her work demonstrates flexibility in blending American and European historical influences with her Classically inspired Beaux-Arts training.

The main building at 3400 Laguna Street was designed by Morgan and completed in 1925, slightly more than midway through the most productive years of her practice. In design, the building shows her noted ability to blend utilitarian needs—in this case, residential eldercare—with sophisticated aesthetics, without compromising either. The building possesses high artistic values in its overall form, balanced massing, abundant exterior terra cotta ornament, and its Jacobethan Revival architectural style expressed in features such as canted bays and the central gabled parapet on the primary façade. Morgan's mastery of façade composition is evident through the primary façade's vertical and horizontal design hierarchies. Windows at the first and second stories are similarly arranged but subtly different in size, leading up to the relatively modest third-story dormers. Likewise, projections at the north and south façades are recessed from the front façade plane; the first-story canted bays to the right and left of center draw the eye to the central paired entrance, canted oriel bay, and upper gabled parapet. The arrangement of the front garden was also completed in 1925, and while no designer is credited with its design, it is likely that Morgan was

involved to some degree as the garden creates a transition zone between the main building and the street and defines the setting of the main building.

The cottage was constructed in 1928-1929 by a local designer/contractor named Ernest Higgins. Research did not reveal any information to indicate that Higgins would be considered an architect or builder of merit at the local, state, or national level. The design of the stone cottage is unique in San Francisco, especially as an example of residential architecture. It evokes a similar English-based architectural influence as that of the significant Julia Morgan Jacobethan Revival main building, which is not commonly found in San Francisco. The cottage exhibits a high level of unique craftsmanship and generally retains its original appearance, having undergone some alterations limited to window replacements, the addition of a square bay window at the west façade, and interior modifications. While the cottage is not individually eligible under Criterion 3, it does contribute to the overall significance of the site under this Criterion as a continuation of the English-inspired architectural setting and is a contributing element to the significance of the property.

The architectural significance of the property does not extend to the 1957 Warren C. Perry addition or the 1963 Gardner A. Daily addition. Perry has not been identified as an architect of merit for the city, despite his important role at the University of California and his status as a fellow of the AIA. His design for the 1957 addition to 3400 Laguna Street is simple and utilitarian in design, and was completed after his retirement in 1954. Overall, the design of Perry's addition does not embody the distinctive characteristics of a type, period, region, or method of construction, or possess high artistic values. Gardener A. Daily, on the other hand, is considered an architect of merit in San Francisco, but his 1963 addition is also a simple and utilitarian design, completed in the last few years of his career. Moreover, the two later additions to the 1963 addition, completed in 1986, further dilute any architectural significance that the 1963 addition might have held. The 1963 addition, despite its design by a locally prominent architect, does not embody the distinctive characteristics of a type, period, region, or method of construction, or possess high artistic values.

Overall, the property is individually eligible for the California Register under Criterion 3 as a work by prominent architect Julia Morgan and for its early twentieth century design. Contributing elements that support the significance of the property include the main building, original landscaping features of the front lawn, and the stone cottage. The later additions to the main building are not considered significant under Criterion 3 (Architecture). The presence of these additions does not impact the significance of the main building; a further discussion of the integrity of the main building is included in the following section.

Criterion 4 (Information Potential)

The "potential to yield information important to the prehistory or history of California" typically relates to archeological resources, rather than built resources. When California Register Criterion 4 (Information Potential) does relate to built resources, it is relevant for cases when the building itself is the principal source of important construction-related information. The analysis of the property at 3400 Laguna Street for eligibility under Criterion 4 is beyond the scope of this report.

PERIOD OF SIGNIFICANCE

The overall period of significance for the property at 3400 Laguna Street, under both Criterion 1 and Criterion 3, is 1925 to 1957, beginning with the construction of the main building and ending with the merger of the San Francisco Ladies' Protection and Relief Society and the Crocker Old People's Home.

INTEGRITY

In order to qualify for listing in any local, state, or national historic register, a property or landscape must possess significance under at least one evaluative criterion as described above and retain integrity. Integrity is defined by the California Office of Historic Preservation as "the authenticity of an historical resource's physical identity evidenced by the survival of characteristics that existed during the resource's period of significance," or more simply defined by the National Park Service as "the ability of a property to convey its significance."[50]

Page & Turnbull used established integrity standards outlined by the *National Register Bulletin: How to Apply the National Register Criteria for Evaluation,* to evaluate whether the subject property retains sufficient integrity to convey its historic significance. Seven variables, or aspects, that define integrity are used to evaluate a resource's integrity—location, setting, design, materials, workmanship, feeling, and association. A property must possess most, or all, of these aspects in order to retain overall integrity. If a property does not retain integrity, it can no longer convey its significance and is therefore not eligible for listing in local, state, or national registers.

The seven aspects that define integrity are defined as follows:

[50] California Office of Historic Preservation, *Technical Assistance Series No. 7: How to Nominate a Resource to the California Register of Historical Resources* (Sacramento: California Office of State Publishing, 4 September 2001) 11; U.S. Department of the Interior, National Park Service, *National Register Bulletin 15: How to Apply the National Register Criteria for Evaluation* (Washington, D.C.: National Park Service, 1995) 44.

Location is the place where the historic property was constructed or the place where the historic event occurred;

Setting addresses the physical environment of the historic property inclusive of the landscape and spatial relationships of the building(s);

Design is the combination of elements that create the form, plan, space, structure, and style of the property;

Materials refer to the physical elements that were combined or deposited during a particular period of time and in a particular pattern or configuration to form the historic property;

Workmanship is the physical evidence of the crafts of a particular culture or people during any given period in history or prehistory;

Feeling is the property's expression of the aesthetic or historic sense of a particular period of time; and

Association is the direct link between an important historic event or person and the historic property.

LOCATION

The property at 3400 Laguna Street retains integrity of location, as none of the buildings have been moved.

SETTING

The property's surrounding environment has not changed substantially to an extent that would compromise integrity of setting. The adjacent blocks to the west and north remain open space, and the surrounding blocks to the south and east consist of low-scale residential properties. Within the original grounds of the property, the setting has been somewhat affected by the accretion of additions and the removal of original gardens to the rear of the main building. However, at the primary façade and within the front yard, few changes to the original design have been made, and integrity of setting is not affected. When the building was constructed in 1925, the area to the east included extensive grounds, with pathways, mature vegetation, and gridded plantings, stretching the full depth of the lot from Bay Street through to Francisco Street. The stone cottage was constructed in 1928-1929, within the period of significance, and amplified the English-inspired design of the property while minimally impacting the original openness of the site due to its small footprint and

massing. Construction of the 1957 addition, marking the end of the property's period of significance, removed these extensive grounds. The remaining landscaped areas are divided into two courtyards, formally landscaped with fountains and other areas of hardscaping. These changes affect the setting of the property, yet are not considered to have a detrimental enough impact to undermine the main building's largely intact setting at its primary façade along Laguna Street.

DESIGN

The property at 3400 Laguna Street also retains integrity of design. The 1925 Julia Morgan-designed main building has undergone relatively few alterations. Known alterations include the enclosure of the construction of a penthouse, stair, and elevator stack within the identified period of significance; enclosure of the primary entry vestibule (with no impact to original material); construction of an adjoining addition at the north wing in 1957; and addition of a loading dock and associated metal awning at the north facade. Although the addition at the north wing necessitated the removal of small portions of the main building, the main building retains its overall design as completed by Julia Morgan in 1925. Features that remain and demonstrate Morgan's original design, include but are not limited to the strong symmetry of the primary façade, terra cotta ornament, fenestration configuration and materials, brick construction, and dormers. Additional features that contribute to the significance of the property, include the original landscape features of the front yard area, and the stone cottage to the northeast of the main building that was constructed in 1928-1929. These three elements retain their historic relationship and placement within the parcel, allowing the historic design of the property to be understood.

MATERIALS

The property retains integrity of materials through the presence of the overwhelming majority of the character-defining features of the main residence, including its brick façade and terra cotta ornament; the retention of the front yard as a planted area that provides a transition between the street and the main building; and the retention of the original materials of the stone cottage on the site.

WORKMANSHIP

3400 Laguna Street retains integrity of workmanship. Components of the original 1925 design of the property, including the construction of the main building and layout of the front garden, and the early addition of the stone cottage (completed in 1929) retain evidence of their original construction techniques. The main residence, in particular, illustrates period workmanship through its integration of terra cotta ornament, multi-lite metal frame windows, and use of complex building forms with canted bays, oriel windows, dormers, and a pediment dormer.

FEELING

The property's continued use as a care facility for the elderly, as well as its current landscaped grounds (although not strictly historic in character), support the property's integrity of feeling, allowing it to convey the peaceful atmosphere that characterized the property during its period of significance.

ASSOCIATION

3400 Laguna Street retains integrity of association, because it remains in use as an eldercare facility; the use for which it was designed and constructed.

Overall, despite additions and alterations, 3400 Laguna Street retains sufficient overall integrity to continue to convey its historic appearance and historic significance.

CHARACTER-DEFINING FEATURES

For a property to be eligible for national or state designation under criteria related to type, period, or method of construction, the essential physical features (or character-defining features) that enable the property to convey its historic identity must be evident. These distinctive character-defining features are the physical traits that commonly recur in property types and/or architectural styles. To be eligible, a property must clearly contain enough of those characteristics to be considered a true representative of a particular type, period, or method of construction, and these features must also retain a sufficient degree of integrity. Characteristics can be expressed in terms such as form, proportion, structure, plan, style, or materials.

The following character-defining features have been identified for the property at 3400 Laguna Street:

Main Building

- Overall regular massing and intersecting hipped roof
- U-shaped plan, consisting of central volume, north and south wings at east façade, and projections at north and south façades
- Structural brick exterior walls
- Slate roof shingles
- Symmetrical arrangement of front façade, with central gabled parapet
- Historic fenestration pattern, consisting of evenly spaced window openings with hierarchy among basement, first story and second story windows and upper dormer windows
- Projecting canted bays
- Hipped dormer windows at roof

- Operable, divided-lite windows retaining historic configurations
- Terra cotta details: window surrounds with vegetative motifs in segmental arches; decorative panels and entablatures at canted bays; belt course above second level windows; projecting cornice with buttons at eave; coping and finial at central gabled parapet; double arched door surround at primary entrance vestibule
- Arched ground-level door openings at ground level
- Stained glass windows at interior chapel
- Additional historic design features: narrow blind niche and recessed diamond and square details in brick
- Historic glazed doors within entrance vestibule
- Three brick chimneys
- Front double stairs with iron railing
- Towers and penthouse at east façade
- Rain catch baskets
- Historic features in publicly accessible interior areas include:
    - Tile floor
    - Central stairwell with trefoil railing
    - Fireplace mantel
    - Wood coffered ceiling

Front Lawn

- Iron fence on brick base along west, north, and south property lines
- Curvilinear pedestrian paths leading from front stairs to two gates along the Laguna Street fence, and two paths curving north and south from the main entrance; paths appear to have been resurfaced since the period of significance, thus circulation routes are character-defining rather than paving materials
- Lawns in front landscaped area

Stone Cottage

- One-story massing
- L-shaped footprint
- Steeply pitched hipped roof
- Rough stone exterior cladding
- Punched window openings with original wood sash casement and double hung windows

VII. CONCLUSION

Page & Turnbull finds that the property at 3400 Laguna Street appears to be eligible for listing in the California Register of Historical Resources as an individual resource. The property is significant under Criterion 1 for its significant associations with the San Francisco Ladies' Protection and Relief Society during the late nineteenth and first half of the twentieth centuries; and under Criterion 3 as an excellent example of institutional architecture designed by prominent architect Julia Morgan in 1925, with a 1929 stone cottage that was a complementary early addition to the property and further amplified the peaceful, English-inspired design by Morgan. The property's period of significance is 1925 to 1957, beginning with the development of the property and construction of the main building, and ending with the merger between the Ladies' Protection and Relief Society and another eldercare institution.

The property has experienced several interventions—most notably rear additions to the main building that were constructed in 1957 (designed by Warren C. Perry) and 1963 (designed by Gardner A. Dailey). The two rear additions do not contribute to the significance of the property either architecturally under Criterion 3, or in association with the Ladies' Protection and Relief Society under Criterion 1. While the additions are conspicuous changes within the site, Page & Turnbull finds that the original main building, the stone cottage, and the landscaped front lawn retain sufficient integrity to convey the historic and architectural significance of the property. Therefore, the property at 3400 Laguna Street appears to be a historic resource for the purposes of CEQA review.

VIII. REFERENCES

Published Works & Reports

Bardell, Robert. "The Presidio Road," *The Argonaut* 23 (Winter 2012).

Boutelle, Sara Holmes. *Julia Morgan Architect*. New York: Abbeville Press Publishers, 1995.

California Art and Architecture (July 1929).

California Office of Historic Preservation. *Technical Assistance Bulletin No. 7: How to Nominate a Resource to the California Register of Historical Resources*. Sacramento: California Office of State Publishing, September 4, 2001.

California Office of Historic Preservation. *Technical Assistance Bulletin No. 8: User's Guide to the California Historical Resource Status Codes & Historic Resources Inventory Directory.* Sacramento: California Office of State Publishing. November 2004. Accessed October 22, 2018, http://ohp.parks.ca.gov/pages/1069/files/tab8.pdf.

Delehanty, Randolph Stephen. *San Francisco Parks and Playground, 1839 to 1990: The History of Public Good in One North American City (Volumes I and II)*. [Thesis.] Cambridge: Harvard University, 1992.

Haber, Carole. *Beyond Sixty-Five: The Dilemma of Old Age in America's Past*. Cambridge: Cambridge University Press, 1983.

"Is there a Bay Area Style?" *Architectural Record* 105 (May 1949).

James, Cary. *Julia Morgan*. New York: Chelsea House Publishers, 1990.

Longstreth, Richard W. *Julia Morgan – Architect*. Berkeley: Architectural Heritage Association, 1986.

Olson, Laura Katz. *The Not-So-Golden Years: Caregiving, the Frail Elderly, and the Long-Term Care Establishment*. Lanham, MD: Rowman & Littlefield, 2003.

Richards, Rand. *Historic San Francisco: A Concise History and Guide.* Heritage House Publishers, San Francisco, 2001 .

San Francisco Planning Department. *Preservation Bulletin No. 9 – Landmarks*. San Francisco: San Francisco Planning Department, January 2003.

VerPlanck, Christopher. "From Mud Flats to Marina: Building a San Francisco Neighborhood." Heritage News 35 (Summer 2007).

-----. "Marina District Development Takes Off." *Heritage News* 35 (Fall 2007).

Wilson, Mark Anthony. *Julia Morgan Architect of Beauty*. Santa Barbara: Gibbs Smith, 2007.

Wollenberg, Charles. *Golden Gate Metropolis: Perspectives on Bay Area History.* Berkeley, California: Institute of Governmental Studies, University of California, Berkeley, 1985.

Public Records

San Francisco Assessor-Recorder's Office, deed records.

San Francisco Department of Building Inspection, building permit applications

San Francisco Planning Department. "Landmark Designation Report, University Mound Old Ladies' Home, 350 University Street." May 20, 2015.

Internet Sources

"About Us." Heritage on the Marina. Accessed February 10, 2023, https://heritageonthemarina.org/about-heritage-on-the-marina.

Archibald, Robert. "Indian Labor at the California Missions." *The Journal of San Diego History,* Spring 1978, v. 24, no. 2. Accessed February 10, 2023, https://sandiegohistory.org/journal/1978/april/labor/

"Biographical Note: Inventory of the Gardener A. Dailey Collection, 1923-1979." University of California at Berkeley Environmental Design Archives. Accessed February 2023. http://www.oac.cdlib.org/findaid/ark:/13030/kt396nb7zw/admin/#bioghist-1.8.4.

California Historical Society. "Finding Aid to the San Francisco Ladies' Protection and Relief Society Records MS 3576." *Online Archive of California.* Accessed February 13, 2023, https://oac.cdlib.org/findaid/ark:/13030/kt338nf0rf/?query=Ladies%E2%80%99+Protection+and+Relief+Society "Julia Morgan, 2014 AIA Gold Medal Recipient." American Institute of Architects. Accessed February 10, 2023, https://www.aia.org/awards/7046-gold-medal.

"Lowe, William, Jr., House, Woodside, CA." Pacific Coast Architecture Database. Accessed February 10, 2023. https://pcad.lib.washington.edu/building/715/.

Parry, David. "Warren Charles Perry." The Encyclopedia of San Francisco. Accessed July 2015. http://sfhistoryencyclopedia.com/articles/p/perryWarren.html.

Sanborn Map Company. Various years. Accessed February 2023. Via the San Francisco Public Library.

San Francisco City Directories. Accessed February 2023. http://archive.org.

San Francisco Chronicle. Accessed July 2015. http://www.newsbank.com.

San Francisco Property Information Map. Accessed July 2015. http://www.sfassessor.org/property-information/homeowners/property-search-tool.

San Francisco Public Library Historical Photograph Collection. Accessed February 2023. http://sfpl.org.

"Warren Charles Perry, Architecture: Berkeley." University of California: In Memorium. Accessed February 2023. http://texts.cdlib.org/view?docId=hb1j49n6pv;NAAN=13030&doc.view=frames&chunk.id=div00073&toc.depth=1&toc.id=&brand=oac4.

IX. APPENDICES

BUILDING PERMIT APPLICATIONS

Front and back pages of building permit applications currently on file with the San Francisco Department of Building Inspection. Cancelled and expired permits are not included.



PAGE&TURNBULL

Imagining change in historic environments through
design, research, and technology

417 S. HILL STREET, SUITE 211 LOS ANGELES, CALIFORNIA 90013 TEL 213.221.1200
2600 CAPITOL AVENUE, SUITE 120 SACRAMENTO, CALIFORNIA 95816 TEL 916.930.9903
170 MAIDEN LANE, 5TH FLOOR SAN FRANCISCO, CALIFORNIA 94108 TEL 415.362.5154
75 E. SANTA CLARA STREET, SUITE 900 SAN JOSE, CALIFORNIA 95113 TEL 408.535.7055

SUB-APPENDIX C.2
3400 LAGUNA STREET HISTORIC RESOURCE REVIEW

This page intentionally left blank

San Francisco Planning

49 South Van Ness Avenue, Suite 1400
San Francisco, CA 94103
628.652.7600
www.sfplanning.org

HISTORIC RESOURCE REVIEW

Record No.:	**2022-009819ENV**
Project Address:	**3400 LAGUNA ST**
Zoning:	RM-1 RESIDENTIAL- MIXED, LOW DENSITY Zoning District 40-X Height and Bulk District
Block/Lot:	0471/003
Staff Contact:	Justin Greving – (628)652-7553 Justin.greving@sfgov.org

HISTORIC RESOURCE IDENTIFICATION

PROJECT SPONSOR SUBMITTAL

To assist in the evaluation of the proposed project, the Project Sponsor has submitted a:

☒ Consultant-prepared Historic Resource Review report
Prepared by: Page & Turnbull, *3400 Laguna Historic Resource Evaluation, Part 1* (HRE Part 1, February 16, 2023)
Staff consensus with Consultant's report: ☒ **Agree** ☐ **Disagree**

Additional Comments: Planning Staff concurs with report provided by Page & Turnbull but disagrees with the determination that the small stone caretaker's cottage on the site isn't individually eligible for listing in the California Register. The Planning Department finds the Caretaker's Cottage to be individually eligible for listing in the California Register. See **Step A: Significance** for more information.

BUILDINGS AND PROPERTY DESCRIPTION

The site at 3400 Laguna is a 68,005 square foot parcel that encompasses a half block bounded by Laguna Street to the west, Bay Street to the north, and Francisco Street to the south. East of the site are 3- and 4-story single-family homes and apartment buildings. The following description provides an overview of prominent site features, buildings, and additions.[1] The most prominent building on the site, the Julia Morgan Building, was constructed in the Jacobethan Revival style by architect of merit Julia Morgan for the Ladies' Protection and Relief Society in 1925. The Julia Morgan Building is a three-story brick building with a U-shaped plan consisting of a central volume and north and south wings extending from the east façade and projections at the north and south elevations. The building has a hipped roof covered in slate shingles and a regular arrangement of dormers and three prominent brick chimneys. The building is unified in its appearance with decorative terracotta detailing that is visible in the arched window surrounds, on the

[1] Pp. 5-28 of the HRE Part 1 provides a detailed description of the site.

second story cornice line, above the canted first floor bays, and on the engaged columns of the main entrance. The Julia Morgan building has a highly symmetrical primary façade that faces west towards Laguna and features seven bays arranged around a centered gable parapet. Two canted one-story bays frame the main entrance to the building which is itself centered below a projecting second story canted bay window. The double arched door surround is the main entrance to the building and is embellished with the same terracotta detailing found on the rest of the façade. The Julia Morgan Building has a generous setback that contains an ornamental lawn with symmetrical curvilinear pathways that lead to the primary entrance. A low brick base with a simple iron fence frames the lawn and wraps around the north and south boundaries of the property.

The Julia Morgan Building is connected to three interconnected additions on the site that are sometimes referred to as separate buildings. For the purposes of this report, the three additions, the Perry Building, Perry Building Connector, and Health Center, are referred to as separate buildings even though they are all interconnected additions to the Julia Morgan Building. The northwest rear elevation of the Julia Morgan Building connects with the two-story rectangular Perry Building Connecter constructed in 1957 that runs parallel to Bay Street. The Perry Building Connecter in turn connects to the four-story Perry Building also constructed in 1957 that runs north south along the eastern end of the property. Lastly, the one-story Health Center constructed in 1963 and 1987 connects with the Perry Building towards the southeast and runs along Francisco Street. There is one other building on the site, the freestanding one-story stone Caretaker's Cottage constructed in 1928-1929 located in the northeast corner of the site just north of the Perry Building. There are three prominent landscaped areas on the site: the front lawn, center courtyard, and the rear courtyard. As mentioned above, the front lawn is located along Laguna Street and creates a generous setback for the primary façade of the Julia Morgan Building. The central courtyard is a paved and landscaped courtyard located in the center of the site framed by the rear elevations of the Julia Morgan Building, the Perry Building and Perry Building Connector, and the Health Center. East of the Perry Building is the rear courtyard that is made up of the rear yards of the adjacent properties to the east.

PRE-EXISTING HISTORIC RATING / SURVEY

☒ Category A – Known Historic Resource, per: Historic Resource Evaluation Response (April 19, 2017), prepared by Shelley Caltagirone for 2016-012057ENV, based on findings of the Historic Resource Evaluation (August 28, 2015), prepared by Page & Turnbull.
☐ Category B – Age Eligible/Historic Status Unknown
☐ Category C – Not Age Eligible / No Historic Resource Present, per: _____

Adjacent or Nearby Historic Resources: ☒ Yes ☐ No

The subject property is located in the Marina and occupies the western half of a residential block situated between Laguna and Octavia streets to the west and east, respectively, and Bay and Francisco streets to the north and south, respectively. Across Laguna Street to the west, 3400 Laguna faces the Moscone Recreation Center that contains the article 10 designated Marina Branch Library and the California Register-eligible Funston bleachers that are identified as contributors to the discontiguous Midcentury Recreation historic district. The Marina Branch Library is significant as an article 10 landmark under National Register Criterion A (events) as reflection of principles of the modern public library promoted by the American Library Association after World War II and under Criterion C (design/construction) as it represents an innovative

example of midcentury modern design in Northern California.[2] Although the entire parcel is designated as an article 10 landmark, the library building itself faces Chestnut Street and has no visual, aesthetic, or historical relationship with the subject property. The Funston bleachers are contributors to the California Register-eligible discontiguous Midcentury Recreation historic district. This historic district is eligible under California Register Criterion 1 (events) for its association with the 1947 bond measure that funded the single largest expansion of recreational facilities in San Francisco's history, and under Criterion 3 (architecture) for embodying the distinctive characteristics of a type and period, and as exemplifying the work of an architect of merit, William Gladstone Merchant.[3] The Funston bleachers are situated closer to the subject property along Bay Street but also do not have any meaningful visual or historic relationship with the subject property.

North of the subject property across Bay Street is the Fort Mason historic district and the Fort Mason Port of Embarkation historic district, two historic districts that are listed in both the National and California registers. The Fort Mason historic district is listed in the National Register under Criterion A for its role as a coastal defense for the Bay as far back as the Spanish and Mexican administration of Alta California up to the post-Spanish American War, and under Criterion C as a collection of military structures spanning over 100 years with various architectural styles reflecting the evolution of this army post.[4] When originally listed in the National Register in 1972, the Fort Mason historic district boundaries were focused on the earliest properties located at the northeast corner of the Fort Mason site. However, in 1979 the nomination was amended to include additional properties and the boundaries were expanded to encompass the entire Fort Mason property west of Van Ness Avenue, north of Bay Street, east of Laguna Street, and south of the San Francisco Bay. Although the 1979 nomination does not specifically mention a period of significance, contributing properties are constructed between 1855 and 1942. The Fort Mason Port of Embarkation historic district is a smaller collection of buildings near the water that is listed in the National Register and is also a National Historic Landmark eligible under Criterion A as one of the most important ports of embarkation for soldiers and supplies during World War II. Contributing features to the Port of Embarkation historic district include buildings, sites, and features along the waterfront and the period of significance spans from 1912-1945.

Planning department staff determined there are no adjacent historic resources immediately south or east of the project site. 3400 Laguna occupies the western half of a residential block situated between Laguna and Octavia streets to the west and east, respectively, and is surrounded to the east and south by residential properties that were constructed after closure of the 1915 Panama Pacific International Exposition. The remainder of the block contains a mixture of two- and three-story single-family homes and multifamily apartment buildings constructed during the mid-1920s designed in simplified vernacular variations of Mediterranean Revival, Mission Revival, and Edwardian architectural styles. A similar pattern of three- and four-story single-family homes and multifamily apartment buildings from the same construction period is found to the south and east of the subject property along Francisco and Octavia streets. Although there is some similarity between the nearby buildings given their close construction dates, planning department staff previously determined the residential blocks immediately adjacent to the subject property do not contain sufficient architectural merit or aesthetic cohesion to be considered a historic district given the variety of architectural styles and numerous additions and alterations that affect the cohesiveness of the neighborhood.[5] Although a portion of the Marina to the west of the subject property has California Register-

[2] Marina Branch Library Article 10 designation, Landmark No. 262, https://sfplanninggis.org/docs/landmarks_and_districts/LM262.pdf
[3] Excerpt from the Cayuga Clubhouse Historic Resource Evaluation prepared by Page and Turnbull, October 25, 2010,
[4] Erwin Thompson, "Fort Mason National Register of Historic Places Inventory – Nomination Form" Section 8, Significance.
[5] Case no. 2013.0874E, "Historic Resource Evaluation Response 1503-1507 Francisco Street," December 20, 2013.

eligible historic districts, Buchanan Street marks the eastern boundary of these districts and the immediate area surrounding the subject property does not rise to the level of architectural significance such that it would be part of the nearby historic district.[6]

CEQA HISTORICAL RESOURCE(S) EVALUATION

Step A: Significance

Individual Significance	Historic District / Context Significance
Property is individually eligible for inclusion in a California Register under one or more of the following Criteria: **Criterion 1** - Event: ☒ Yes ☐ No **Criterion 2** - Persons: ☐ Yes ☐ No **Criterion 3** - Architecture: ☒ Yes ☐ No **Criterion 4** - Info. Potential: ☐ Yes ☐ No Period of Significance: Julia Morgan Building: 1925-1957 (Criterion 1), 1925 (Criterion 3); Caretaker's Cottage: 1928-1957 (Criterion 1), 1928-1929 (Criterion 3)	Property is eligible for inclusion in a California Register Historic District/Context under one or more of the following Criteria: **Criterion 1** - Event: ☐ Yes ☒ No **Criterion 2** - Persons: ☐ Yes ☒ No **Criterion 3** - Architecture: ☐ Yes ☒ No **Criterion 4** - Info. Potential: ☐ Yes ☒ No Period of Significance: _____ ☐ Contributor ☐ Non-Contributor ☒ N/A

Analysis:
The planning department determined the historic resource status of the property at 3400 Laguna Street in the HRER Part I dated April 19, 2017 for Case No. 2016-012057ENV. This HRER Part I found the original Julia Morgan-designed building at 3400 Laguna Street to be eligible for listing in the California Register under Criterion 1 for its association with the San Francisco Ladies' Protection and Relief Society, one of the longest operating, if not the single longest operating eldercare service organizations in San Francisco, and under Criterion 3 as a representative work of architect of merit Julia Morgan, with a design that blends utilitarian needs with sophisticated aesthetics. The period of significance under Criterion 1 is 1925-1957, beginning with construction of the building and ending with the merger of the San Francisco Ladies' Protection and Relief Society and the Crocker Old People's Home. The period of significance under Criterion 3 is 1925, the year the building was completed.

The department determined that none of the later alterations, including the 1957 Perry Building and Perry Building Connecter, and 1963 and 1987 Health Center, contribute to the site. Furthermore, despite these alterations the site retains all seven aspects of integrity. This determination provided a list of character-defining features that has since been updated and is described in more detail below.

The updated HRE dated February 16, 2023 prepared by Page & Turnbull provided new information and an evaluation of the Caretaker's Cottage on the northeast corner of the site. Page & Turnbull determined a more accurate date of construction for the caretaker's cottage of 1928-1929 and identified a local Berkeley designer and contractor Ernest Higgins as the builder. Page and Turnbull did not find the Caretaker's Cottage rose to the level of being individually eligible even if it contributed to the character of the property.

The planning department finds the Caretaker's Cottage is of sufficient architectural merit and unique for San Francisco as an English-inspired stone cottage such that it is individually eligible for listing in the California Register under Criterion 3 as an excellent and unique example of this architectural style. The period of significance under

[6] More information about the Marina historic districts can be found at 2016-013786ENV, "Historic Resource Evaluation Response, 465 Marina Boulevard," December 4, 2017, and 2012.1448E "Historic Resource Evaluation Response, 1410 Jefferson Street," May 13, 2013.

Criterion 3 is 1928-1929 and reflects the Caretaker's Cottage date of construction. The structure is also eligible under Criterion 1 for its association with San Francisco Ladies' Protection and Relief Society with a period of significance from 1928-1957.

The department is still in concurrence with the findings that none of the additions or alterations to the site constructed on or after 1957 have taken on significance. The alterations that are not significant include the Perry Building and Perry Building Connector (the L-shaped two- and four-story addition designed by Warren C. Perry constructed in 1957), and the Health Center (the 1-story addition designed by Gardner Daily constructed in 1963, with later alterations designed by Spencer & Associates added in 1987), the central courtyard and fountains located east of the original Julia Morgan Building, and the rear courtyard located east of the Perry Building. The only significant landscape feature on the property is the front lawn that is considered a significant landscape feature of the Julia Morgan Building.

Therefore, the site at 3400 Laguna contains two individually eligible buildings and one important landscape feature, the Julia Morgan Building and front lawn, and the Caretaker's Cottage.

Step B: Integrity

The subject property has retained or lacks integrity from the period of significance noted in Step A:

Location:	☒ Retains	☐ Lacks	**Setting:**	☒ Retains	☐ Lacks
Association:	☒ Retains	☐ Lacks	**Feeling:**	☒ Retains	☐ Lacks
Design:	☒ Retains	☐ Lacks	**Materials:**	☒ Retains	☐ Lacks
Workmanship:	☒ Retains	☐ Lacks			

Analysis:
In order to be determined eligible for listing in the California Register, the subject property must be found to retain sufficient integrity to convey its historic significance under Criterion 1 and 3. Planning staff concurs with the consultant report's findings that the property retains all seven aspects of integrity. A brief summary of how the subject property meets the seven aspects of integrity is included here (see a more detailed analysis on pp. 69-71 of the HRE Part 1). The subject property retains integrity of location as none of the buildings have moved since they were constructed. The subject property retains integrity of setting as the surrounding environment has not changed such that it would compromise the integrity of setting with the adjacent blocks to the west and north still open space and the adjacent blocks to the south and east consisting of three- and four-story multifamily apartments and single-family homes. Within the subject property, the new additions that took place after 1957 removed some of the grounds to the rear of the Julia Morgan Building somewhat affecting the setting through the accretion of additions and removal of original gardens to the rear of the Julia Morgan Building. However, while these alterations affected somewhat the setting, the Julia Morgan Building's primary façade and the front lawn remain largely intact. The property retains integrity of design as the Julia Morgan Building and the Caretaker's Cottage have both undergone few alterations. The subject property retains integrity of materials through the retention of the majority of character-defining features of the Julia Morgan Building and Caretaker's Cottage. The subject property retains integrity of workmanship due to the retention and layout of the front lawn along with the construction type of the Julia Morgan Building and Caretaker's Cottage. Of particular note is the fine terracotta ornament of the Julia Morgan Building and the stonework of the Caretaker's Cottage. The subject property also retains integrity of feeling and association through its continued use as a care facility for the elderly with its historic buildings and front lawn that convey a peaceful atmosphere.

Therefore, the subject property retains integrity and is a historic resource individually eligible for listing in the California Register under Criterion 1 and 3.

Step C: Character Defining Features

Based on the above findings, the character-defining features of the subject property include the following:

Julia Morgan Building

- Overall regular massing and intersecting hipped roof
- U-shaped plan, consisting of central volume, north and south wings at east façade, and projections at north and south façades
- Structural brick exterior walls
- Slate roof shingles
- Symmetrical arrangement of front façade, with central gabled parapet
- Historic fenestration pattern, consisting of evenly spaced window openings with hierarchy among basement, first story and second story windows and upper dormer windows
- Projecting canted bays
- Hipped dormer windows at roof
- Operable, divided-lite windows retaining historic configurations
- Terra cotta details: window surrounds with vegetative motifs in segmental arches; decorative panels and entablatures at canted bays; belt course above second level windows; projecting cornice with buttons at eave; coping and finial at central gabled parapet; double arched door surround at primary entrance vestibule
- Arched ground-level door openings
- Stained glass windows at interior chapel
- Additional historic design features: narrow blind niche and recessed diamond and square details in brick
- Historic glazed doors within entrance vestibule
- Three brick chimneys
- Front double stairs with iron railing
- Towers and penthouse at east façade
- Rain catch baskets
- Historic features in publicly accessible interior areas include:
  - Tile floor
  - Central stairwell with trefoil railing
  - Fireplace mantel
  - Wood coffered ceiling

Front Lawn of the Julia Morgan Building

- Iron fence on brick base along west, north, and south property lines
- Curvilinear pedestrian paths leading from front stairs to two gates along the Laguna Street fence, and two paths curving north and south from the main entrance; paths appear to have been resurfaced since the period of significance, thus circulation routes are character-defining rather than paving materials
- Lawns in front landscaped area

Caretaker's Cottage

- One-story massing
- L-shaped footprint
- Steeply pitched hipped roof

- Rough stone exterior cladding
- Punched window openings with fixed and casement windows

CEQA HISTORIC RESOURCE DETERMINATION

☒ Individually-eligible Historical Resource Present
☐ Contributor to an eligible Historical District / Contextual Resource Present
☐ Non-contributor to an eligible Historic District / Context / Cultural District
☐ No Historical Resource Present

NEXT STEPS

☒ Project Evaluation Required (see evaluation below)
☐ Categorically Exempt, consult:
☐ Design Advisory Team
☐ Current Planner

Historic Resource Identification: Principal Preservation Planner Review

Signature: Allison Vanderslice Date: 2/27/2024

Allison Vanderslice, *Principal Preservation Planner*
CEQA Cultural Resources Team Manager, Environmental Planning Division

CC: Jeff Horn, *Senior Current Planner*
Team 1-2, Current Planning Division

Megan Calpin, *Senior Environmental Planner*
Environmental Planning Division

Project Evaluation

Proposed Project:		Per Drawings Dated:
☒ **Demolition / New Construction**	☐ **Alteration**	1/10/2024

PROJECT DESCRIPTION

The proposed project would include interior renovation and exterior restoration of the three-story Julia Morgan Building. The proposed project would demolish portions of the existing additions on site including the two-story Perry Building Connector, and the one-story Health Center, and construct two new additions (the Bay Building and Francisco Building) in approximately the same locations as the demolished additions.[7] The four-story Bay Building would be an addition to the Julia Morgan Building and similar to the Perry Building Connector would connect directly with the north wing of the Julia Morgan Building but would have a larger footprint. The four-story Francisco Building would replace the Health Center and would connect directly with the Perry Building. The project would include renovation of the other buildings and additions on the site, including renovation and exterior additions to the four-story Perry Building, rehabilitation of the Julia Morgan Building and interior renovation of the Caretaker's Cottage. The center courtyard would be remodeled while the rear courtyard and front lawn would not change. The new additions and alterations to the existing additions would all still be interconnected as all existing structures (except the Caretaker's Cottage), are today. The Caretaker's Cottage would remain a standalone building on the site. The new additions would collectively contain approximately 58,382 square feet of institutional use and would each be 40 feet tall (with an additional 10 feet for the elevator penthouse).

PROJECT EVALUATION

The proposed project's conformance with the Secretary of the Interior's Standards:					
Standard 1 –Minimal Change:	☒ Yes	☐ No	☐ N/A	**Standard 6** – Repairment:	☒ Yes ☐ No ☐ N/A
Standard 2 –Maintain Character:	☒ Yes	☒ No	☐ N/A	**Standard 7** – Treatments:	☒ Yes ☐ No ☐ N/A
Standard 3 –Avoid Conjecture:	☒ Yes	☐ No	☐ N/A	**Standard 8** – Archeology:	☒ Yes ☐ No ☐ N/A
Standard 4 –Acquired Significance:	☒ Yes	☐ No	☐ N/A	**Standard 9** – Compatibility:	☒ Yes ☒ No ☐ N/A
Standard 5 –Building Techniques:	☒ Yes	☐ No	☐ N/A	**Standard 10** – Reversibility:	☒ Yes ☐ No ☐ N/A

Standard 1 - A property shall be used for its historic purpose or be placed in a new use that requires minimal change to the defining characteristics of the building and its site and environment.

The proposed project does not propose a change in use and the existing facility will continue to be a residential care retirement community as it has been since opening in 1925. Aside from some minor repairs to the Julia Morgan Building, the proposed project does not require changes to the building's character-defining features in order to maintain its continued use as a nursing care facility. Furthermore, even if it is necessary to use a different primary entrance to meet ADA requirements given the slope of the pathways leading up to the Julia Morgan Building, the center entrance to the Julia Morgan Building will retain its appearance as a main entrance to the facility and will still function as an entrance.

[7] The three interconnected additions to the Julia Morgan Building are all referred to as "buildings" for the sake of clarity even though they are not separate buildings on the site.

Therefore, the proposed project is in conformance with Standard 1.

Standard 2 - The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.

The proposed project will change the character of the property by constructing additions on the site that are taller and have larger footprints that the existing additions. The renovation and exterior addition to the Perry Building will have a minimal change on the overall features and spaces that characterize the property because for the most part they will modify this non-historic addition that is located along the western edge of the site. The Perry Building is the addition behind the Julia Morgan Building located along the rear of the property in a location that has minimal effect on the Julia Morgan Building. From Laguna Street the Perry Building is almost completely obscured by the Julia Morgan Building. Therefore, alterations and additions to the Perry Building will affect the setting minimally due to its existing location at the site's eastern edge at the rear of the property.

Construction of the new Bay Building in the approximate location of the Perry Building Connector will cause some alterations to the overall character of the property due to it being taller and having a larger footprint than the addition it will replace (Attachment 2: Heritage on the Marina, Site line studies of proposed project prepared by HKS, November 6, 2023, view H). The four-story massing of the Bay Building will be taller than the existing two-story massing of the Perry Building Connector and will therefore be more visually prominent on the site. Additionally, while the north elevation of the Julia Morgan Building and the Perry Building Connecter are aligned with each other, the Bay Building will have a larger footprint and its north elevation will project further north towards Bay Street. In order to provide some space between the massing the of Bay Building and the Julia Morgan Building, a glass hyphen that is slightly recessed from the north elevation of the Julia Morgan Building will provide a separation between the two buildings. As described below, a mitigation measure will require coordination with planning department preservation staff on the details of the glass separation to ensure the connection is sensitive to the brickwork, is visually transparent, and incorporates a slight reveal to as to give a slight aesthetic separation from the Julia Morgan Building.

The biggest change in the character of the property will take place along the southern portion of the site where the one-story Health Center is currently located. Demolition of the one-story Health Care Center and construction of the four-story Francisco Building will alter somewhat the setting of this portion of the site because the four-story massing will be a large new structure near the three-story Julia Morgan Building (Attachment 2: views A and B). However, the massing of the new Francisco Building will be set back from Laguna Street further than the existing Health Center so as to almost be aligned with the rear roof gable of the Julia Morgan Building's south elevation projection. Pushing this taller massing of the Francisco Building farther east means that the primacy of the Julia Morgan Building will be maintained. Although the Francisco Building will be taller than the Health Center it will still have a generous setback from Laguna Street and will be spaced apart from the Julia Morgan Building.

Despite these alterations to the property that will cause some changes to some of the features and spaces that characterize the property overall, the most prominent views of the Julia Morgan Building will only be slightly affected (Attachment 2: views D, E, F). The character-defining front lawn will remain intact, as will the overall massing and configuration of the Julia Morgan Building. Additionally, the new additions and alterations will connect with the Julia Morgan Building in the location already altered by the Perry Building Connector. Therefore, the character-defining features related to the Julia Morgan Building's overall form will

remain intact including its regular massing and intersecting fixed roof, U-shaped plan with north and south wings, not to mention all the decorative detailing on all elevations.

Therefore, there are elements of the proposed project that are in conformance with Standard 2 but other elements of the project that aren't entirely in conformance with this standard.

Standard 3 - Each property shall be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or architectural elements from other buildings, shall not be undertaken.

The proposed project does not propose any alterations to the identified character-defining features of the Julia Morgan Building or the Caretaker's Cottage that would be conjectural or would incorporate architectural elements from other buildings. The design of the new construction will not give the impression of a false sense of historical development and will be understood as contemporary additions.

Therefore, the proposed project is in conformance with Standard 3.

Standard 4 - Most properties change over time; those changes that have acquired historic significance in their own right shall be retained and preserved.

The subsequent additions to the subject property that were added over time have been evaluated and determined to not have taken on significance. Both the Perry Building and Perry Building connector, and the Health Center do not contribute to the significance of the subject property. Additionally, the central courtyard and fountains located east of the Julia Morgan Building and the rear courtyard located east of the Perry Building also have not taken on significance and are non-contributing features of the subject property. Therefore, demolition of the Perry Building Connecter and Health Center, and alteration and addition to the Perry Building and central courtyard is in conformance with Standard 4 because these portions of the site have not taken on significance.

The only part of the property that has taken on significance since the home originally opened in 1925 is the Caretaker's Cottage that was constructed in 1928-1929. The proposed project will retain the Caretaker's Cottage in its existing location and all its associated character-defining features will not be altered. The portions of the property that have taken on significance over time will be retained and preserved.

Therefore, the proposed project is in conformance with Standard 4.

Standard 5 - Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a historic property shall be preserved.

A number of character-defining features of the Julia Morgan Building and Caretaker's Cottage reflect the distinctive features, finishes, and construction techniques that characterize the property. The distinctive features of the Julia Morgan Building include the structural brick exterior walls, slate roof shingles, operable divided-lite windows (including stained glass windows in the ground floor chapel area), terra cotta details, among others. Other distinctive features and finishes of the site include the iron fence on a brick base along the front lawn and the rough stone exterior cladding of the Caretaker's Cottage. The proposed project will retain and repair as necessary the distinctive features described in the list of character-defining features, and

will include any necessary repairs as part of the preservation treatment plan to be reviewed and approved by planning department preservation staff.

Therefore, the proposed project is in conformance with Standard 5.

Standard 6 - Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence.

As part of the proposed project the Julia Morgan Building will see some exterior repairs to the windows and brickwork. As described below, a mitigation measure will require coordination with planning department preservation staff to ensure the distinctive historic features will be repaired rather than replaced. This mitigation measure will require the project sponsor to submit a preservation treatment plan for the repair of distinctive features to planning department preservation staff for review and approval.

Therefore, the proposed project is in conformance with Standard 6.

Standard 7 - Chemical or physical treatments, such as sandblasting, that cause damage to historic materials shall not be used. The surface cleaning of structures, if appropriate, shall be undertaken using the gentlest means possible.

The proposed project does not anticipate use of any chemical or physical treatments that would cause damage to any historic materials.

Therefore, the proposed project is in conformance with Standard 7.

Standard 8 - Significant archeological resources affected by a project shall be protected and preserved. If such resources must be disturbed, mitigation measures shall be undertaken.

Archeological resources will be treated as part of a standard archeological mitigation measure outlined in the Initial Study to ensure that if archeological resources are disturbed, mitigation measures shall be undertaken.

Therefore, the proposed project is in conformance with Standard 8.

Standard 9 - New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.

The proposed project includes the demolition and alteration to several existing buildings on the property that function as additions to the Julia Morgan Building but have not taken on significance. Demolition of the Perry Building Connector and Health Center, and renovation and additions to the existing Perry Building does not cause the demolition of any historic materials that characterize the historic property.

In general, the proposed project will include additions and alterations to the overall site that are in locations that do not affect the integrity of the property and its environment. New construction is limited to locations where there have already been alterations, such as in the locations east and south of the Julia Morgan Building where there are currently non-historic additions and non-historic courtyards. The footprint of the new Bay Building will encroach in some areas that are currently occupied by the central courtyard in the middle of the property and the parking lot to the north of the property. Both areas are not considered character-defining features and do not contribute to the significance of the property. In a similar fashion, the new Bay Building will be located roughly on the footprint of the Health Center on a part of the property that has not taken on significance.

The new construction will connect with the Julia Morgan Building only at the point where there is already a connection, at the rear eastern end of the northern wing. This allows the retention of the Julia Morgan Building's character-defining "U-shaped" plan. Therefore, the footprint of the new construction is limited to areas that allows for the retention of the most important and historically significant portions of the site, including the Julia Morgan Building and its front lawn, and the Caretaker's Cottage.

Modifications to the Julia Morgan Building include some removal of non-historic features that currently detract from the character of the north elevation. The HVAC equipment and loading dock that projects from the Julia Morgan Building's north elevation will be removed.

The height of the new Francisco Building will be taller than the existing Health Center and will therefore be a four-story mass where there is currently only one story. The height of the new four-story Francisco Building will roughly match the height of the roof peak of the Julia Morgan Building. This additional height and massing will block somewhat the view of the Julia Morgan Building from certain vantage points along Francisco Street and will impose somewhat on the setting of the Julia Morgan Building at the southern portion of the property. However, it should be noted that the footprint of the new Bay Building does not extend as far west into the property as the existing Health Center and is instead aligned approximately with the rear roof gable of the south façade projection. As mentioned in Standard 2, this further setback on the new building will allow for increased visibility of the southern elevation of the Julia Morgan Building in some areas although the height of the new building presents a new mass in this location.

On a similar note, the massing of the new Bay Building at the northern side of the property extends into the existing parking lot. While this does not directly affect any of the identified character-defining features of the Julia Morgan Building, because the Bay Building is slightly taller than the roof peak of the Julia Morgan Building, this new massing does affect the setting of the original building in this location because it starts to encroach on the Julia Morgan Building's primacy from certain vantage points. To reduce the imposition of Bay Building's massing on the Julia Morgan Building, a two-story glass connecting hyphen will connect the Bay Building and the Julia Morgan Building. The materials, massing, and location of this glass hyphen will provide a sensitive connection to the Julia Morgan Building as well as a transition to the taller mass of the Bay Building. This glass hyphen will be slightly recessed behind the north elevation of the Julia Morgan Building so as to provide a reveal between the historic building and the new connection. The use of glass as a material for the hyphen will allow for a transparent wall at the only location where the proposed project actually touches the Julia Morgan Building. The glass hyphen will also be only two-stories tall so as to align with the bottom of the roof line of the Julia Morgan Building and allow for a more gradual transition to the higher four-story massing of the Bay Building.

The materials and fenestration of the new construction is contemporary but will not be incompatible with the regular rhythm of punched openings and brick façade of the Julia Morgan Building or the stone construction of the Caretaker's Cottage. The new construction will feature a ground floor finished in Roman style brick and upper floors of a pre-weathered metal panel system. The elevations are broken up into bays through the use of different colored panels and slight recesses in the elevations which helps reduce their overall monumentality by breaking up the elevation into discrete portions. The pattern of openings will also be primarily of vertically oriented punched openings with fixed and double casement windows. Overall, the use of solid materials such as metal panels and Roman brick, and regularly spaced punched openings of vertically oriented windows will be compatible with the character of the historic resource without mimicking it.

Despite these impositions on the massing of the Julia Morgan Building by the proposed new construction, it is important to note that the most important feature of the Julia Morgan Building's setting, the front lawn, will remain intact. The most important views of the Julia Morgan Building demonstrate how the proposed project still allows for the Julia Morgan Building to retain its prominence on the larger site while the additions recede into the background as is the case with the Bay and Francisco buildings, or are entirely invisible as with the renovated Perry Building (see Attachment 2: views E, M). The front lawn affords the most important views of the Julia Morgan Building from vantage points along Laguna Street from Bay to Francisco streets and provides the necessary setback to maintain the primacy of the Julia Morgan Building on the site. Additionally, the location of the front lawn and its relationship to the Julia Morgan Building reinforces the importance of the site's primary entrance that is located directly in the center of the Julia Morgan Building's west elevation, a building that is itself centered in the middle of the front lawn. The additions to the property will not interrupt the symmetrical and hierarchical aspects of the property along Laguna Street, from the front lawn and its curvilinear pathway, to the primary entrance centered on the Julia Morgan Building.

Therefore, while there are elements of the project that are in conformance with Standard 9, there are other elements that aren't entirely in conformance with this standard.

Standard 10 - New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

Because the location of the new additions and alterations will take place on portions of the property that have not taken on significance, the new construction does not affect any parts of the property that relate to its significance. The additions will connect with the Julia Morgan Building in the location where there already is an existing connection thus reducing the physical alterations required to connect the Julia Morgan Building with the new construction. Other areas of the property, such as the front lawn and Caretaker's Cottage will also not be affected by the new construction. If in the future, the proposed project were to be removed, the Julia Morgan Building and front lawn, and Caretaker's Cottage would maintain their essential form and integrity and would be unimpaired.

Therefore, the proposed project is in conformance with Standard 10.

*See **Project Impact Analysis** and **Cumulative Impacts Analysis** comments for additional information.*

PROJECT DETERMINATION

Based on the Historic Resource Identification, the project's scope of work:

☐ **Will** cause a significant adverse impact to the **individual historic resource** as proposed.
☐ **Will** cause a significant adverse impact to a **historic district / context** as proposed.

☒ **Will not** cause a significant adverse impact to the **individual historic resource** as proposed.
☐ **Will not** cause a significant adverse impact to a **historic district / context** as proposed.

PROJECT IMPACT ANALYSIS

Based on the above evaluation of the project the planning department finds some aspects of the project are not entirely in conformance with the Secretary's Standards. However, the planning department finds that the proposed project, even if not entirely in conformance with all 10 standards, will not cause material impairment to the historic resource. The proposed massing of the new construction is such that it will be taller than the Julia Morgan Building in some areas and will appear to encroach on the Julia Morgan Building from some secondary perspectives. The massing of the new Bay Building will be most visible from along Francisco Street and at the intersection of Francisco and Laguna streets where currently the one-story Health Center will be replaced by the four-story Bay Building. Because of the increase in height at this location the new building will be much more prominent from this vantage point and will impose on the setting of the Julia Morgan Building from certain points of view (see Attachment 2: views A and B). However, the new construction will not block the Julia Morgan Building from these perspectives entirely even if the roof line of the Julia Morgan Building will be less visible from the street at certain perspectives. Because the new building will be set back from Laguna Street further than the existing Health Center, this deeper setback will reveal more of the Julia Morgan Building's south elevation from these perspectives.

The new Bay Building will be most visible from the intersection of Bay and Laguna streets and will thus have the biggest modification to the setting from this perspective. The Bay Building will be taller than the Julia Morgan Building and the Caretaker's Cottage and will have a massing that projects out farther towards Bay Street than the existing Perry Building Connector. While the new construction will be visible from the northern corner of the site, it will not compete with the primacy of the Julia Morgan Building and will not affect the generous setback that the front lawn provides for the Julia Morgan Building's most important elevation (see views D, E, and F).

As stated in review of the project for conformance with Standard 9, planning department staff determined that the design and materials of the new addition is compatible with the character of the historic resource and will not negatively affect the site overall.

Planning staff have also reviewed the proposed project and determined it would not cause material impairment to the Caretaker's Cottage. The immediate setting of the Caretaker's Cottage is already characterized by contemporary urban infill as the Caretaker's Cottage is currently situated just north of the Perry Building and is immediately west of the neighboring four-story multi-family residential building. Furthermore, the inward orientation of the Caretaker's Cottage, with its primary entrance facing away from Bay Street, makes the Caretaker's Cottage less of a public facing building than the Julia Morgan Building. While the new construction may intensify the built-up nature of the Caretaker's Cottage's immediate setting, it will not be a significant change from its existing condition.

Planning department staff have determined that while the new construction will cause some changes to the setting of 3400 Laguna, these changes do not rise to the level such that the individual historic resources on the site would no longer communicate their significance. While the massing of the new construction will be visible from some perspectives of the site, the property will still maintain the Julia Morgan Building's prominence along Laguna Street. The new construction is limited to areas away from the front lawn to preserve the setting of the Julia Morgan Building's primary façade. Additionally, the proposed project will include rehabilitation of the Julia Morgan Building that will repair some character-defining features and remove some non-historic alterations that have altered the Julia Morgan Building's north elevation. The character-defining features of the Julia Morgan Building and Caretaker's Cottage will be retained.

Although there will be construction on the site that will be more visible in locations where there are already non-historic additions and in some cases in locations currently dedicated to a parking lot, the larger effect of these additions on the Julia Morgan Building and Caretaker's Cottage is not such that the two individually eligible historic resources would no longer communicate their significance and eligibility for listing in the California Register. The Julia Morgan Building at 3400 Laguna would still convey its significant association under Criterion 1 with the San Francisco Ladies' Protection and Relief Society as well as its association under Criterion 3 as a representative work of Julia Morgan, an architect of merit who created a design that blended utilitarian needs with sophisticated aesthetics. Similarly, the stone Caretaker's Cottage would also continue to convey its association under Criterion 1 with the San Francisco Ladies' Protection and Relief Society and under Criterion 3 as an excellent and unique example of an English-inspired stone cottage. Although the proposed project will cause some changes to the property's overall setting, it is not to the level such that it would cause material impairment to the identified historic resource. After completion of the proposed project, the site at 3400 Laguna will still be eligible for listing in the California Register.

Planning department preservation staff continue to work with the project sponsor to ensure the proposed treatment of the Julia Morgan Building, including repair of the windows and brick repointing, along with any other necessary repairs, and the detail of the connecting hyphen is in conformance with the Secretary's Standards. These details will be reviewed and approved by planning department preservation staff in the preservation treatment plan.

Construction Impacts

Because the proposed project will take place on the site where historic resources are located, there is the potential for the construction to damage historic resources. Therefore, the department will require implementation *of Mitigation Measure M-CR-1b: Best Practices and Construction Monitoring Program for Historic Resources* to ensure best practices when construction takes place on a site that contains historic resources.

Off-Site Impacts

Adjacent Historic Resources
Historic resources that have been identified west of the subject property include the article 10 listed Marina Branch library and the California Register-eligible Funston bleachers that were identified as a contributor to the discontiguous Midcentury Recreation historic district. Historic resources identified north of the subject property include the Fort Mason historic district and the Fort Mason Port of Embarkation historic district. Because the proposed project includes infill of an urban site adjacent to these historic properties in a

manner that is consistent with the height and massing of the surrounding neighborhood, there are no anticipated offsite impacts to historic resources caused by this infill. All identified adjacent historic resources are surrounded by residential neighborhoods that contain single family homes and multifamily apartments that range between three and four stories. Additional construction that is compatible with the size and massing of the surrounding residential neighborhood does not have the potential to cause an indirect impact on any of the identified historic resources nearby.

There are no identified historic resources immediately south or east of the subject property. However, if in the future, any of the properties immediately south or west of the subject property were to be identified as historic resources, the urban infill of the proposed project that is compatible with the height and massing of the neighborhood would in no way have an indirect impact on the neighboring properties.

Vibration
Any potential vibration impacts caused by construction of the proposed project on adjacent buildings will be addressed in the noise and vibration section of the Initial Study.

MITIGATION MEASURES

Implementation of the following Mitigation Measures would reduce the project's impacts on character defining features to historic resources to less than significant.

Mitigation Measure M-CR-1b: Best Practices and Construction Monitoring Program for Historic Resources

Although construction-related damage to the subject property is unlikely, the project site contains historic resources. Therefore, implementation of best practices and construction monitoring are necessary to reduce potential direct impacts through construction-related damages.

Furthermore, given the close proximity of new construction to historic buildings on the site, this mitigation measure will include a requirement that the project sponsor coordinate with planning department preservation staff and submit for review and approval a preservation treatment plan with additional details about the glass hyphen that will connect the new Bay Building with the Julia Morgan Building, and additional information about rehabilitation of the Julia Morgan Building.

CUMULATIVE IMPACTS
The only identified project within the cumulative study area is the Marina Improvement and Remediation Project. Because 3400 Laguna Street has no aesthetic or historic relationship with the Marina, the proposed project at 3400 Laguna Street does not have the potential to combine with the Marina Improvement and Remediation Project to negatively affect historic resources. As a site containing two individually eligible historic resources, the proposed project's potential impact to historic resources is limited to the historic resources on the site and those immediately adjacent to the site. The planning department determined that the impact to resources on and adjacent to the site would be less than significant and would not combine with the projects in the cumulative study area to have an impact on any of the identified historic resources.

CONCLUSION

Planning Department staff find that the proposed project is in conformance with most of the Secretary's Standards but is not fully in conformance will all 10 standards. However, the proposed project will not cause material impairment to the identified historic resources such that they would no longer retain their eligibility for listing in the California Register. Additionally, the potential adverse impacts of caused by the proposed project's construction can be reduced through the implementation of Mitigation Measures as outlined above such that they would reduce the project's impacts on historic resources to less than significant (LSM). Therefore, the proposed project will have a less than significant impact on historic resources with the implementation of mitigation measures.

Project Evaluation: Principal Preservation Planner Review

Signature: Allison Vanderslice Date: 2/27/2024

Allison Vanderslice, *Principal Preservation Planner*
CEQA Cultural Resources Team Manager, Environmental Planning Division

CC: Jeff Horn, *Senior Current Planner*
Team 1-2, Current Planning Division

Megan Calpin, *Senior Environmental Planner*
Environmental Planning Division

HRR ATTACHMENTS:

- ☒ Figures 1-5: Existing property photos / Current conditions
- ☒ Attachment 1: HRE prepared by Page and Turnbull
- ☒ Attachment 2: Heritage on the Marina, Site line studies of proposed project prepared by HKS, November 6, 2023

EXISTING PROPERTY PHOTOS / CURRENT CONDITIONS



Figure 1: Aerial photo showing location of the original Julia Morgan Building, additions, and landscape features of the site.
1: Original Julia Morgan Building, three stories, constructed 1925
2. Perry Building Connecter, two stories, constructed 1957
3. Perry Building, four stories, constructed 1957
4. Health center, one story, constructed 1963 and 1987
5. front lawn
6. central courtyard
7. rear courtyard



Figure 2: View northeast of the primary façade of the Julia Morgan Building and front lawn (Source: San Francisco Planning Department).



Figure 3: View southeast of the property showing the north (left) and west (right) elevations of the Julia Morgan Building. Note the one-story Perry Building Connector is also visible at the left of the photo (Source: San Francisco Planning Department).



Figure 4: View east of the property showing the primary façade (west elevation) of the Julia Morgan Building (Source: San Francisco Planning Department).



Figure 5: View southeast of the north (left) and west (right) elevation of the caretaker's cottage. Note the neighboring property and Perry Building in the background (Source: San Francisco Planning Department).

SUB-APPENDIX C.3
3400 LAGUNA STREET JULIA MORGAN BUILDING AND CARETAKER'S COTTAGE CHARACTER-DEFINING FEATURES

This page intentionally left blank

PAGE&TURNBULL

MEMORANDUM

DATE	August 1, 2024	PROJECT NUMBER	21286
TO	Frank Rockwood	PROJECT	3400 Laguna Street
OF	Rockwood Pacific, Inc. 36 Southwood Drive Orinda, CA 94563	FROM	Elisa Skaggs, Lex Campbell, Carolyn Kiernat
CC	M. Linde	VIA	Email

REGARDING: 3400 Laguna Street – Morgan Building Historic Features

BACKGROUND

This memorandum provides a description of the interior and exterior character-defining features of the historic Julia Morgan-designed building at 3400 Laguna Street as well as an assessment of the building's exterior condition and treatment recommendations.

CHARACTER-DEFINING FEATURES

The character-defining features of the Morgan Building include the following:

Exterior Building (Photos 1-38)

- Overall regular massing and intersecting hipped roof
- U-shaped plan, consisting of central volume, north and south wings at east façade, and projections at north and south façades
- Structural brick exterior walls
- Slate roof shingles
- Symmetrical arrangement of front façade, with central gabled parapet
- Historic fenestration pattern, consisting of evenly spaced window openings with hierarchy among basement, first story and second story windows and upper dormer windows
- Projecting canted bays
- Hipped dormer windows at roof
- Operable, divided-lite windows retaining historic configurations
- Terra cotta details: window surrounds with vegetative motifs in segmental arches; decorative panels and entablatures at canted bays; belt course above second level windows; projecting cornice with buttons at eave; coping and finial at central gabled parapet; double arched door surround at primary entrance vestibule

- Arched ground-level door openings at ground level
- Stained glass windows at interior chapel
- Additional historic design features: narrow blind niche and recessed diamond and square details in brick
- Historic glazed doors within entrance vestibule
- Three brick chimneys
- Front double stairs with iron railing
- Towers and penthouse at east façade
- Rain catch baskets

Exterior Site: Iron fence on brick base along west, north, and south property lines

Interior Building (photos 39-41)
The following features are located on the first floor of the Morgan Building in the lobby / reception area, library and reading room:

- Tile floor
- Central stairwell with trefoil railing
- Fireplace mantel
- Wood coffered ceiling

EXTERIOR CONDITIONS ASSESSMENT

On January 5, 2024, Page & Turnbull Inc. conducted a conditions assessment of the exterior walls, roof, and landscape at 3400 Laguna Street. The assessment was limited to the historic building constructed in 1925. Two additions constructed in 1957 and 1963 were excluded. The Caretaker's Cottage constructed in 1928-1929 was also excluded from the assessment. The objective of the investigation was to gain an understanding of the current conditions of the walls and roof and to make recommendations for maintenance and/or repair.

Page & Turnbull's field investigation was limited to visual observations and performed primarily from the ground level. A closer look at typical hipped roof conditions was obtained from an adjacent low-slope roof. Our observations and recommendations, along with photographs of specific existing conditions, are provided at the end of the memorandum.

OBSERVATIONS

The 1925 building has a U-shaped footprint with two wings that extend from the north and south ends of the east façade. The building is two-and-one-half stories over a partially exposed basement level and has an attic-story penthouse (Photos 1-3). The building is clad in brick with a 5-1 common bond. The walls terminate at a hipped roof that incorporates built-in gutters. The roof is punctuated by hipped roof dormers and a central low-sloped roof penthouse projecting from the east facing

roof pitch. Slate shingles cover the roof pitches, dormers, and penthouse walls. Specific observations of the walls, roof, and landscape conditions are summarized below. Observations are general or typical in nature unless stated otherwise.

Hipped Roof, Dormers, and Roof Drainage

- Slate tiles installed in a standard configuration cover the roofs and dormer walls (Photos 4-5). The tiles are uniformly installed with adequate side laps (min. 3 in. offset from the centerline of the above shingle) and appear to be predominantly intact. We did not observe any slippage or missing tiles. The tiles exhibit minor weathering.
- The roof tiles are incorporated into closed valleys and rakes with uniform cuts. The flashing is not visible.
- The penthouse walls terminate at a roof parapet covered with ornamental copper sheet metal coping free of loose or deformed components. In general, the coping appears intact and is in the early stages of developing a protective patina.
- Three brick masonry chimneys project from the roof surface (Photo 6). Painted steel angle braces provide additional lateral support for the chimneys. The brick pointing mortar appears intact and the white color suggests the mortar is newer than the original masonry mortar. The paint forms a uniform coating on the steel. There are no obvious signs of corrosion.
- The hipped roof incorporates sheet metal, built-in gutters behind a molded terra cotta parapet. The gutters that were visually accessible appear clear of debris with no evidence of standing water.
- The gutters drain through outlets connected to copper sheet metal down leaders (Photos 7-8). The down leaders feature ornamental terra cotta scuppers. Staining, biological growth, and mortar deterioration are visible on the brick walls at approximately half of the rain leader systems.
- A detached down leader seam was observed in one location on the north elevation. The same down leader is also detached from the wall (Photo 9).
- In one location on the south elevation of the north wing, a conductor and down leader are missing. The roof outlet drains directly onto the wall and deck below. (Photo?)

Brick and Terra Cotta Walls

- The brick walls consist of brick set in 5-1 common bond with terra cotta ornamentation.
- There is moderate erosion of the brick mortar joints. We observed isolated cracking and holes in the joints that can lead to moisture infiltration (Photo 10).
- On the east elevation and inside elevations of the wings (facing the courtyard), there is staining and biological growth on the brick at the base of the brick wall. The brick mortar at these locations exhibits more severe deterioration (Photo 11).
- At approximately three locations on the west elevation, there is isolated staining on the brick frieze area just below the terra cotta coping, which is also stained. The brick mortar is

deteriorated in these locations (Photos 12-14). This suggests the presence or prior presence of leakage in the roof drainage system.

- A central brick dormer that incorporates a brick front gabled wall has an open (> 1/16 in. wide) diagonal crack in the brick masonry. In other locations at the corners of the wall, there are bulges and slight displacement of some brick units (Photos 15-16).
- In one location on the west elevation, brick mortar joints were repointed or filled with white sealant. The sealant does not match the adjacent mortar (Photo 17).
- In general, most terra cotta ornamentation is free of defects such as cracking, spalling, and or displacement (Photo 18).
- There is significant deterioration of terra cotta parapet mortar joints (Photo 19-20). White staining that appears to be efflorescence is seen in isolated locations on the west and east elevations.
- Isolated terra cotta blocks (5-6 locations) found on the west elevation contain moderate glaze spalling (Photos 21-22).
- At two locations on the west elevation, horizontal joints above the terra cotta window arches are filled with white sealant. This appears to be a temporary remedy to protect exposed steel lintels that may be experiencing corrosion and expansion of the steel product (Photo 23).
- At the projecting bays on the west elevation, the mortar joints of the terra cotta window trim are cracked and deteriorated (Photo 24).

Concrete Foundation Wall

- A concrete foundation wall with cement plaster finish is visible in a basement stair well on the north elevation.
- The concrete wall contains some open cracks in the finish surface (Photo 25).

Steel Windows and Leaded Glass

- The painted steel casement windows generally are free of paint failure and material defects (e.g., peeling paint, corrosion, glazing failure) are in generally good condition. There are isolated occurrences of flaking paint and cracked glazing putty particularly on the south elevation (Photo 26). Window perimeter sealant joints are adhered and intact.
- There is minor surface corrosion on the lead cames of some leaded glass windows on the south elevation (Photo 27). The steel frames contain minor spot corrosion. The leaded glass panels are otherwise in good condition.

Wood and Metal Doors

- Painted wood and metal doors are free of paint and material defects (e.g., peeling paint, corrosion) and the doors generally are in good condition (Photo 28).
- There is minor wood checking and paint deterioration on an eight-lite wood door on the east elevation (Photo 29).

- A wood door on the east elevation is missing a sweep (weatherstripping) at the base of the door panel (Photo 30).
- The front door on the west elevation features a steel frame storefront system fitted with an aluminum door. There is minor cracking of the glazing putty and peeling paint on the steel frame (Photo 31).

Landscaping Components

- The courtyard behind the building features a brick paver patio and sidewalks around two concrete fountains (inoperable). Planting beds are found around the perimeter of the patio and sidewalks (Photo 32).
- The planters incorporate well maintained mature shrubs, ground covering, and trees.
- There are open cracks in the concrete paver trim. In isolated locations the trim is buckling due to settlement of the subsoil (Photo 33).
- In specific locations, the brick pavers are buckling and dislodged due to settlement of the subsoil (Photo 34).
- There are cracks in the fluid applied waterproofing applied to the walls and floors of the fountains (Photo 35).
- The front lawn features concrete sidewalks that intersect a grass lawn. Planting beds incorporate boxwood and azalea shrubs and flower planting beds. An iron fence set on a brick stem wall is found around the perimeter of the property adjacent to the public sidewalk (Photo 36).
- Components of the iron fence and gate contain isolated corrosion and blistered paint (Photos 37-38). There is scaling on some fence pickets leading to section loss.
- The brick stem wall contains minor biological growth on the surface but is otherwise in good condition.

INTERIOR AND EXTERIOR FEATURES AND TREATMENT RECOMMENDATIONS

The following is a list of interior and exterior features of the Julia Morgan building with treatment recommendations:

Exterior Feature + Condition	Treatment Recommendation
Hipped Roof, Dormers, and Roof Drainage	
Staining and biological growth adjacent to down leaders	Investigate conductors and leaders to locate leakage, reseal (solder and fasten) open joints.
Detached down leader	Reattach down leader to wall.
Missing down leader	Install new sheet metal down leader to match existing.
Brick and Terra Cotta Walls	
Erosion, cracking, and holes in mortar joints	Repoint deteriorated mortar joints to match composition and color of existing.
Staining and biological growth as base of wall, mortar deterioration	Relocate or adjust sprinklers so that they do not distribute water onto the wall. Repoint deteriorated mortar joints.
Staining at brick frieze	Investigate sheet metal gutter for leakage and repair. Repoint deteriorated mortar joints to match color and composition of existing.
Diagonal crack, masonry displacement	Investigate wall for loose masonry. Install masonry anchors as required and rout and point crack.
Non-matching sealant in mortar joints	Remove and replace sealant with mortar that matches the existing.
Deteriorated terra cotta mortar joints at parapet, staining	Investigate sheet metal gutter for leakage and repair. Repoint deteriorated mortar joints.
Glaze spalling	Patch/paint glaze spalls to match the color and texture of existing glaze.
Sealed horizontal joint at window lintels	Monitor joints for masonry cracking and displacement. If movement occurs, remove brick and clean and paint lintel with rust inhibiting coating. Replace brick to match existing.
Deteriorated terra cotta mortar joints at window trim	Repoint deteriorated mortar joints to match composition and color of existing.
Concrete Foundation Wall	

Open cracks	Rout and seal cracks. Paint to match existing wall.
Steel Windows and Leaded Glass	
Flaking paint	Remove loose paint and repaint to match existing.
Cracked glazing putty	Remove cracked glazing putty and reglaze. Paint to match existing.
Surface corrosion on lead cames	Remove corrosion using abrasive cleaning. Coat lead came with a clear rust inhibitive sealer.
Wood and Metal Doors	
Wood checking and paint deterioration	Patch wood using a wood filler. Remove loose paint and repaint to match existing.
Missing sweep (weatherstripping)	Replace sweep as required.
Flaking paint and cracked glazing putty	Remove cracked glazing putty and reglaze. Paint to match existing. Remove loose paint and repaint to match existing.
Landscaping Components	
Cracks and buckling of concrete paver trim	Investigate and correct settlement. Remove and reinstall concrete trim on level substrate to match existing.
Buckling and dislodged brick pavers	Investigate and correct settlement. Remove and replace pavers on level substrate.
Open cracks in concrete fountain waterproofing	Replace fluid applied waterproofing if fountains are refilled.
Corrosion and scaling of iron fence	Remove corrosion using abrasive methods. Repaint using rust inhibitive paint.

INTERIOR FEATURES TREATMENT RECOMMENDATIONS	
Interior Features The following features are located on the first floor of the Morgan Building in the lobby / reception area, library and reading room. All features will be retained and protected during construction.	
Tile floor	Retain and repair existing tile floor. Replace broken or missing tiles as needed to match original.

Central stairwell with trefoil railing	Retain existing central stair and railing. Clean, repair and refinish railing as needed.
Fireplace mantel	Retain existing fireplace mantel. Clean and patch as needed.
Wood coffered ceiling	Retain existing wood coffered ceiling. Repair and refinish as needed.

EXTERIOR PHOTOS



Photo 1: Overall view, West elevation



Photo 2: Overall view, southwest corner



Photo 3: Overall view, North elevation



Photo 4: Overview of hipped roof.




Photo 5: Hipped roof and built-in gutter.



Photo 6: Three brick chimneys projecting from roof.



Photo 7: Staining, biological growth, and mortar deterioration around down leader



Photo 8: Staining, biological growth, and mortar deterioration around down leader.



Photo 9: Detached down leader seam.



Photo 10: Isolated cracking and holes in mortar.



Photo 11: Staining and biological growth at wall base.



Photo 12: Brick mortar deterioration.



Photo 13: Brick mortar deterioration.



Photo 14: Brick mortar deterioration.



Photo 15: Crack in brick dormer.



Photo 16: Bulges in brick at central brick dormer.



Photo 17: Sealant does not match mortar.



Photo 18: Most terracotta ornamentation is free of defect.



Photo 19: Deterioration of terra cotta mortar joints at parapet.



Photo 20: Deterioration of terra cotta mortar joints a parapet.



Photo 21: Glaze spalling.



Photo 22: Glaze spalling.



Photo 23: Sealant over exposed steel lintel.



Photo 24: Mortar at trim cracked and deteriorated.




Photo 25: Cracks at finish surface.



Photo 26: Flaking paint and cracked glazing putty.



Photo 27: Minor surface corrosion on lead cames.




Photo 28: Door at courtyard.




Photo 29: Minor wood checking.



Photo 30: Missing weatherstripping.



Photo 31: Peeling paint.



Photo 32: Planting beds at sidewalk perimeter.



Photo 33: Cracks and settlement of concrete trim.



Photo 34: Dislodging brick pavers from soil settlement.



Photo 35: Cracks in fluid applied waterproofing.



Photo 36: Front lawn.




Photo 37: Corrosion at iron fence.



Photo 38: Corrosion at iron fence.

INTERIOR PHOTOS



Photo 39: Lobby and reception area, viewed facing south.



Photo 40: Sitting Room



Photo 41: Library and Reading Room