
passing
trapped–passing boundary, $H = 1$
1
0
−1
μB, energy
$\theta = 0$
$\theta = 2\pi$
trapped
HFS
LFS
HFS
poloidal angle along the field line, θ