Assignment No: 02

D1:LOOP D1

Assignment Name: Write an assembly code to glow G+R1(ON)-R1(OFF)-Y(ON) in LED Display respectively.

Assembly Code: G13_AS2 SEGMENT PARA PUBLIC 'CODE' ASSUME CS:G13_AS2 ORG 1000H START: MOV AL,80H OUT 1FH,AL MOV AL, OFFH OUT 19H,AL LED: MOV AL,03H OUT 1BH,AL MOV CX,0FFFFH D0:LOOP D0 MOV AL,02H OUT 1BH,AL MOV CX,0FFFFH

MOV AL,06H

OUT 1BH,AL

MOV CX,0FFFFH

D2:LOOP D2

G13_AS2 ENDS

END START