## **How to Update Firmware on ATPL Breath Analyzer Device**

## Requirements:

- 1. Windows PC
- 2. Breath Analyzer Device
- 3. BA firmware updating tool
- 4. BA Latest Firmware
- USB driver installed on windows (CP210x\_Windows\_Drivers\_with\_Serial\_Enumeration).

**Steps 1**: Install **CP210x\_Windows\_Drivers\_with\_Serial\_Enumeration** driver for support USB to serial device.




Step 2: Connect your BA device with Windows pc via USB cable.

Step 3: Launch BA firmware tool via double click.




After connect BA device with windows pc click on connect button.




**Step 4**: First **Delete old** installed firmware via click on delete button.

Version V 1.1 Page 1




And you got message on terminal "Delete success!"

**Step 5**: Now your device is ready to install new updated firmware. Click **on open file** and choose updated firmware file from your PC as per showing in screen



Step 6: Now click on "Start Upgrade" to start firmware updating.

Version V 1.1 Page 2



When updating is completed you see message on terminal screen "Update Success" with firmware version and device automatic disconnected.

**Step 7:** Now disconnect BA device with your windows pc and switch on the BA device via press on button. Here you can see on welcome BA screen with updated firmware version.



------ Thank you ------

Version V 1.1 Page 3