IoT_Weather_Monitoring Issues and Solutions

- I. Module is not inserted: Unknown symbols in device tree source code.
- i. Cross compile by loading uImage in 0x80008000 adress as make ARCH=arm CROSS_COMPILE=arm-linux-gnueabi- uImage LOADADDR=0x80008000
 - ii. properly compiled zImage and .config file are ported in board.
- II. No binary file is generated while compiling device tree source code...

 Cross compile by loading uImage in 0x80008000 adress as

 make ARCH=arm CROSS_COMPILE=arm-linux-gnueabi- uImage
 LOADADDR=0x80008000
- III. In database creation, every command ending with semicolon(;)
- IV. dpkg is not configured, while installing mysql-server...

 Configure mysql-server using the command shown in prompt window.
- V. Device is not created in board for communication purpose Port properly compiled zImage and .config file in board and .dtb file.