


Two-block thermal exchange across a contact conductance

Contact-coupled pair relaxing to equilibrium (max |error| = 0.057 K)



Early-transient overshoot: the only case over tolerance

