

TAX INVOICE / PAYMENT RECEIPT Vendor: BuildRight Construction & Repairs SSM No: 201902567890 Invoice No: BR-INV-2026-0418 Receipt ID: RCPT-2026-0418 Service Date: 2026-04-18 Property: Damai Residence, Unit 1 (Apartment), Jalan Damai, Keramat, W.P. Kuala Lumpur, Malaysia

BILL TO Landlord One Sdn Bhd Finance Department

WORK ORDER SUMMARY Service Request No: MNT-OAK-2026-0052 Issue Reported: Ceiling seepage and water stain damage from roof leak Technician: Rahman Zakaria

LINE ITEMS 1) Ceiling patch and plaster repair Area: 2.5 sqm Materials: RM 35.00 Labor: RM 85.00

2) Surface primer and finishing paint Area: 2.5 sqm Paint & Materials: RM 28.80 Labor: RM 8.00

FINANCIAL SUMMARY Subtotal: RM 156.80 SST (6%): RM 9.41 Grand Total: RM 166.21

PAYMENT DETAILS Payment Method: Bank Transfer Payment Date: 2026-04-22 Reference: IBG-88503294 Payment Status: Paid in Full

WARRANTY ON WORKMANSHIP Labor workmanship warranty: 6 months from service date. Paint warranty subject to manufacturer terms and exclusions.