




TP70 Calibration v2.68c.exe




1. Choose com port
2. Choose baud rate. (TP70 default value is 9600.)
3. Connect : Strat Protocol



4. Version number

5. Calibrate

4. Display the version number when the connection is successful.
5. Calibrate. Put the white card in the middle of the machine.



7. End

6. White card value

6. If the white card value is incorrect, confirm that the white card is correct and repeat step five (the existing white card is 11)
7. End.