

VehicleIQ Diagnostic Report — VEHICLE_002

Generated: 2026-07-27 20:52 UTC | Driver Profile Mode

Overall Health	Brake Health	Engine Health	Battery Health	Driving Style
81.5%	75.2%	71.9%	97.4%	AGGRESSIVE (20.0/100)

Diagnostic Findings & Repair Solution Guides

[WARNING] Accelerated Brake Pad Friction Wear (75.2% Health Remaining)

Finding: Frequent hard braking events detected during recent trips (hard braking rate: 30.0%). Rapid decelerations elevate rotor friction temperature and accelerate pad wear.
Solution: Brake Pad Inspection & Progressive Driving Adjustment
Estimated Cost: \$60 - \$140 (■1,800 - ■4,500) | **Urgency:** Moderate — Schedule inspection within 500 km

[WARNING] Engine Coolant Temperature Elevation (99.3°C Peak)

Finding: Coolant temperature reached 99.3°C while engine operated at high RPM (46.7% of trip duration). Thermal expansion risks cylinder head gasket stress.
Solution: Coolant System Flush & Radiator Fan Relay Test
Estimated Cost: \$35 - \$95 (■1,200 - ■3,200) | **Urgency:** HIGH — Inspect before next long highway trip

[INFO] Driving Behavior: AGGRESSIVE (Score: 20.0/100)

Finding: Repeated hard braking, sharp acceleration bursts, and high-RPM gear shifts accelerate pad wear and engine heat stress.
Solution: Behavioral Driving Smoothing & Component Relief Plan
Estimated Cost: \$0 (Habit Adjustment Saves ~\$400/yr in repairs) | **Urgency:** Immediate Behavioral Adjustment