Sheet2

1 3 5 7	2 4 6 8	1 3 5	2 4 6 8	1 3 5 7	2 4 6 8	1 3 5	2 4 6 8	1 3 5	2 4 6 8		1 2 3 4 5 6 7 8		1 3 5 7	2 4 6 8
9	10	9	10	9	10	9	10	9			9 10		9	10
11	12	11	12	11	12	11	12	11	12	1		1	11	12
13	14	13	14	13	14	13	14	13	14		3 14	1	13	14
15	16	15	16	15	16	15	16	15		-	5 16		15	16
17	18	17	18	17	18	17	18	17	18		7 18	1	17	18
19	20	19	20	19	20	19	20	19			9 20		19	20
21	22	21	22	21	22	21	22	21	22	2			21	22
23	24	23	24	23	24	23	24	23	24		3 24		23	24
25	26	25	26	25	26	25	26	25	26	2	5 26		25	26
27	28	27	28	27	28	27	28	27	28	2			27	28
29 31	30	29	30	29	30	29	30	29	30		9 30		29	30
	32	31	32	31	32	31	32	31	32	3	1 32		31	32
33	34	33	34	33	34	33	34	33	34	3	3 34		33	34
35	36	35	36	35	36	35	36	35	36	3	5 36		35	36
37	38	37	38	37	38	37	38	37	38	3	7 38		37	38
39	40	39	40	39	40	39	40	39	40	3	9 40		39	40
·													,	

col height =0.10 in Center col width=0.20 in

cut the grey part out and lay it over your GPIO pins