


Overall Inspection Summary: INS Mumbai

Date: 2026-02-18 07:12:05

Inspector: Inspector B

Hull Type: Aluminum

Ship ID: 1



Defect	Avg Percentage	Recommended Maintenance
Corrosion	8.03%	Welding/steel replacement
Cracks	5.58%	Welding/reinforcement
Paint Degradation	4.70%	Repainting/anti-fouling coating
Barnacles	4.99%	Scraping/cleaning
Algae	5.80%	Pressure washing/anti-fouling paint
Sediment	1.23%	Dry-docking/cleaning

Hull Inspection Report: 3.jpg



Date: 2026-02-18 07:12:05

Inspector: Inspector B

Hull Type: Aluminum

Ship Name: INS Mumbai

Ship ID: 1



Defect	Percentage	Recommended Action
Corrosion	8.03%	Welding/steel replacement
Cracks	5.58%	Welding/reinforcement
Paint Degradation	4.70%	Repainting/anti-fouling coating
Barnacles	4.99%	Scraping/cleaning
Algae	5.80%	Pressure washing/anti-fouling paint
Sediment	1.23%	Dry-docking/cleaning