REPAIR INSTRUCTION SOUND SYSTEM with id

84010fa502136d41911cde0569f9b708640c76344da78acd04868f338841ec56

Diagnose: speaker not working

Solution: return to sound manufacturing for speaker replacement