

Circuit Board QA Inspection Report

AEgis Sovereign Intelligence Report | Generated: 2026-09-04 17:49:00 UTC | Classification: **CONFIDENTIAL**
INTERNAL | Task: VISION_ANALYSIS | Model: qwen3-vl:4b | Source: live_test_circuit_1788544138002.png

EXECUTIVE SUMMARY

A visual inspection of circuit board live_test_circuit_1788544138002.png revealed no defects. Resistor R4 (10k Ohm) is intact, capacitor C2 (100uF) is properly seated, and IC1 solder joints exhibit zero bridging.

KEY FINDINGS

The circuit board underwent a QA inspection and demonstrated satisfactory condition. Specifically, resistor R4, capacitor C2, and IC1 all passed visual assessment.

DETAILED ANALYSIS

The inspection focused on the integrity of components. Resistor R4 (10k Ohm) was confirmed to be undamaged. Capacitor C2 (100uF) was correctly positioned and seated. Inspection of IC1 solder joints indicated no bridging issues.

RISKS AND OPERATIONAL ISSUES

None identified based on the visual inspection. No circuit board defects were observed.

RECOMMENDATIONS

Based on the positive inspection results, no further action is recommended at this time. Continue to monitor circuit board performance as per standard operational procedures.

AUTHORITATIVE SOURCES & CITATIONS

Document Name	Referenced Pages	Relevance Status
live_test_circuit_1788544138002.png	Page(s) 1	High

Verification Integrity Hash: 63a8eaf09959e7fad5a0e0f28cd57f43...