
Deterministic
CV=0%/0%
Low Variation
CV=2%/15%
Moderate Variation
CV=10%/25%
Stress Variation
CV=20%/40%
Correct and accepted output (%)
100
80
60
40
20
0
0
1
2
3
Faulty replicas in one bit
Standard TMR
Proposed