

## Cut from 3 - 4 mm thick aluminum





This one is optional. You can either solder the thick wire bend to an u-shape directly to the pcb as before or cut this aluminum piece and screw it with m2 screws to the pcb.