Native net88/lead9: same 16 current-flux gates, refined spatial mesh

Original CAD, 12 region properties and P2 contact law unchanged; both coupon runs FAIL electrical Gate B



Zero-current net88 middle landing is retained. Two interior-foil cut errors are near zero and included in the chart.

Independent source-current audits confirm reported values; this is not an experimentally calibrated current distribution.