

1. Overview & specifications

The AquaPure UV Max 9 (AquaPure, water-purifier) is covered by this service manual for authorised technicians holding the 'water-treatment' skill. It documents diagnosis, fault codes, and board/mechanical-level repair.

Specifications — type: UV purifier, capacityL: 7, stages: 4, powerW: 40.

Warranty: 12 months. Parts and labour on the UV ballast and chamber for 12 months. UV lamp and filters are consumables.

Reference: <https://support.example-fieldflow.test/ap-uv-9/manual>

AquaPure UV Max 9 — Service Manual — page 1

2. Installation & commissioning

Flush the pre-filters for ten minutes, sanitise the RO/UV chamber, set the inlet TDS, and verify reject-to-product ratio before handover.

Record the serial number and commissioning date against the work order. A failed self-test must be cleared before the visit is closed.

3. Fault codes

UV1 — UV fail alarm; ballast not driving the lamp. Replace UVB-9. Skill: water-treatment.

UV3 — Low UV dose; lamp aged (consumable). Replace UVL-9. Skill: water-treatment.

UV5 — No flow detected; flow sensor or pump. Replace PUMP-9. Skill: water-treatment.

4. Part replacement — UVB-9 / UVL-9

UVB-9 — UV electronic ballast (board). Isolate mains and follow the safety SOP. Remove the faulty unit, fit UVB-9, and run the self-test. Requires 'water-treatment'. This part is covered under active warranty (free). List price ■960.

UVL-9 — UV lamp 11W (consumable). Isolate mains and follow the safety SOP. Remove the faulty unit, fit UVL-9, and run the self-test. Requires 'water-treatment'. This part is chargeable (out of warranty scope). List price ■520.

5. Part replacement — CHAM-9 / PUMP-9

CHAM-9 — Quartz UV chamber (mechanical). Isolate mains and follow the safety SOP. Remove the faulty unit, fit CHAM-9, and run the self-test. Requires 'water-treatment'. This part is covered under active warranty (free). List price ■1,300.

PUMP-9 — Diaphragm pump (pump). Isolate mains and follow the safety SOP. Remove the faulty unit, fit PUMP-9, and run the self-test. Requires 'water-treatment'. This part is covered under active warranty (free). List price ■1,800.

6. Part replacement — FLOW-9 / FILT-9

FLOW-9 — Flow sensor (sensor). Isolate mains and follow the safety SOP. Remove the faulty unit, fit FLOW-9, and run the self-test. Requires 'water-treatment'. This part is chargeable (out of warranty scope). List price ■460.

FILT-9 — Spun sediment filter (consumable). Isolate mains and follow the safety SOP. Remove the faulty unit, fit FILT-9, and run the self-test. Requires 'water-treatment'. This part is chargeable (out of warranty scope). List price ■240.

7. Maintenance, safety & warranty

Maintenance: inspect at each visit; clean or replace consumables on the service interval; log any recurring fault code.

Isolate mains and relieve line pressure before opening the pump or valve housing.

Warranty annex: under an active warranty, UVB-9, CHAM-9, PUMP-9 are replaced free with labour. Consumables and cosmetic parts are never covered. If warranty is expired or the fault is outside the original scope, the part is chargeable: a quote is raised and payment is collected before the visit is confirmed.

Policy reference: <https://support.example-fieldflow.test/warranty/v5>